

**FORM  
INSP**Rev  
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

02/08/2012

Document Number:

663800140

Overall Inspection:

Unsatisfactory**FIELD INSPECTION FORM**

Location Identifier: 210769 Facility ID: 335219 Loc ID:                      Tracking Type:                      Inspector Name: LONGWORTH, MIKE

**Operator Information:**OGCC Operator Number: 96850 Name of Operator: WILLIAMS PRODUCTION RMT COMPANY LLCAddress: 1001 17TH STREET - SUITE #1200City: DENVERState: COZip: 80202**Contact Information:**

Contact Name	Phone	Email	Comment
Moss, Brad	(970) 285-9377	Brad.Moss@Williams.com	Production foreman

**Compliance Summary:**

QtrQtr: <u>SWNE</u>	Sec: <u>34</u>	Twp: <u>6S</u>	Range: <u>95W</u>				
Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
01/12/2001	200014327	PR	PR	S		P	N
02/04/1999	500142208	PR	PR				
10/17/1994	500142207	PR	PR			P	N

**Inspector Comment:**

The W21-34 has gas leaking at the tubing/casing seal. Fix leak ASAP! Call was made to Brad Moss at 3pm 2/8/12 to inform Williams of leak. He advised me that he would have someone check on it.

**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
210769	WELL	PR	01/30/1987		045-06527	ACCO TOSCO W-21-34	X
210892	WELL	PR	06/30/1990	GW	045-06650	ARCO GV 53-34	X
335219	LOCATION	AC	04/14/2009		-	ACCO TOSCO-66S95W 34SWNE	

**Equipment:**Location Inventory

Special Purpose Pits:                      Drilling Pits:                      Wells:                      Production Pits:                       
 Condensate Tanks:                      Water Tanks:                      Separators:                      Electric Motors:                       
 Gas or Diesel Mortors:                      Cavity Pumps:                      LACT Unit:                      Pump Jacks:                       
 Electric Generators:                      Gas Pipeline:                      Oil Pipeline:                      Water Pipeline:                       
 Gas Compressors:                      VOC Combustor:                      Oil Tanks:                      Dehydrator Units:                       
 Multi-Well Pits:                      Pigging Station:                      Flare:                      Fuel Tanks:                     

**Location****Lease Road:**

Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Access	Satisfactory			

<b>Signs/Marker:</b>				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory			
BATTERY	Satisfactory			
CONTAINERS	Satisfactory	tote at GV53-35		
TANK LABELS/PLACARDS	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

<b>Good Housekeeping:</b>				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
TRASH	Satisfactory			

<b>Spills:</b>				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

<b>Fencing/:</b>				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
SEPARATOR	Satisfactory			
TANK BATTERY	Satisfactory			
WELLHEAD	Satisfactory			

<b>Equipment:</b>					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Plunger Lift	1	Satisfactory	on the GV 53-35		
Bird Protectors	1	Satisfactory			

<b>Tanks/Berms:</b>				
<input type="checkbox"/> New Tank		Tank ID: _____		
Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST	,
S/U/V: Satisfactory	Comment: _____			
Corrective Action:	_____			Corrective Date: _____

**Paint**

Condition	Adequate
Other (Content)	_____
Other (Capacity)	_____
Other (Type)	_____

<b>Berms</b>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Corrective Action	_____			Corrective Date: _____
Comment	_____			

<b>Venting:</b>		
Yes/No	Comment	
YES	bradens open	

<b>Flaring:</b>				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

**Predrill**

Location ID: 335219

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_

Pads: \_\_\_\_\_

Soil Stockpile: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:****Wildlife BMPs:****Stormwater:****Comment:** \_\_\_\_\_**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

**Operator Rep. Contact Information:**

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

**LGD Contact Information:**

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

**Summary of Landowner Issues:****Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Well**

Facility ID: 210769 API Number: 045-06527 Status: PR Insp. Status: PR

Facility ID: 210892 API Number: 045-06650 Status: PR Insp. Status: PR

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Inspector Name: LONGWORTH, MIKE

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_  
Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Debris removed? \_\_\_\_\_ CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
Waste Material Onsite? \_\_\_\_\_ CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
Unused or unneeded equipment onsite? \_\_\_\_\_ CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
Pit, cellars, rat holes and other bores closed? \_\_\_\_\_ CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

Inspector Name: LONGWORTH, MIKE

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_

Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_

Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_

No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_

Contoured \_\_\_\_\_

Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_

Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_

Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_

Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_

Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date \_\_\_\_\_

Overall Final Reclamation

**Storm Water:**

Loc Erosion BMPs

BMP  
Maintenance

Lease Road Erosion  
BMPs

Lease BMP  
Maintenance

Chemical BMPs

Chemical BMP  
Maintenance

Comment

S/U/V: \_\_\_\_\_

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_