

**FORM  
INSP**Rev  
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

02/10/2012

Document Number:

664000355

Overall Inspection:

Unsatisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name:
	<u>212667</u>	<u>324798</u>		<u>LEONARD, MIKE</u>

**Operator Information:**

OGCC Operator Number:	<u>95620</u>	Name of Operator:	<u>WESTERN OPERATING COMPANY</u>
Address:	<u>518 17TH ST STE 200</u>		
City:	<u>DENVER</u>	State:	<u>CO</u>
		Zip:	<u>80202</u>

**Contact Information:**

Contact Name	Phone	Email	Comment
James, Steve	(303) 893-2438	s.d.james@worldnet.att.net	President
Hart, Dale	(719) 729-3391	dalehartwoc@fairpoint.net	Field Foreman

**Compliance Summary:**

QtrQtr:	<u>SWSW</u>	Sec:	<u>9</u>	Twp:	<u>19S</u>	Range:	<u>45W</u>
Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
02/02/2012	664000346	IJ	AO	U			N
06/30/2011	200314346	MI	SI	U			N
06/10/2011	200312326	MI	AC	U			Y
06/02/2011	200312527	ES	AC	U			Y
05/06/2011	200310049	RT	AC	U			N
12/09/2010	200288159	ES	AC	U			Y
06/29/2010	200261215	ES	AO	U			Y
05/28/2010	200253227	CO	AO	U			Y
04/12/2010	200242416	RT	AC	S			N
06/17/2009	200213262	RT	AC	S			N
07/11/2008	200192441	RT	AC	S			N
04/06/2007	200108904	RT	AC	S		P	N
07/05/2006	200094293	MI	AC	S		P	N
07/26/2005	200074849	RT	AC	S		P	N
07/27/2004	200058118	RT	AC	S		P	N
08/20/2003	200043210	RT	AC	S		P	N
07/24/2002	200029480	RT	AC	S		P	N
08/21/2001	200019520	MI	AC	S		P	N
08/28/2000	200009366	RT	AC	S	I	P	N
03/20/2000	200005256	PR	AC	S	I	P	N
11/12/1998	500144528	PR	AC			P	N
03/04/1996	500144527	PR	AC			P	N

Inspector Name: LEONARD, MIKE

10/27/1995	500144526	PR	AC			P	N
04/07/1994	500144525		AC				

**Inspector Comment:**

RECLAMATION HAS STARTED ALONG DISPOSAL LINE. CONTINUE WITH REMEDIATION PLAN AS APPROVED

**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
150316	UIC DISPOSAL	AC	09/12/1991		-	KING-PYLES 2	<input type="checkbox"/>
212667	WELL	IJ	09/12/1991		061-06027	KING-PYLES 2	<input checked="" type="checkbox"/>
324798	LOCATION	AC	04/14/2009		-	KING-PYLES-619S45W 9SWSW	<input type="checkbox"/>

**Equipment:**

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location**

Emergency Contact Number: (S/U/V) \_\_\_\_\_ Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

**Spills:**

Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

**Venting:**

Yes/No	Comment

**Flaring:**

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

**Predrill**

Location ID: 324798

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_

Pads: \_\_\_\_\_

Soil Stockpile: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:****Wildlife BMPs:****Stormwater:****Comment:** \_\_\_\_\_**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

**Operator Rep. Contact Information:**

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

**LGD Contact Information:**

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

**Summary of Landowner Issues:****Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Well**

Facility ID: 212667 API Number: 061-06027 Status: IJ Insp. Status: AO

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: AREA ALONG DISPOSAL LINE NEAREST TO WELL APPEARS TO HAVE BEEN SEEDED. MAUNURE HAS BEEN SPREAD FOR SOIL AMENDMENT AND STORMWATER CONTROL

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Inspector Name: LEONARD, MIKE

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Debris removed? \_\_\_\_\_ CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
Waste Material Onsite? \_\_\_\_\_ CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
Unused or unneeded equipment onsite? \_\_\_\_\_ CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
Pit, cellars, rat holes and other bores closed? \_\_\_\_\_ CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_  
Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_  
CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**

**Cropland**

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

**Non-Cropland**

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation \_\_\_\_\_

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Inspector Name: LEONARD, MIKE

Comment:

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_  
Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_  
Access Roads \_\_\_\_\_ Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_  
Gravel removed \_\_\_\_\_  
Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_  
Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_  
Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_  
Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

Comment: AREA ALONG DISPOSAL LINE NEAREST TO WELL APPEARS TO HAVE BEEN SEEDED. MAUNURE HAS BEEN SPREAD FOR SOIL AMENDMENT AND STORMWATER CONTROL

Corrective Action:

Date

Overall Final Reclamation Fail

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: \_\_\_\_\_ Corrective Date: \_\_\_\_\_

Comment:

CA: