

FORM INSP
Rev 05/11

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
02/10/2012

Document Number:
659700075

Overall Inspection:
Satisfactory

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name:
	<u>265284</u>	<u>335793</u>		<u>Baroumand, Soraya</u>

Operator Information:

OGCC Operator Number: 69175 Name of Operator: PETROLEUM DEVELOPMENT CORPORATION

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

Contact Information:

Contact Name	Phone	Email	Comment
Lake, Jim	970-285-9606	JLake@petd.com	Production Supervisor
Winters, Ed	(970) 285-9606	edwinters@petd.com	
Ferguson, Randall	(303) 831-3904	rferguson@petd.com	Environmental Supervisor

Compliance Summary:

QtrQtr: NESW Sec: 17 Twp: 6S Range: 96W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
08/13/2009	200224745	PR	PR	S			N
07/06/2004	200072356	PR	PR	S	I	F	N
11/26/2003	200050305	PR	PR	S		P	N

Inspector Comment:

The tank battery was observed having adequate signage and labeling requirements, meeting the corrective action noted in a previous inspection on November, 28, 2011 (Doc# 661400026).

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
263452	WELL	AL	06/11/2003	LO	045-08130	CSOC 696-18 1	X
265284	WELL	PR	11/20/2002	LO	045-08993	CHEVRON 12-17D	X
265285	WELL	PR	11/20/2002	LO	045-08994	CHEVRON 14-17D	X
265286	WELL	PR	11/20/2002	LO	045-08995	CHEVERON 13-17D	X
267891	LEASE	PR	04/03/2003		-	CHEVRON 14-17D	
267892	LEASE	PR	04/08/2003		-	CHEVRON 12-17D	
267894	LEASE	PR	04/03/2003		-	CHEVERON 13-17D	
335793	LOCATION	AC	04/14/2009		-	CSOC 696-18-66S96W 17NESW	

Equipment:

Location Inventory

Tanks/Berms:		<input type="checkbox"/> New Tank	Tank ID: _____		
Contents	#	Capacity	Type	SE GPS	
CONDENSATE	2	300 BBLS	STEEL AST	,	
S/U/V:	Satisfactory	Comment:			
Corrective Action:				Corrective Date:	
Paint					
Condition					
Other (Content)	_____				
Other (Capacity)	_____				
Other (Type)	_____				
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Corrective Action				Corrective Date	
Comment					
Venting:					
Yes/No	Comment				
Flaring:					
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date	

Predrill

Location ID: 335793

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____
 Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Wildlife BMPs:

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Well

Facility ID: 263452 API Number: 045-08130 Status: AL Insp. Status: AL

Facility ID: 265284 API Number: 045-08993 Status: PR Insp. Status: PR

Facility ID: 265285 API Number: 045-08994 Status: PR Insp. Status: PR

Facility ID: 265286 API Number: 045-08995 Status: PR Insp. Status: PR

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____
Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? Pass CM _____

CA _____ CA Date _____

Waste Material Onsite? Pass CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass CM _____

CA _____ CA Date _____

Guy line anchors removed? Pass CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____ P _____

Comment: Good interim reclamation. Notable reduction of Well pad "footprint" observed based on field observations and aerial reviews. Recontoured and vegetated slopes observed.

Overall Interim Reclamation Pass

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
Ditches	Pass					
		Ditches	Pass			
Other	Pass					stable & vegetated slopes
		Waddles	Pass			

S/U/V: Satisfactory Corrective Date: _____

Comment: _____

CA: _____