

FORM INSP Rev 05/11	State of Colorado Oil and Gas Conservation Commission 1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109		DE	ET	OE	ES
	FIELD INSPECTION FORM		Inspection Date: <u>02/16/2012</u> Document Number: <u>663900602</u> Overall Inspection: <u>Satisfactory</u>			

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name: <u>QUINT, CRAIG</u>
	<u>416060</u>	<u>415744</u>		

Operator Information:

OGCC Operator Number: 10275 Name of Operator: AUGUSTUS ENERGY PARTNERS LLC

Address: 2016 GRAND AVE STE A

City: BILLINGS State: MT Zip: 59102

Contact Information:

Contact Name	Phone	Email	Comment
Davis, Lonnie	970-332-3587	ldavis@augustusenergy.com	

Compliance Summary:

QtrQtr: SENE Sec: 22 Twp: 1S Range: 44W

Inspector Comment:

CENTRAL METER BATTERY 895' NE

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
415744	LOCATION	AC	02/20/2010		-	SCHOBE 22-08	<input type="checkbox"/>
416060	WELL	PR	06/19/2010		125-11777	SCHOBE 22-08	<input checked="" type="checkbox"/>

Equipment: Location Inventory

Special Purpose Pits: _____	Drilling Pits: <u>1</u>	Wells: <u>1</u>	Production Pits: _____
Condensate Tanks: _____	Water Tanks: <u>1</u>	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: <u>1</u>	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: <u>1</u>
Electric Generators: _____	Gas Pipeline: <u>1</u>	Oil Pipeline: _____	Water Pipeline: <u>1</u>
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:

Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Access	Satisfactory	DIRT TRAIL THROUGH FARM GROUND.		

Signs/Marker:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory	LEASE SIGN BY UNIT.		

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____

Comment: _____

Corrective Action:

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory	STEEL PANELS AROUND ALL WELLHEAD EQUIPMENT.		

Equipment:					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Ancillary equipment	1	Satisfactory	ELEC PANEL		
Pump Jack	1	Satisfactory	25 JENSEN ON A CEMENT PAD.		
Prime Mover	1	Satisfactory	ELEC MOTOR		

Venting:	
Yes/No	Comment

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 415744

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____
Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Wildlife BMPs:

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Well

Facility ID: 416060 API Number: 125-11777 Status: PR Insp. Status: PR

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: DRY LAND

Comment: _____

1003a. Debris removed? Pass CM _____

CA _____ CA Date _____

Waste Material Onsite? Pass CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? Pass Segregated soils have been replaced? Pass

RESTORATION AND REVEGETATION

Cropland

Top soil replaced Pass Recontoured Pass Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____ P _____

Comment: UNUSED AREAS OF THE LOCATION ARE FARMED.

Overall Interim Reclamation Pass

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: DRY LAND

Reminder: _____

Comment: _____

Inspector Name: QUINT, CRAIG

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____
Debris removed _____ No disturbance /Location never built _____
Access Roads Regraded _____ Contoured _____ Culverts removed _____
Gravel removed _____
Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____
Compaction alleviation _____ Dust and erosion control _____
Non cropland: Revegetated 80% _____ Cropland: perennial forage _____
Weeds present _____ Subsidence _____
Comment: _____
Corrective Action: _____ Date _____

Overall Final Reclamation

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

S/U/V: Satisfactory Corrective Date: _____
Comment: _____
CA: _____