

Cement work date: 09/09/2011

Method used	String	Cementing tool setting/pref depth	Cement volume	Cement top	Cement bottom
	SURF	931	440	320	1,300

Details of work:

CREW TO LOC UNLAND CSG RU DUAL ENTRY FLANGE TALLEY TIH W/ 1-1/4" TBG TO 1170' BREAK CIRCULATION ROLL HOLE UNTIL CEMENT CREW ARRIVED MIX AND PUMP 440 SCKS 15.8# G NEAT CEMENT GOT APPROX 4 BBLS BACK IN SURFACE RETURNS (SEE REMARKS)

21. Formation log intervals and test zones:

FORMATION LOG INTERVALS AND TEST ZONES

FORMATION NAME	Measured Depth		Check if applies		COMMENTS (All DST and Core Analyses must be submitted to COGCC)
	Top	Bottom	DST	Cored	
SUSSEX	4,225		<input type="checkbox"/>	<input type="checkbox"/>	
NIOBRARA	7,044		<input type="checkbox"/>	<input type="checkbox"/>	
CODELL	7,318		<input type="checkbox"/>	<input type="checkbox"/>	
J SAND	7,750		<input type="checkbox"/>	<input type="checkbox"/>	

Comment:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: CARA MAHLER

Title: REGULATORY ANALYST Date: 1/4/2012 Email: CARA.MAHLER@ANADARKO.COM

Attachment Check List

Att Doc Num	Document Name	attached ?	
Attachment Checklist			
400237328	CMT Summary *	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
	Core Analysis	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
	Directional Survey **	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
	DST Analysis	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
	Logs	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
	Other	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
Other Attachments			
400236577	FORM 5 SUBMITTED	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>

General Comments

User Group	Comment	Comment Date

Total: 0 comment(s)