

FORM INSP Rev 05/11	State of Colorado Oil and Gas Conservation Commission <small>1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109</small>		DE	ET	OE	ES
--	---	--	----	----	----	----

Inspection Date:
02/27/2012

Document Number:
659700080

Overall Inspection:
Satisfactory

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name: <u>Baroumand, Soraya</u>
	<u>266566</u>	<u>334916</u>		

Operator Information:

OGCC Operator Number: 100185 Name of Operator: ENCANA OIL & GAS (USA) INC

Address: 370 17TH ST STE 1700

City: DENVER State: CO Zip: 80202-

Contact Information:

Contact Name	Phone	Email	Comment
Friesen, Kathy	(970) 285-2665	Kathy.Friesen@encana.com	Environmental Lead Piceance

Compliance Summary:

QtrQtr: NWSW Sec: 34 Twp: 6S Range: 92W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
12/01/2006	200101342	PR	PR	S	I	P	N
05/15/2006	200095032	PR	PR	S		P	N
05/21/2004	200060377	PR	PR	S		P	N
12/16/2003	200051607	CO	PR	S	I	P	N
12/12/2003	200050812	ES	PR	U		F	N

Inspector Comment:

overall inspection was satisfactory, but requires placards on tank battery and removal and monitoring of russian knapweed, which historically originated offsite, but has recently migrated to location. Refer to interim reclamation section for specifics.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
266566	WELL	PR	10/17/2003	OW	045-09153	MAGNALL 34-5 (L34)	X
266567	WELL	PR	10/17/2003	OW	045-09154	MAGNALL 34-6 (L34)	X
266570	WELL	PR	11/10/2003	OW	045-09156	MAGNALL 34-12 (L34)	X
266571	WELL	PR	10/13/2003	OW	045-09159	MAGNALL 34-11 (L34)	X
270898	LEASE	PR	12/29/2003		-	MAGNALL 34-5 (L34)	
270948	LEASE	PR	12/29/2003		-	MAGNALL 34-11 (L34)	
270949	LEASE	PR	12/30/2003		-	MAGNALL 34-12 (L34)	
271063	LEASE	PR	11/20/2003		-	MAGNALL 34-6 (L34)	
274962	WELL	PR	06/24/2005	GW	045-13446	SCHICKLING 34-5C(L34)	X
274963	WELL	PR	06/21/2005	GW	045-13445	SCHICKLING 34-6C(L34)	X
278845	LEASE	PR	06/27/2005		-	SCHICKLING 34-5C(L34)	
278846	LEASE	PR	06/27/2005		-	SCHICKLING 34-6C(L34)	
334916	LOCATION	AC	04/14/2009		-	MAGNALL-66S92W 34NWSW	

Equipment: Location Inventory

Inspector Name: Baroumand, Soraya

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Signs/Marker:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
OTHER	Satisfactory	complete signage at separators with emergency contact information		
TANK LABELS/PLACARDS	Unsatisfactory	no placards on tanks	Install placard to comply with rule 210.d	03/29/2012
OTHER	Satisfactory	complete info at separators		

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____

Comment: signage at lease road access with emergency contact information

Corrective Action: _____

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
LOCATION	Satisfactory	wire fencing & panel gates		

Equipment:					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Emission Control Device	2	Satisfactory			
Pig Station	1	Satisfactory			
Bird Protectors		Satisfactory			
Vertical Heated Separator	6	Unsatisfactory	1 double-unit & 1 quad-unit separators. condensate & staining noted on separator surface gravels & have no secondary berms or dikes & is adjacent to a irrigation ditch	remove condensate & stained gravels & install secondary berming.	03/29/2012

Tanks/Berms:		<input type="checkbox"/> New Tank	Tank ID: _____		
Contents	#	Capacity	Type	SE GPS	
CONDENSATE	4	300 BBLS	HEATED STEEL AST	,	
S/U/V:	Satisfactory	Comment:	4 (250 bbl) insulated & heated tanks w/stacks and screens. no placards noted.		
Corrective Action:				Corrective Date:	
Paint					
Condition	Adequate				
Other (Content)	_____				
Other (Capacity)	_____				
Other (Type)	_____				
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Corrective Action				Corrective Date	
Comment					
Venting:					
Yes/No	Comment				
Flaring:					
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date	

Predrill

Location ID: 334916

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____

CDP Num.: _____

Form 2A COAs:

Wildlife BMPs:

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____

Phone Number: _____

Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Well

Facility ID: 266566

API Number: 045-09153

Status: PR

Insp. Status: PR

BradenHead

Comment: 18 psi

CA: _____

CA Date: _____

Facility ID: 266567

API Number: 045-09154

Status: PR

Insp. Status: PR

BradenHead

Comment: 10 psi

CA: _____

CA Date: _____

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? Pass CM _____
 CA _____ CA Date _____
 Waste Material Onsite? Pass CM _____
 CA _____ CA Date _____
 Unused or unneeded equipment onsite? Pass CM _____
 CA _____ CA Date _____
 Pit, cellars, rat holes and other bores closed? Pass CM _____
 CA _____ CA Date _____
 Guy line anchors removed? _____ CM _____
 CA _____ CA Date _____
 Guy line anchors marked? Pass CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? Pass

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? Pass Segregated soils have been replaced? Pass

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced Pass Recontoured Pass 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____ F _____

Comment: Russian knapweed has encroached location and was identified along the east-southeast location perimeter adjacent to irrigation ditch. Vegetative density of areas not needed adequate but not quite 80% density in some areas

Overall Interim Reclamation Pass

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Inspector Name: Baroumand, Soraya

Compaction alleviation _____ Dust and erosion control _____
Non cropland: Revegetated 80% _____ Cropland: perennial forage _____
Weeds present _____ Subsidence _____
Comment: _____
Corrective Action: _____ Date _____

Overall Final Reclamation

Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding	Pass					
Other	Pass					vegetated visibility berm to the south
Ditches	Pass					
Berms	Pass					

S/U/V: Satisfactory Corrective Date: _____
Comment: _____
CA: _____