

**FORM
INSP**

Rev
05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
02/17/2012

Document Number:
662300215

Overall Inspection:
Violation

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name: <u>NEIDEL, KRIS</u>
	<u>223266</u>	<u>313006</u>		

Operator Information:

OGCC Operator Number: <u>44350</u>	Name of Operator: <u>J-W OPERATING COMPANY</u>
Address: <u>7074 S REVERE PKWY</u>	
City: <u>CENTENNIAL</u>	State: <u>CO</u> Zip: <u>80112</u>

Contact Information:

Contact Name	Phone	Email	Comment
KOEHLER, BOB		bob.koehler@state.co.us	
molte, Shauna	(303) 422-4990	snolte@jwenergy.com	

Compliance Summary:

QtrQtr: <u>SENW</u>	Sec: <u>19</u>	Twp: <u>12N</u>	Range: <u>91W</u>
---------------------	----------------	-----------------	-------------------

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
07/19/1999	500154654	PR	PR			P	N
03/28/1995	500154653	ID	SI			P	N

Inspector Comment:

well does not show production for greater than 2 years. Plug, produce or MIT; RULE 326.B. location in disrepair.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name
100590	PIT		09/23/1999		-	HEDGES 1-19
223266	WELL	SI	10/01/1990		081-06630	HEDGES 1-19
313006	LOCATION	AC	04/14/2009		-	HEDGES-612N91W 19SENW

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Signs/Marker:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
OTHER	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory

Corrective Date: _____

Comment:	
Corrective Action:	

Good Housekeeping:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
UNUSED EQUIPMENT	Unsatisfactory	chart recorder,etc	remove equipment not necessary for production.	05/01/2012
WEEDS	Violation	weeds everywhere, overrun location.	Treat/remove weeds per rule 603.j	05/01/2012
DEBRIS	Unsatisfactory	old oil bbl, old fence.	remove equipment not necessary for production.	05/01/2012

Spills:				
Type	Area	Volume	Corrective action	CA Date

Multiple Spills and Releases?

Fencing/:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
PIT	Unsatisfactory	falling over,	fix or remove.	05/01/2012

Equipment:					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
FWKO	1	Satisfactory			

Venting:	
Yes/No	Comment
NO	

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 313006

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____
Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Wildlife BMPs:

Stormwater:

Comment:

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Well

Facility ID: 223266 API Number: 081-06630 Status: SI Insp. Status: SI

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS: _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Inspector Name: NEIDEL, KRIS

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____
 Debris removed _____ No disturbance /Location never built _____
 Access Roads Regraded _____ Contoured _____ Culverts removed _____
 Gravel removed _____
 Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____
 Compaction alleviation _____ Dust and erosion control _____
 Non cropland: Revegetated 80% _____ Cropland: perennial forage _____
 Weeds present _____ Subsidence _____
 Comment: _____
 Corrective Action: _____ Date _____

Overall Final Reclamation

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: _____ Corrective Date: _____
 Comment: _____
 CA: _____

Pits:

Pit Type: Produced Water Lined: NO Pit ID: _____ Lat: _____ Long: _____

Lining:
 Liner Type: _____ Liner Condition: _____
 Comment: _____

Fencing:
 Fencing Type: None Fencing Condition: Inadequate
 Comment: _____

Netting:
 Netting Type: Mesh Netting Condition: _____
 Comment: _____

Anchor Trench Present: NO Oil Accumulation: NO 2+ feet Freeboard: _____

Pit (S/U/V): Unsatisfactory Comment: no permed, plumbed off FWKO, not lined, no contents, no weeds growing inside pit, weeds are all over everywhere else.

Corrective Action: _____ Date: _____

Pits:

Inspector Name: NEIDEL, KRIS

Pit Type: Blowdown Lined: NO Pit ID: _____ Lat: _____ Long: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: _____

Fencing:

Fencing Type: Safety Fencing Condition: Inadequate

Comment: _____

Netting:

Netting Type: Fence/Net Netting Condition: _____

Comment: _____

Anchor Trench Present: NO Oil Accumulation: NO 2+ feet Freeboard: _____

Pit (S/U/V): Unsatisfactory Comment: not permitted, plumbed to wellhead.

Corrective Action: _____ Date: _____