

FORM
5A

Rev
02/08

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Document Number:

400253942

COMPLETED INTERVAL REPORT

The completed interval Report, Form 5A, shall be submitted within thirty (30) days of completing a formation (successful or not), when a formation is temporarily abandoned or permanently abandoned, for a recompletion, reperforation or restimulation, or when a formation is commingled. Fill out a section for each formation. Attach as many pages as required to fully describe the work. List in order of completion.

1. OGCC Operator Number: 66571

4. Contact Name: Joan Proulx

2. Name of Operator: OXY USA WTP LP

Phone: (970) 263-3641

3. Address: P O BOX 27757

Fax: (970) 263-3694

City: HOUSTON State: TX Zip: 77227

5. API Number 05-045-17767-00

6. County: GARFIELD

7. Well Name: SHELL

Well Number: 697-34-08B

8. Location: QtrQtr: NWNE Section: 3 Township: 7S Range: 97W Meridian: 6

9. Field Name: GRAND VALLEY Field Code: 31290

Completed Interval

FORMATION: WILLIAMS FORK - CAMEO

Status: PRODUCING

Treatment Date: 03/30/2010

Date of First Production this formation: 04/11/2010

Perforations Top: 5646 Bottom: 7293 No. Holes: 156 Hole size: 36/100

Provide a brief summary of the formation treatment:

Open Hole: ☐

7 stages of slickwater frac with 24,006 bbls of frac fluid and 775,656 lbs of white sand proppant

This formation is commingled with another formation: ☐ Yes ☒ No

Test Information:

Date: 01/26/2012 Hours: 24 Bbls oil: 0 Mcf Gas: 291 Bbls H2O: 305

Calculated 24 hour rate: Bbls oil: 0 Mcf Gas: 291 Bbls H2O: 305 GOR: 0

Test Method: Flowing Casing PSI: 381 Tubing PSI: 781 Choke Size: 24/64

Gas Disposition: SOLD Gas Type: DRY BTU Gas: 1460 API Gravity Oil: 0

Tubing Size: 2 + 3/8 Tubing Setting Depth: 6895 Tbg setting date: 01/23/2012 Packer Depth:

Reason for Non-Production:

Date formation Abandoned: Squeeze: ☐ Yes ☐ No If yes, number of sacks cmt

Bridge Plug Depth: Sacks cement on top:

Comment:

The 697-34-08B well went through a clean-out process, and a leak was discovered in the tubing at 496'. The tubing was pulled and re-landed at 6,895', and the well was returned to production.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: Print Name: Joan Proulx

Title: Regulatory Analyst Date: 2/21/2012 Email joan_proulx@oxy.com

Attachment Check List

Att Doc Num	Name
400253942	FORM 5A SUBMITTED

Total Attach: 1 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Permit	No WBD available.	3/2/2012 11:12:07 AM

Total: 1 comment(s)