

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Inspection Date:

02/10/2012

Document Number:

656500068

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name: HELGELAND, GARY
	247529	327925		

Operator Information:OGCC Operator Number: 47120 Name of Operator: KERR-MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVERState: COZip: 80217-**Contact Information:**

Contact Name	Phone	Email	Comment
Eikenberg, Cory	/10318	cory.eikenberg@anadarko.com	Wattenberg North Prod'n Supervisor

Compliance Summary:QtrQtr: SWSE Sec: 22 Twp: 3N Range: 67W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
07/21/2008	200193373	PR	PR	S			N
04/20/1998	500172142	PR	PR			P	N

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
247529	WELL	PR	05/08/2011	GW	123-15326	JOHNNIE ULRICH UNIT NAV 2	<input checked="" type="checkbox"/>
327925	LOCATION	AC	04/14/2009		-	JOHNNIE ULRICH UNIT /NAV/- 63N67W 22SWSE	<input type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

LocationEmergency Contact Number: (S/U/V) _____

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date

Inspector Name: HELGELAND, GARY

☐ Multiple Spills and Releases?

Venting:		
Yes/No	Comment	

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 327925

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:

Wildlife BMPs:

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

--

Summary of Operator Response to Landowner Issues:

--

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

--

Well

Facility ID: 247529 API Number: 123-15326 Status: PR Insp. Status: PR

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____	GPS: Lat _____	Long _____
Proximity to Surface Water: _____	Depth to Ground Water: _____	

Water Well:

DWR Receipt Num: _____	Owner Name: _____	GPS : _____
Lat _____ Long _____		

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a.	Debris removed? <u>Pass</u>	CM _____	
	CA _____		CA Date _____
	Waste Material Onsite? <u>Pass</u>	CM _____	
	CA _____		CA Date _____
	Unused or unneeded equipment onsite? <u>Pass</u>	CM _____	
	CA _____		CA Date _____
	Pit, cellars, rat holes and other bores closed? <u>Pass</u>	CM _____	
	CA _____		CA Date _____
	Guy line anchors removed? <u>Pass</u>	CM _____	
	CA _____		CA Date _____
	Guy line anchors marked? _____	CM _____	
	CA _____		CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass1003c. Compacted areas have been cross ripped? Pass1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? Pass Segregated soils have been replaced? Pass**RESTORATION AND REVEGETATION**CroplandTop soil replaced Pass Recontoured Pass Perennial forage re-established PassNon-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds?	P
Comment:	
Overall Interim Reclamation	Pass

Date Final Reclamation Started:	_____	Date Final Reclamation Completed:	_____
Final Land Use:	_____		
Reminder:	_____		
Comment:	_____		
Well plugged	_____	Pit mouse/rat holes, cellars backfilled	_____
Debris removed	_____	No disturbance /Location never built	_____
Access Roads	Regraded _____	Contoured _____	Culverts removed _____
	Gravel removed _____		
Location and associated production facilities reclaimed	_____	Locations, facilities, roads, recontoured	_____
Compaction alleviation	_____	Dust and erosion control	_____
Non cropland: Revegetated 80%	_____	Cropland: perennial forage	_____
Weeds present	_____	Subsidence	_____
Comment:	_____		
Corrective Action:	_____		Date _____
Overall Final Reclamation			

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: _____	Corrective Date: _____
Comment: _____	
CA: _____	