

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

03/08/2012

Document Number:

661600841

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name: MONTOYA, JOHN
	414449	414451		

Operator Information:OGCC Operator Number: 27742 Name of Operator: EOG RESOURCES INCAddress: 600 17TH ST STE 1100NCity: DENVERState: COZip: 80202**Contact Information:**

Contact Name	Phone	Email	Comment
Gardner, Kaylene	435-781-9111	kaylene_gardner@eogresources.com	

Compliance Summary:QtrQtr: SESE Sec: 16 Twp: 11N Range: 63W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
04/12/2008	200242332	DG	DG	S			N

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
414449	WELL	PR	03/19/2010		123-30749	RED POLL 10-16H	<input checked="" type="checkbox"/>
414451	LOCATION	AC	11/13/2009		-	RED POLL 10-16H	<input type="checkbox"/>
417049	PIT	AC	05/18/2010		-	RED POLL 10-16H	<input type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: <u>1</u>	Drilling Pits: <u>1</u>	Wells: <u>1</u>	Production Pits: <u> </u>
Condensate Tanks: <u> </u>	Water Tanks: <u> </u>	Separators: <u>1</u>	Electric Motors: <u>2</u>
Gas or Diesel Mortors: <u> </u>	Cavity Pumps: <u> </u>	LACT Unit: <u> </u>	Pump Jacks: <u>1</u>
Electric Generators: <u> </u>	Gas Pipeline: <u> </u>	Oil Pipeline: <u> </u>	Water Pipeline: <u> </u>
Gas Compressors: <u> </u>	VOC Combustor: <u> </u>	Oil Tanks: <u>7</u>	Dehydrator Units: <u> </u>
Multi-Well Pits: <u> </u>	Pigging Station: <u> </u>	Flare: <u>1</u>	Fuel Tanks: <u> </u>

Location**Signs/Marker:**

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
BATTERY	Satisfactory			
CONTAINERS	Satisfactory			
WELLHEAD	Satisfactory			

Inspector Name: MONTOYA, JOHN

TANK LABELS/PLACARDS	Satisfactory			
----------------------	--------------	--	--	--

Emergency Contact Number: (S/U/V) _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Fencing/:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
------	-----------------------------	---------	-------------------	---------

PUMP JACK Satisfactory

Equipment:

Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Veritcal Heater Treater	1	Satisfactory			
Emission Control Device	1	Satisfactory			
Flare	1	Satisfactory			
Bird Protectors	3	Satisfactory			
Vertical Separator	1	Satisfactory			
Deadman # & Marked	4	Satisfactory			
Horizontal Heater Treater	1	Satisfactory			
Ancillary equipment	4	Satisfactory	propane tank, recycle pump, gas dryer, ambitrol storage tank, OK		
Pump Jack	1	Satisfactory			
Gas Meter Run	1	Satisfactory			

Tanks/Berms: ☐ New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	2	400 BBLS	STEEL AST	,

S/U/V:		Comment:	
Corrective Action:		Corrective Date:	

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action		Corrective Date	
-------------------	--	-----------------	--

Comment	
---------	--

Tanks/Berms: ☐ New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
CRUDE OIL	4	400 BBLS	STEEL AST	40.915940, -104.430960

S/U/V:		Comment:	
Corrective Action:		Corrective Date:	

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action		Corrective Date	
-------------------	--	-----------------	--

Comment	
---------	--

Venting:	
Yes/No	Comment
YES	

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Field Flare				

Predrill

Location ID: 414451

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Wildlife BMPs:****Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:**Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Well**

Facility ID: 414449 API Number: 123-30749 Status: PR Insp. Status: PR

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Inspector Name: MONTOYA, JOHN

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment: _____

Inspector Name: MONTOYA, JOHN

Well plugged _____	Pit mouse/rat holes, cellars backfilled _____		
Debris removed _____	No disturbance /Location never built _____		
Access Roads _____	Regraded _____	Contoured _____	Culverts removed _____
Gravel removed _____			
Location and associated production facilities reclaimed _____		Locations, facilities, roads, recontoured _____	
Compaction alleviation _____		Dust and erosion control _____	
Non cropland: Revegetated 80% _____		Cropland: perennial forage _____	
Weeds present _____		Subsidence _____	
Comment: _____			
Corrective Action: _____			Date _____

Overall Final Reclamation

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: _____	Corrective Date: _____
Comment: _____	
CA: _____	

Permit:	Facility ID	Permit Num	Expiration Date
	417049	200246524	