Inspector Name: QUINT, CRAIG

FORM INSP Rev 05/11

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109

FIELD INSPECTION FORM

DE	ET	OE	ES

Inspection Date: 03/09/2012

Document Number: 663900746

Overall Inspection: Satisfactory

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name:
	213351	324873		QUINT, CRAIG

Operator Information:

OGCC Operator Number: 81480 Name of Operator: THOMAS L SPRING LLC

Address: 7400 E ORCHARD RD STE 2000

City: GREENWOOD State: CO Zip: 80111

Contact Information:

Contact Name	Phone	Email	Comment
Springs, Tom	303-771-1889 off	T1spring@aol.com	

Compliance Summary:

QtrQtr: SESE Sec: 29 Twp: 20S Range: 48W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
11/15/2010	200285016	PR	PR	S			N
06/01/2009	200211639	PR	PR	S			N
11/02/2007	200121495	PR	PR	S			N
04/16/2007	200109397	PR	PR	U		F	Y
03/16/2000	200005235	PR	PR	S	I	P	N
04/08/1997	500145691	ID	SI			P	N
12/07/1995	500145690	PR	PR			P	Y

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
102511	PIT		09/23/1999		-	WARNE TEMPLIN 1-29	
213351	WELL	SI	10/27/2011	GW	061-06713	WARNE TEMPLIN 1-29	X
324873	LOCATION	AC	04/14/2009		-	WARNE TEMPLIN-620S48W 29SESE	

Equipment: Location Inventory

Special Purpose Pits:		Drilling Pits:		Wells:		Production Pits:	
Condensate Tanks:		Water Tanks:		Separators:		Electric Motors:	
Gas or Diesel Mortors:		Cavity Pumps:		LACT Unit:		Pump Jacks:	
Electric Generators:		Gas Pipeline:		Oil Pipeline:		Water Pipeline:	
Gas Compressors:		VOC Combustor:		Oil Tanks:		Dehydrator Units:	
Multi-Well Pits:		Pigging Station:		Flare:		Fuel Tanks:	

Location

Inspector Name: QUINT, CRAIG

Lease Road:

Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Access	Satisfactory	2 TRACK THROUGH PASTURE		

Signs/Marker:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory	LEASE SIGN MOUNTED ON SEPARATOR.		
TANK LABELS/PLACARDS	Satisfactory	METAL SIGN BY TANK		
OTHER	Unsatisfactory	NO VISIBLE WELL SIGN BY METER RUN 4500' SW OF WELL HEAD BY ROAD A-50.	Install sign to comply with rule 210.b.	**06/11/2012**

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date:

Comment:

Corrective Action:

Spills:

Type	Area	Volume	Corrective action	CA Date

☐ Multilple Spills and Releases?

Equipment:

Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Plunger Lift	1	Satisfactory			
Gas Meter Run	1	Satisfactory	4500' SW BY COMPRESSOR STATION NORTH SIDE OF ROAD A-50.		
Horizontal Heated Separator	1	Satisfactory			

Inspector Name: QUINT, CRAIG

Tanks/Berms: ☐ New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	<50 BBLS	Open Top	38.284810,-102.807240

S/U/V:	Satisfactory	Comment:	40BBL OPEN TOP FIBERGLASS TANK W/ADEQUATE WILDLIFE SCREENING.

Corrective Action:		Corrective Date:	

Paint

Condition	

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Corrective Action		Corrective Date	
Comment			

Venting:	
Yes/No	Comment
NO	

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 324873

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Wildlife BMPs:

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Well

Facility ID: 213351 API Number: 061-06713 Status: SI Insp. Status: PR

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well: Lat Long

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ _____

Field Parameters:

Sample Location: _____

Inspector Name: QUINT, CRAIG

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use:

Comment:

1003a. Debris removed? Pass CM

CA CA Date

Waste Material Onsite? Pass CM

CA CA Date

Unused or unneeded equipment onsite? Pass CM

CA CA Date

Pit, cellars, rat holes and other bores closed? Pass CM

CA CA Date

Guy line anchors removed? CM

CA CA Date

Guy line anchors marked? CM

CA CA Date

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped?

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management:

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Pass

Production areas have been stabilized? Pass Segregated soils have been replaced? Pass

RESTORATION AND REVEGETATION

Cropland

Top soil replaced Recontoured Perennial forage re-established

Non-Cropland

Top soil replaced Pass Recontoured Pass 80% Revegetation Pass

1003 f. Weeds Noxious weeds? P

Comment: UNUSED AREAS OF THE LOCATION ARE PASTURE

Overall Interim Reclamation Pass

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: Date Final Reclamation Completed:

Final Land Use:

Reminder:

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment:

Corrective Action: Date _____

Overall Final Reclamation

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Compaction	Pass			

S/U/V: Satisfactory Corrective Date: _____

Comment:

CA: