

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
03/02/2012

Document Number:
667600087

Overall Inspection:
Satisfactory

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name:
	<u>417529</u>	<u>317936</u>		<u>HICKEY, MIKE</u>

Operator Information:

OGCC Operator Number:	<u>47120</u>	Name of Operator:	<u>KERR-MCGEE OIL & GAS ONSHORE LP</u>
Address:	<u>P O BOX 173779</u>		
City:	<u>DENVER</u>	State:	<u>CO</u>
		Zip:	<u>80217-</u>

Contact Information:

Contact Name	Phone	Email	Comment
Kilcrease, Keith	/24135	keith.kilcrease@anadarko.com	Production Superintendent

Compliance Summary:

QtrQtr:	<u>SWNE</u>	Sec:	<u>2</u>	Twp:	<u>1N</u>	Range:	<u>66W</u>
---------	-------------	------	----------	------	-----------	--------	------------

Inspector Comment:

Routine inspection of new well API #05-123-31687, Highway 160 24-2.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
240207	WELL	PR	11/14/2008	OW	123-07995	BROWN, GORDON D. UNIT 1	<input checked="" type="checkbox"/>
317936	LOCATION	AC	04/14/2009		-	HIGHWAY 160 7-2	<input type="checkbox"/>
417525	WELL	PR	05/20/2011		123-31683	HIGHWAY 160 41-2	<input checked="" type="checkbox"/>
417526	WELL	PR	03/04/2011		123-31684	HIGHWAY 160 1-2	<input checked="" type="checkbox"/>
417529	WELL	PR	05/20/2011		123-31687	HIGHWAY 160 24-2	<input checked="" type="checkbox"/>
417530	WELL	PR	05/17/2011	GW	123-31688	HIGHWAY 160 8-2S	<input checked="" type="checkbox"/>
417533	WELL	PR	01/23/2011		123-31690	HIGHWAY 160 8-2	<input checked="" type="checkbox"/>
417537	WELL	PR	01/17/2011		123-31691	HIGHWAY 160 7-2	<input checked="" type="checkbox"/>
417539	WELL	PR	01/11/2011		123-31692	HIGHWAY 160 2-2	<input checked="" type="checkbox"/>
417543	WELL	PR	07/14/2011		123-31693	HIGHWAY 160 1-2S	<input checked="" type="checkbox"/>
417544	WELL	PR	01/20/2011		123-31694	HIGHWAY 160 26-2	<input checked="" type="checkbox"/>
417546	WELL	PR	05/27/2010		123-31695	HIGHWAY 160 2-2S	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: <u>1</u>	Wells: <u>11</u>	Production Pits: _____
Condensate Tanks: _____	Water Tanks: <u>1</u>	Separators: <u>11</u>	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: <u>1</u>	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: <u>1</u>	Oil Tanks: <u>11</u>	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: <u>1</u>	Fuel Tanks: <u>11</u>

Location

Signs/Marker:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory			
BATTERY	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
LOCATION	Satisfactory			

Equipment:					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Plunger Lift	1	Satisfactory			

Tanks/Berms: New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
CRUDE OIL				

S/U/V: _____ Comment: Shared battery. See inspection of API #05-123-07995 for battery/separator inspection.

Corrective Action: _____ Corrective Date: _____

Paint

Condition: _____

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Corrective Action: _____ Corrective Date: _____

Comment: _____

Venting:	
Yes/No	Comment

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 317936

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____
 Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Wildlife BMPs:

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Well

Facility ID: 240207 API Number: 123-07995 Status: PR Insp. Status: PR

Facility ID: 417525 API Number: 123-31683 Status: PR Insp. Status: PR

Facility ID: 417526 API Number: 123-31684 Status: PR Insp. Status: PR

Facility ID: 417529 API Number: 123-31687 Status: PR Insp. Status: PR

Facility ID: 417530 API Number: 123-31688 Status: PR Insp. Status: PR

Facility ID: 417533 API Number: 123-31690 Status: PR Insp. Status: PR

Facility ID: 417537 API Number: 123-31691 Status: PR Insp. Status: PR

Facility ID: 417539 API Number: 123-31692 Status: PR Insp. Status: PR

Facility ID: 417543 API Number: 123-31693 Status: PR Insp. Status: PR

Facility ID: 417544 API Number: 123-31694 Status: PR Insp. Status: PR

Facility ID: 417546 API Number: 123-31695 Status: PR Insp. Status: PR

Environmental

Spills/Releases:

Type of Spill: Description: Estimated Spill Volume:
Comment:
Corrective Action: Date:
Reportable: GPS: Lat Long
Proximity to Surface Water: Depth to Ground Water:

Water Well:

DWR Receipt Num: Owner Name: GPS: Lat Long

Field Parameters:

Sample Location:

Emission Control Burner (ECB):

Comment:
Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use: DRY LAND

Comment:

1003a. Debris removed? CM
CA CA Date
Waste Material Onsite? CM
CA CA Date
Unused or unneeded equipment onsite? CM
CA CA Date
Pit, cellars, rat holes and other bores closed? CM
CA CA Date
Guy line anchors removed? CM
CA CA Date
Guy line anchors marked? CM
CA CA Date

1003b. Area no longer in use? Production areas stabilized ?

1003c. Compacted areas have been cross ripped?

Inspector Name: HICKEY, MIKE

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
Cuttings management: _____
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: DRY LAND

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: _____ Corrective Date: _____

Comment: _____

CA: _____