

FORM INSP
Rev 05/11

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
03/01/2012

Document Number:
659400299

Overall Inspection:
Satisfactory

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name: <u>DURAN, JOHN</u>
	<u>295966</u>	<u>333421</u>		

Operator Information:

OGCC Operator Number: <u>10084</u>	Name of Operator: <u>PIONEER NATURAL RESOURCES USA INC</u>
Address: <u>1401 17TH ST STE 1200</u>	
City: <u>DENVER</u>	State: <u>CO</u> Zip: <u>80202</u>

Contact Information:

Contact Name	Phone	Email	Comment
HISS, DUANE	719-845-4394/719-680-0024	duane.hiss@ pxd.com	
GLINISTY, JUDY	303-675-2658	Judy.Glinisty @pxd.com	

Compliance Summary:

QtrQtr: <u>NWSE</u>	Sec: <u>36</u>	Twp: <u>31S</u>	Range: <u>66W</u>
---------------------	----------------	-----------------	-------------------

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
06/28/2011	200314161	RT	AC	S			N
08/25/2010	200268279	RT	AC	S			N
06/22/2009	200213462	RT	AC	S			N
12/22/2008	200201511	MI	SI	S			N
12/18/2008	200201509	MI	SI	S			N

Inspector Comment:

(MiT) Mechanical Integrity Test : Pressured up T-C Ann. to 1060 psig. Pressure held for 15 min. with no pressure loss.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name
159257	UIC DISPOSAL	AC	01/20/2009		-	SOUTHPAW 33-36 WD
258246	WELL	PR	08/11/2001	GW	071-07088	SOUTHPAW 33-36
273015	LEASE	PR	06/25/2004		-	SOUTHPAW 33-36
274259	PIT	AC	10/21/2004		-	SOUTHPAW 33-36 ONSITE
295966	WELL	IJ	06/13/2011	DSPW	071-09594	SOUTHPAW 33-36 WD
333421	LOCATION	AC	04/14/2009		-	SOUTHPAW-631S66W 36NWSE
414724	PIT	AC	12/14/2009		-	SOUTPAW SPEICAL USE 33-36 WD

Equipment:

Location Inventory

--

Inspector Name: DURAN, JOHN

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Signs/Marker:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
PIT	Satisfactory			

Equipment:					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Deadman # & Marked	4	Satisfactory	Filtration BLDG., Pumpshed.		

Tanks/Berms: New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	2	1000 BBLS	FIBERGLASS AST	,

S/U/V: Satisfactory Comment: _____

Corrective Action: _____ Corrective Date: _____

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action _____ Corrective Date _____

Comment _____

Venting:		
Yes/No	Comment	

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill	
Location ID: <u>333421</u>	
Site Preparation:	
Lease Road Adeq.: _____	Pads: _____
Soil Stockpile: _____	
Corrective Action: _____	Date: _____ CDP Num.: _____
Form 2A COAs:	
Wildlife BMPs:	
Stormwater:	
Comment: _____	
Staking:	
On Site Inspection (305):	
<u>Surface Owner Contact Information:</u>	
Name: _____	Address: _____
Phone Number: _____	Cell Phone: _____
<u>Operator Rep. Contact Information:</u>	
Landman Name: _____	Phone Number: _____
Date Onsite Request Received: _____	Date of Rule 306 Consultation: _____
Request LGD Attendance: _____	
<u>LGD Contact Information:</u>	
Name: _____	Phone Number: _____
Agreed to Attend: _____	
<u>Summary of Landowner Issues:</u>	

<u>Summary of Operator Response to Landowner Issues:</u>	

<u>Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:</u>	

Well	

Facility ID: 295966 API Number: 071-09594 Status: IJ Insp. Status: IJ

Underground Injection Control

UIC Violation: Maximum Injection Pressure:

UIC Routine

Inj./Tube: Pressure or inches of Hg Previous Test Pressure MPP Inj Zone: DKENT

TC: Pressure or inches of Hg Previous Test Pressure Last MIT: 01/07/2009

Brhd: Pressure or inches of Hg Previous Test Pressure AnnMTReq:

Comment:

Method of Injection:

Test Type: Verification of Repairs Tbg psi: Csg psi: 1060 BH psi:

Insp. Status: Pass

Comment: Change packer and tubing from 2 7/8" to 3 1/2" to increase water flow. Well Shut In, no inj. pressure. Pressured up T - C Ann. to 1060 psig. Pressure held for 15 min. with no pressure loss.

Environmental

Spills/Releases:

Type of Spill: Description: Estimated Spill Volume:

Comment:

Corrective Action: Date:

Reportable: GPS: Lat Long

Proximity to Surface Water: Depth to Ground Water:

Water Well:

Lat Long

DWR Receipt Num: Owner Name: GPS:

Field Parameters:

Sample Location:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use:

Comment:

1003a. Debris removed? CM

CA CA Date

Waste Material Onsite? CM

CA CA Date

Unused or unneeded equipment onsite? CM

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____

Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits:

Pit Type: Produced Water Lined: YES Pit ID: _____ Lat: _____ Long: _____

Lining:
 Liner Type: _____ Liner Condition: _____
 Comment: _____

Fencing:
 Fencing Type: _____ Fencing Condition: _____
 Comment: _____

Netting:
 Netting Type: _____ Netting Condition: _____
 Comment: _____

Anchor Trench Present: _____ Oil Accumulation: NO 2+ feet Freeboard: _____

Pit (S/U/V): Satisfactory Comment: 30' X 70'

Corrective Action: _____ Date: _____

Permit:	Facility ID	Permit Num	Expiration Date
	274259	1230358	
	414724	1841369	
	414724	200223781	