

**FORM  
INSP**Rev  
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

03/23/2012

Document Number:

661700213

Overall Inspection:

**Violation****FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name:
	<u>284891</u>	<u>333406</u>		<u>LABOWSKIE, STEVE</u>

**Operator Information:**OGCC Operator Number: 76104 Name of Operator: SAMSON RESOURCES COMPANYAddress: TWO WEST SECOND STCity: TULSA State: OK Zip: 74103**Contact Information:**

Contact Name	Phone	Email	Comment
Deater, Shanelle		sdeater@samson.com	Regulatory Specialist (Denver)

**Compliance Summary:**QtrQtr: SESW Sec: 30 Twp: 33N Range: 7W**Inspector Comment:**

Large motor oil leak at muffler on ground by pumping unit. This requires immediate clean-up and might be reportable if it's determined to be greater than 5 bbls. Excavate all stained soil and determine extent of contamination. See attached picture.

**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
216465	WELL	PR	04/22/1997	GW	067-08071	IGNACIO 33-7 19A	<input type="checkbox"/>
284891	WELL	PR	01/11/2012	GW	067-09177	BROOME 33-7-30 3	<input checked="" type="checkbox"/>
333406	LOCATION	AC	04/14/2009		-	IGNACIO 33-7-N33N7W 30SESW	<input type="checkbox"/>

**Equipment:**Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location**Emergency Contact Number: (S/U/V) \_\_\_\_\_

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

**Good Housekeeping:**

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WEEDS		dead thistles in interim rec area	remove dead weeds and control regrowth	

<b>Spills:</b>				
Type	Area	Volume	Corrective action	CA Date
Lube Oil	Pump Jack	<= 5 bbls	stop leaking muffler and clean spill and stained soil	03/02/2012

☐ Multiple Spills and Releases?

<b>Fencing/:</b>				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
PUMP JACK		guard fence and mesh fence		

<b>Equipment:</b>					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Pump Jack	1	Unsatisfactory	see oil leak/spill above	stop releases of oil onto ground	03/02/2012
Deadman # & Marked	4		1 needs to be re-marked		
Horizontal Heated Separator	1		combined unit with meter run and telemetry equipment		

<b><u>Tanks/Berms:</u></b>		<input type="checkbox"/> New Tank	Tank ID: _____		
Contents		#	Capacity	Type	SE GPS
LUBE OIL		1	OTHER	STEEL AST	,
S/U/V:	Unsatisfactory		Comment:		
Corrective Action:		label lube oil tank with proper NFPA placard, install secondary containment			Corrective Date: 05/01/2012

**Paint**

Condition	Adequate
-----------	----------

Other (Content) \_\_\_\_\_

Other (Capacity) \_\_\_\_\_

Other (Type) \_\_\_\_\_

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Corrective Action		Corrective Date	
Comment			

<b>Venting:</b>			
Yes/No	Comment		

<b>Flaring:</b>				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

**Predrill**

Location ID: 333406

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_

Pads: \_\_\_\_\_

Soil Stockpile: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:****Wildlife BMPs:****Stormwater:****Comment:** \_\_\_\_\_**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Well**

Facility ID: 284891 API Number: 067-09177 Status: PR Insp. Status: PR

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Inspector Name: LABOWSKIE, STEVE

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Debris removed? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Waste Material Onsite? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? Fail CM \_\_\_\_\_ 1 needs re-marked

CA mark anchor \_\_\_\_\_ CA Date **05/01/2012**

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: watch for weeds in this area, dead weeds remian from last season with seed pods

Overall Interim Reclamation \_\_\_\_\_

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Inspector Name: LABOWSKIE, STEVE

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_  
Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_  
Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_  
Gravel removed \_\_\_\_\_  
Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_  
Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_  
Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_  
Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_  
Comment: \_\_\_\_\_  
Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
S/U/V: _____ Corrective Date: _____						
Comment: _____						
CA: _____						

**COGCC Comments**

Comment	User	Date
Engine oil accumulation at muffler, first in bucket, then overflowing is a violation. Clean-up by March 30 or NOAV will be issued. Report spill if determined to be more than 5 bbls.	labowsks	03/26/2012

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
661700213	INSPECTION APPROVED	<a href="http://cogcc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=2891201">http://cogcc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=2891201</a>
661700214	Lube oil release	<a href="http://cogcc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=2891199">http://cogcc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=2891199</a>