

**FORM  
INSP**Rev  
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

03/20/2012

Document Number:

663800212

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name:
	<u>282307</u>	<u>335574</u>		<u>LONGWORTH, MIKE</u>

**Operator Information:**OGCC Operator Number: 100185 Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVERState: COZip: 80202-**Contact Information:**

Contact Name	Phone	Email	Comment
Friesen, Kathy	970-285-2665	Kathy.Friesen@EnCana.com	

**Compliance Summary:**QtrQtr: NWNW Sec: 27 Twp: 5S Range: 95W**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
282307	WELL	PR	03/28/2007	LO	045-11718	N. PARACHUTE EF12B-22 D27595	<input checked="" type="checkbox"/>
282308	WELL	PR	05/09/2008	GW	045-11719	N. PARACHUTE EF05D-22D27 595	<input checked="" type="checkbox"/>
282309	WELL	PR	03/28/2007	LO	045-11720	N.PARACHTE EF11B-22 D27 59	<input checked="" type="checkbox"/>
282310	WELL	PR	03/28/2007	LO	045-11721	N. PARACHUTE EF09B-21D27 595	<input checked="" type="checkbox"/>
282311	WELL	PR	03/28/2007	LO	045-11722	N.PARACHUTE EF06D-22-D27 59	<input checked="" type="checkbox"/>
282312	WELL	PR	05/11/2008	GW	045-11723	N. PARACHUTE EF05B-22D27595	<input checked="" type="checkbox"/>
282313	WELL	PR	03/28/2007	LO	045-11724	N. PARACHUTE EF11D-22-D27 59	<input checked="" type="checkbox"/>
282314	WELL	PR	03/28/2007	LO	045-11728	N.PARACHUTE EF06B-22 D27 59	<input checked="" type="checkbox"/>
282315	WELL	PR	03/28/2007	LO	045-11729	N.PARACHUTE EF09B-22 D27 59	<input checked="" type="checkbox"/>
282316	WELL	PR	03/28/2007	LO	045-11730	N.PARACHUTE EF14B-22 D27 59	<input checked="" type="checkbox"/>
282317	WELL	PR	03/28/2007	LO	045-11731	N PARACHUTE EF10B22 D27 595	<input checked="" type="checkbox"/>
282318	WELL	PR	03/28/2007	LO	045-11732	N. PARACHUTE EF10D-22 D27 59	<input checked="" type="checkbox"/>
282334	WELL	PR	08/12/2008	OW	045-11748	N. PARACHUTE EF14B D27 595	<input checked="" type="checkbox"/>

282335	WELL	PR	11/26/2008	GW	045-11747	N.PARACHUTE EF 12B D27 595	X
282336	WELL	PR	12/20/2007	LO	045-11746	N. PARACHUTE EF13B D27 595	X
282338	WELL	PR	08/01/2008	OW	045-11745	N. PARACHUTE EF11B D27 595	X
282339	WELL	PR	12/01/2008	GW	045-11744	N.PARACHUTE EF 16B-28 D27 5	X
282340	WELL	PR	12/01/2008	OW	045-11743	N. PARACHUTE EF05B D27 595	X
282545	WELL	PR	12/09/2008	OW	045-11778	N. PARACHUTE EF08D-28 D27 59	X
282546	WELL	PR	12/05/2008	OW	045-11779	N. PARACHUTE EF05A-27 D27 59	X
282547	WELL	PR	11/30/2008	OW	045-11780	N. PARACHUTE EF09D-28 D27 59	X
282556	WELL	PR	12/04/2008	OW	045-11790	N. PARACHUTE EF09B-28 D27 59	X
282557	WELL	PR	12/05/2008	OW	045-11791	N. PARACHUTE EF13A-27 D27 59	X
282923	WELL	PR	08/10/2008	OW	045-11866	N. PARACHUTE EF12D D27 595	X
284001	PIT	AC	03/24/2006		-	NPR EF D@& 595	
291335	WELL	PR	07/10/2007	LO	045-14332	N.PARACHUTE EF03B D27 595	X
291336	WELL	PR	07/10/2007	LO	045-14333	N.PARACHUTE EF04D D27 595	X
291337	WELL	PR	07/10/2007	LO	045-14334	N.PARACHUTE EF02B D27 595	X
291338	WELL	PR	07/10/2007	LO	045-14335	N.PARACHUTE EF 15B-22 D27 5	X
335574	LOCATION	AC	04/14/2009		-	N. PARACHUTE-65S95W 27NWNW	

**Equipment:**Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location****Lease Road:**

Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Access	Satisfactory			

**Signs/Marker:**

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
BATTERY	Satisfactory			
CONTAINERS	Satisfactory			

Inspector Name: LONGWORTH, MIKE

TANK LABELS/PLACARDS	Satisfactory			
WELLHEAD	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

**Good Housekeeping:**

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
DEBRIS	Unsatisfactory	needle valves, gloves, sand, oil stains	pick up debri	04/06/2012
TRASH	Unsatisfactory	needle valves, gloves, sand, oil stains	pick up trash	04/06/2012

**Spills:**

Type	Area	Volume	Corrective action	CA Date
Lube Oil	WELLHEAD	<= 5 bbls	clean up oil stains around well heads	04/06/2012

☐ Multiple Spills and Releases?**Equipment:**

Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Plunger Lift	10	Satisfactory			
Plunger Lift	10	Satisfactory			
Plunger Lift	8	Satisfactory			
Gas Meter Run	5	Satisfactory	metersheds		

**Tanks/Berms:**☐ New Tank

Tank ID: \_\_\_\_\_

Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST	,

S/U/V: Satisfactory Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Corrective Date: \_\_\_\_\_

**Paint**

Condition	Adequate
-----------	----------

Other (Content) \_\_\_\_\_

Other (Capacity) \_\_\_\_\_

Other (Type) \_\_\_\_\_

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action build up berm Corrective Date 03/31/2012

Comment: \_\_\_\_\_

<b>Venting:</b>		
Yes/No	Comment	

<b>Flaring:</b>				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

**Predrill**

Location ID: 335574

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_

Pads: \_\_\_\_\_

Soil Stockpile: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:****Wildlife BMPs:****Stormwater:****Comment:** \_\_\_\_\_**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

**Operator Rep. Contact Information:**

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

**LGD Contact Information:**

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

**Summary of Landowner Issues:**

--

**Summary of Operator Response to Landowner Issues:**

--

**Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**

--

**Well**

Facility ID: 282307 API Number: 045-11718 Status: PR Insp. Status: PR

Facility ID: 282308 API Number: 045-11719 Status: PR Insp. Status: PR

Facility ID: 282309 API Number: 045-11720 Status: PR Insp. Status: PR

Facility ID: 282310 API Number: 045-11721 Status: PR Insp. Status: PR

Facility ID: 282311 API Number: 045-11722 Status: PR Insp. Status: PR

Inspector Name: LONGWORTH, MIKE

Facility ID: <u>282312</u>	API Number: <u>045-11723</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>282313</u>	API Number: <u>045-11724</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>282314</u>	API Number: <u>045-11728</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>282315</u>	API Number: <u>045-11729</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>282316</u>	API Number: <u>045-11730</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>282317</u>	API Number: <u>045-11731</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>282318</u>	API Number: <u>045-11732</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>282334</u>	API Number: <u>045-11748</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>282335</u>	API Number: <u>045-11747</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>282336</u>	API Number: <u>045-11746</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>282338</u>	API Number: <u>045-11745</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>282339</u>	API Number: <u>045-11744</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>282340</u>	API Number: <u>045-11743</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>282545</u>	API Number: <u>045-11778</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>282546</u>	API Number: <u>045-11779</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>282547</u>	API Number: <u>045-11780</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>282556</u>	API Number: <u>045-11790</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>282557</u>	API Number: <u>045-11791</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>282923</u>	API Number: <u>045-11866</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>291335</u>	API Number: <u>045-14332</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>291336</u>	API Number: <u>045-14333</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>291337</u>	API Number: <u>045-14334</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>291338</u>	API Number: <u>045-14335</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>

### Environmental

#### Spills/Releases:

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_  
 Comment:

Inspector Name: LONGWORTH, MIKE

Corrective Action: _____		Date: _____	
Reportable: _____	GPS: Lat _____	Long _____	
Proximity to Surface Water: _____		Depth to Ground Water: _____	

<b>Water Well:</b>		Lat _____	Long _____
DWR Receipt Num: _____	Owner Name: _____	GPS : _____	_____

<b>Field Parameters:</b>
--------------------------

Sample Location: _____
------------------------

Emission Control Burner (ECB): _____
Comment: _____
Pilot: _____ Wildlife Protection Devices (fired vessels): _____

**Reclamation - Storm Water - Pit**

<b>Interim Reclamation:</b>	
Date Interim Reclamation Started: _____	Date Interim Reclamation Completed: _____
Land Use: _____	
Comment: _____	
1003a.	Debris removed? _____ CM _____
	CA _____ CA Date _____
	Waste Material Onsite? _____ CM _____
	CA _____ CA Date _____
	Unused or unneeded equipment onsite? _____ CM _____
	CA _____ CA Date _____
	Pit, cellars, rat holes and other bores closed? _____ CM _____
	CA _____ CA Date _____
	Guy line anchors removed? _____ CM _____
	CA _____ CA Date _____
	Guy line anchors marked? _____ CM _____
	CA _____ CA Date _____
1003b.	Area no longer in use? _____ Production areas stabilized ? _____
1003c.	Compacted areas have been cross ripped? _____
1003d.	Drilling pit closed? _____ Subsidence over on drill pit? _____
	Cuttings management: _____
1003e.	Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
	Production areas have been stabilized? _____ Segregated soils have been replaced? _____
<b>RESTORATION AND REVEGETATION</b>	
<u>Cropland</u>	
Top soil replaced _____	Recontoured _____ Perennial forage re-established _____
<u>Non-Cropland</u>	

Inspector Name: LONGWORTH, MIKE

Top soil replaced \_\_\_\_\_

Recontoured \_\_\_\_\_

80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_

Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_

Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_

No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_

Contoured \_\_\_\_\_

Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_

Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_

Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_

Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_

Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date \_\_\_\_\_

Overall Final Reclamation

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: \_\_\_\_\_ Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
663800212	INSPECTION APPROVED	<a href="http://cogcc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=2896625">http://cogcc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=2896625</a>