

FORM
4
Rev 12/05

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303)894-2100 Fax: (303)894-2109



SUNDRY NOTICE

Submit original plus one copy. This form is to be used for general, technical and environmental sundry information. For proposed or completed operations, describe in full on Technical Information Page (Page 2 of this form.) Identify well or other facility by API Number or by OGCC Facility ID. Operator shall send an informational copy of all sundry notices for wells located in High Density Areas to the Local Government Designee (Rule 603b.)

RECEIVED
3/27/2012

1. OGCC Operator Number: 96850	4. Contact Name: Karolina Blaney	Complete the Attachment Checklist OP OGCC
2. Name of Operator: WPX Energy Rocky Mountain LLC	Phone: 970 683 2295	
3. Address: 1058 County Road 215 City: Parachute State: CO Zip: 81635	Fax: 970 285 9573	
5. API Number 05-045-06539	OGCC Facility ID Number 311557	Survey Plat
6. Well/Facility Name:	7. Well/Facility Number MV 23-27	Directional Survey
8. Location (Qtr/Qt, Sec, Twp, Rng, Meridian): NENE 27 6S 96W 06M		Surface Equipmt Diagram
9. County: Garfield	10. Field Name: Grand Valley	Technical Info Page
11. Federal, Indian or State Lease Number:		Other

General Notice

<input type="checkbox"/> CHANGE OF LOCATION: Attach New Survey Plat (a change of surface qtr/qtr is substantive and requires a new permit)	
Change of Surface Footage from Exterior Section Lines:	<input type="checkbox"/> FNL/FSL <input type="checkbox"/> FEL/FWL
Change of Surface Footage to Exterior Section Lines:	<input type="checkbox"/> <input type="checkbox"/>
Change of Bottomhole Footage from Exterior Section Lines:	<input type="checkbox"/> <input type="checkbox"/>
Change of Bottomhole Footage to Exterior Section Lines:	<input type="checkbox"/> <input type="checkbox"/> attach directional survey
Bottomhole location Qtr/Qt, Sec, Twp, Rng, Mer	
Latitude	Distance to nearest property line
Longitude	Distance to nearest bldg, public rd, utility or RR
Ground Elevation	Distance to nearest lease line
	Is location in a High Density Area (rule 603b)? Yes/No
	Distance to nearest well same formation
	Surface owner consultation date:
GPS DATA:	
Date of Measurement	PDOF Reading
	Instrument Operator's Name
<input type="checkbox"/> CHANGE SPACING UNIT	
Formation	Formation Code
Spacing order number	Unit Acreage
Unit configuration	
<input type="checkbox"/> Remove from surface bond	
Signed surface use agreement attached	
<input type="checkbox"/> CHANGE OF OPERATOR (prior to drilling):	
Effective Date:	
Plugging Bond: <input type="checkbox"/> Blanket <input type="checkbox"/> Individual	
<input type="checkbox"/> CHANGE WELL NAME	
From:	NUMBER
To:	
Effective Date:	
<input type="checkbox"/> ABANDONED LOCATION:	
Was location ever built? <input type="checkbox"/> Yes <input type="checkbox"/> No	
Is site ready for inspection? <input type="checkbox"/> Yes <input type="checkbox"/> No	
Date Ready for Inspection:	
<input type="checkbox"/> NOTICE OF CONTINUED SHUT IN STATUS	
Date well shut in or temporarily abandoned:	
Has Production Equipment been removed from site? <input type="checkbox"/> Yes <input type="checkbox"/> No	
MIT required if shut in longer than two years. Date of last MIT	
<input type="checkbox"/> SPUD DATE:	
<input type="checkbox"/> REQUEST FOR CONFIDENTIAL STATUS (6 mos from date casing set)	
<input type="checkbox"/> SUBSEQUENT REPORT OF STAGE, SQUEEZE OR REMEDIAL CEMENT WORK	
*submit cbl and cement job summaries	
Method used	Cementing tool setting/perf depth
Cement volume	Cement top
Cement bottom	Date
<input type="checkbox"/> RECLAMATION: Attach technical page describing final reclamation procedures per Rule 1004.	
Final reclamation will commence on approximately	
<input type="checkbox"/> Final reclamation is completed and site is ready for inspection.	

Technical Engineering/Environmental Notice

<input type="checkbox"/> Notice of Intent		<input type="checkbox"/> Report of Work Done	
Approximate Start Date:		Date Work Completed:	
Details of work must be described in full on Technical Information Page (Page 2 must be submitted.)			
<input type="checkbox"/> Intent to Recomplete (submit form 2)	<input type="checkbox"/> Request to Vent or Flare	<input type="checkbox"/> E&P Waste Disposal	
<input type="checkbox"/> Change Drilling Plans	<input type="checkbox"/> Repair Well	<input type="checkbox"/> Beneficial Reuse of E&P Waste	
<input type="checkbox"/> Gross Interval Changed?	<input type="checkbox"/> Rule 502 variance requested	<input type="checkbox"/> Status Update/Change of Remediation Plans	
<input type="checkbox"/> Casing/Cementing Program Change	<input checked="" type="checkbox"/> Other: Background	for Spills and Releases	

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct and complete.

Signed: Karolina Blaney

Date: 3/27/2012

Email: Karolina.Blaney@WPXEnergy.com

Print Name: Karolina Blaney

Title: Environmental Specialist

COGCC Approved:

Title: FOR

Date: 04/09/2012

CONDITIONS OF APPROVAL, IF ANY:

Chris Canfield
EPS NW Region

TECHNICAL INFORMATION PAGE



FOR OGCC USE ONLY

1. OGCC Operator Number: _____ API Number: _____

2. Name of Operator: _____ OGCC Facility ID # _____

3. Well/Facility Name: _____ Well/Facility Number: _____

4. Location (QtrQtr, Sec, Twp, Rng, Meridian): _____

This form is to be completed whenever a Sundry Notice is submitted requiring detailed report of work to be performed or completed. This form shall be transmitted within 30 days of work completed as a "subsequent" report and must accompany Form 4, page 1.

5.

DESCRIBE PROPOSED OR COMPLETED OPERATIONS



Legend

- Sample Location
- Existing Road
- Existing Pad
Limit of Disturbance

MV 23-27
Arsenic Background Sample Location Map
T6S R96W, Section 27

March 26, 2012



REPORT OF ANALYSIS

Karolina Blaney
WPX Energy
1058 County Road 215
Parachute, CO 81635

March 27, 2012

Date Received : March 01, 2012
Description : MV 23-27 Cuttings

Sample ID : MV 23-27

Collected By :
Collection Date : 02/28/12 08:50

ESC Sample # : L562839-01

Site ID : MV 23-27

Project # :

Parameter	Result	Det. Limit	Units	Method	Date	Dil.
Chromium, Hexavalent	BDL	2.0	mg/kg	3060A/7196A	03/05/12	1
Chromium, Trivalent	15.	2.0	mg/kg	Calc.	03/02/12	1
ORP	-79.		mV	2580	03/06/12	1
pH	12.		su	9045D	03/02/12	1
Sodium Adsorption Ratio	57.			Calc.	03/08/12	1
Specific Conductance	4600		umhos/cm	9050AMod	03/04/12	1
Mercury	0.025	0.020	mg/kg	7471	03/02/12	1
Arsenic	2.1	1.0	mg/kg	6010B	03/02/12	1
Barium	5100	0.50	mg/kg	6010B	03/02/12	2
Cadmium	BDL	0.25	mg/kg	6010B	03/02/12	1
Chromium	15.	0.50	mg/kg	6010B	03/02/12	1
Copper	21.	1.0	mg/kg	6010B	03/02/12	1
Lead	13.	0.25	mg/kg	6010B	03/02/12	1
Nickel	11.	1.0	mg/kg	6010B	03/02/12	1
Selenium	2.0	1.0	mg/kg	6010B	03/02/12	1
Silver	BDL	0.50	mg/kg	6010B	03/02/12	1
Zinc	46.	1.5	mg/kg	6010B	03/02/12	1

BDL - Below Detection Limit

Det. Limit - Practical Quantitation Limit (PQL)

Note:

The reported analytical results relate only to the sample submitted.

This report shall not be reproduced, except in full, without the written approval from ESC.

Reported: 03/08/12 15:41 Revised: 03/27/12 14:15
L562839-01 (PH) - 12@21.0c



12065 Lebanon Rd.
Mt. Juliet, TN 37122
(615) 758-5858
1-800-767-5859
Fax (615) 758-5859

Tax I.D. 62-0814289

Est. 1970

REPORT OF ANALYSIS

Karolina Blaney
Williams
1058 County Road 215
Parachute, CO 81635

October 26, 2011

Date Received : October 19, 2011
Description : MV 23-27

Sample ID : MV 23-27-B-1

Collected By :
Collection Date : 10/13/11 09:35

ESC Sample # : L542352-02

Site ID : MV 23-27

Project # :

Parameter	Result	Det. Limit	Units	Method	Date	Dil.
Arsenic	4.3	1.0	mg/kg	6010B	10/23/11	1

BDL - Below Detection Limit

Det. Limit - Practical Quantitation Limit(PQL)

Note:

The reported analytical results relate only to the sample submitted.

This report shall not be reproduced, except in full, without the written approval from ESC.

.

Reported: 10/26/11 15:10 Printed: 10/26/11 16:18



12065 Lebanon Rd.
Mt. Juliet, TN 37122
(615) 758-5858
1-800-767-5859
Fax (615) 758-5859

Tax I.D. 62-0814289

Est. 1970

REPORT OF ANALYSIS

Karolina Blaney
Williams
1058 County Road 215
Parachute, CO 81635

October 26, 2011

Date Received : October 19, 2011
Description : MV 23-27

Sample ID : MV 23-27-B-2

Collected By :
Collection Date : 10/13/11 09:40

ESC Sample # : L542352-03

Site ID : MV 23-27

Project # :

Parameter	Result	Det. Limit	Units	Method	Date	Dil.
Arsenic	4.5	1.0	mg/kg	6010B	10/23/11	1

BDL - Below Detection Limit

Det. Limit - Practical Quantitation Limit(PQL)

Note:

The reported analytical results relate only to the sample submitted.

This report shall not be reproduced, except in full, without the written approval from ESC.

.

Reported: 10/26/11 15:10 Printed: 10/26/11 16:18



12065 Lebanon Rd.
Mt. Juliet, TN 37122
(615) 758-5858
1-800-767-5859
Fax (615) 758-5859

Tax I.D. 62-0814289

Est. 1970

REPORT OF ANALYSIS

Karolina Blaney
Williams
1058 County Road 215
Parachute, CO 81635

October 26, 2011

Date Received : October 19, 2011
Description : MV 23-27

Sample ID : MV 23-27-B-3

Collected By :
Collection Date : 10/13/11 09:45

ESC Sample # : L542352-04

Site ID : MV 23-27

Project # :

Parameter	Result	Det. Limit	Units	Method	Date	Dil.
Arsenic	8.4	1.0	mg/kg	6010B	10/23/11	1

BDL - Below Detection Limit

Det. Limit - Practical Quantitation Limit(PQL)

Note:

The reported analytical results relate only to the sample submitted.

This report shall not be reproduced, except in full, without the written approval from ESC.

.

Reported: 10/26/11 15:10 Printed: 10/26/11 16:18



12065 Lebanon Rd.
Mt. Juliet, TN 37122
(615) 758-5858
1-800-767-5859
Fax (615) 758-5859

Tax I.D. 62-0814289

Est. 1970

REPORT OF ANALYSIS

Karolina Blaney
Williams
1058 County Road 215
Parachute, CO 81635

October 26, 2011

Date Received : October 19, 2011
Description : MV 23-27

Sample ID : MV 23-27-B-4

Collected By :
Collection Date : 10/13/11 09:50

ESC Sample # : L542352-05

Site ID : MV 23-27

Project # :

Parameter	Result	Det. Limit	Units	Method	Date	Dil.
Arsenic	5.8	1.0	mg/kg	6010B	10/23/11	1

BDL - Below Detection Limit

Det. Limit - Practical Quantitation Limit(PQL)

Note:

The reported analytical results relate only to the sample submitted.

This report shall not be reproduced, except in full, without the written approval from ESC.

Reported: 10/26/11 15:10 Printed: 10/26/11 16:18



12065 Lebanon Rd.
Mt. Juliet, TN 37122
(615) 758-5858
1-800-767-5859
Fax (615) 758-5859

Tax I.D. 62-0814289

Est. 1970

REPORT OF ANALYSIS

Karolina Blaney
Williams
1058 County Road 215
Parachute, CO 81635

October 26, 2011

Date Received : October 19, 2011
Description : MV 23-27

Sample ID : MV 23-27-B-5

Collected By :
Collection Date : 10/13/11 09:55

ESC Sample # : L542352-06

Site ID : MV 23-27

Project # :

Parameter	Result	Det. Limit	Units	Method	Date	Dil.
Arsenic	3.9	1.0	mg/kg	6010B	10/23/11	1

BDL - Below Detection Limit

Det. Limit - Practical Quantitation Limit(PQL)

Note:

The reported analytical results relate only to the sample submitted.

This report shall not be reproduced, except in full, without the written approval from ESC.

.

Reported: 10/26/11 15:10 Printed: 10/26/11 16:18



12065 Lebanon Rd.
Mt. Juliet, TN 37122
(615) 758-5858
1-800-767-5859
Fax (615) 758-5859

Tax I.D. 62-0814289

Est. 1970

REPORT OF ANALYSIS

Karolina Blaney
WPX Energy
1058 County Road 215
Parachute, CO 81635

March 27, 2012

Date Received : March 01, 2012
Description : MV 23-27 Cuttings
Sample ID : MV 23-27-B-6
Collected By :
Collection Date : 02/28/12 09:10

ESC Sample # : L562839-03

Site ID : MV 23-27

Project # :

Parameter	Result	Det. Limit	Units	Method	Date	Dil.
Arsenic	3.8	1.0	mg/kg	6010B	03/02/12	1

BDL - Below Detection Limit

Det. Limit - Practical Quantitation Limit(PQL)

Note:

The reported analytical results relate only to the sample submitted.

This report shall not be reproduced, except in full, without the written approval from ESC.

.

Reported: 03/08/12 15:41 Revised: 03/27/12 14:15



12065 Lebanon Rd.
Mt. Juliet, TN 37122
(615) 758-5858
1-800-767-5859
Fax (615) 758-5859

Tax I.D. 62-0814289

Est. 1970

REPORT OF ANALYSIS

Karolina Blaney
WPX Energy
1058 County Road 215
Parachute, CO 81635

March 27, 2012

Date Received : March 01, 2012
Description : MV 23-27 Cuttings
Sample ID : MV 23-27-B-7
Collected By :
Collection Date : 02/28/12 09:29

ESC Sample # : L562839-04

Site ID : MV 23-27

Project # :

Parameter	Result	Det. Limit	Units	Method	Date	Dil.
Arsenic	BDL	1.0	mg/kg	6010B	03/02/12	1

BDL - Below Detection Limit

Det. Limit - Practical Quantitation Limit(PQL)

Note:

The reported analytical results relate only to the sample submitted.

This report shall not be reproduced, except in full, without the written approval from ESC.

.

Reported: 03/08/12 15:41 Revised: 03/27/12 14:15



12065 Lebanon Rd.
Mt. Juliet, TN 37122
(615) 758-5858
1-800-767-5859
Fax (615) 758-5859

Tax I.D. 62-0814289

Est. 1970

REPORT OF ANALYSIS

Karolina Blaney
WPX Energy
1058 County Road 215
Parachute, CO 81635

March 27, 2012

Date Received : March 01, 2012
Description : MV 23-27 Cuttings
Sample ID : MV 23-27-B-8
Collected By :
Collection Date : 02/28/12 09:33

ESC Sample # : L562839-05

Site ID : MV 23-27

Project # :

Parameter	Result	Det. Limit	Units	Method	Date	Dil.
Arsenic	1.2	1.0	mg/kg	6010B	03/02/12	1

BDL - Below Detection Limit

Det. Limit - Practical Quantitation Limit(PQL)

Note:

The reported analytical results relate only to the sample submitted.

This report shall not be reproduced, except in full, without the written approval from ESC.

.

Reported: 03/08/12 15:41 Revised: 03/27/12 14:15



12065 Lebanon Rd.
Mt. Juliet, TN 37122
(615) 758-5858
1-800-767-5859
Fax (615) 758-5859

Tax I.D. 62-0814289

Est. 1970

REPORT OF ANALYSIS

Karolina Blaney
WPX Energy
1058 County Road 215
Parachute, CO 81635

March 27, 2012

Date Received : March 01, 2012
Description : MV 23-27 Cuttings
Sample ID : MV 23-27-B-9
Collected By :
Collection Date : 02/28/12 09:40

ESC Sample # : L562839-06

Site ID : MV 23-27

Project # :

Parameter	Result	Det. Limit	Units	Method	Date	Dil.
Arsenic	2.8	1.0	mg/kg	6010B	03/02/12	1

BDL - Below Detection Limit

Det. Limit - Practical Quantitation Limit(PQL)

Note:

The reported analytical results relate only to the sample submitted.

This report shall not be reproduced, except in full, without the written approval from ESC.

.

Reported: 03/08/12 15:41 Revised: 03/27/12 14:15



12065 Lebanon Rd.
Mt. Juliet, TN 37122
(615) 758-5858
1-800-767-5859
Fax (615) 758-5859

Tax I.D. 62-0814289

Est. 1970

REPORT OF ANALYSIS

Karolina Blaney
WPX Energy
1058 County Road 215
Parachute, CO 81635

March 27, 2012

Date Received : March 01, 2012
Description : MV 23-27 Cuttings
Sample ID : MV 23-27-B-10
Collected By :
Collection Date : 02/28/12 09:43

ESC Sample # : L562839-07

Site ID : MV 23-27

Project # :

Parameter	Result	Det. Limit	Units	Method	Date	Dil.
Arsenic	12.	1.0	mg/kg	6010B	03/02/12	1

BDL - Below Detection Limit

Det. Limit - Practical Quantitation Limit(PQL)

Note:

The reported analytical results relate only to the sample submitted.

This report shall not be reproduced, except in full, without the written approval from ESC.

.

Reported: 03/08/12 15:41 Revised: 03/27/12 14:15