

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

04/03/2012

Document Number:

663800238

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name:
	<u>299284</u>	<u>335978</u>		<u>LONGWORTH, MIKE</u>

Operator Information:OGCC Operator Number: 100185 Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVERState: COZip: 80202-**Contact Information:**

Contact Name	Phone	Email	Comment
Friesen, Kathy	970-285-2665	Kathy.Friesen@EnCana.com	

Compliance Summary:QtrQtr: NWNW Sec: 27 Twp: 5S Range: 95W**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
299283	WELL	PR	05/19/2010	LO	045-17639	N. PARACHUTE EF09C-21 D27A 5	<input checked="" type="checkbox"/>
299284	WELL	PR	05/28/2010	LO	045-17640	N. Parachute EF01D-28 D27A 5	<input checked="" type="checkbox"/>
299285	WELL	PR	04/21/2010	OW	045-17641	N. Parachute EF12D-22 D27A 5	<input checked="" type="checkbox"/>
299286	WELL	PR	03/23/2010	LO	045-17642	N. PARACHUTE EF13B-22 D27A 5	<input checked="" type="checkbox"/>
299287	WELL	PR	05/22/2010	LO	045-17643	N. Parachute EF09A-21 D27A 5	<input checked="" type="checkbox"/>
299288	WELL	PR	10/27/2008	LO	045-17644	N. Parachute EF11C-22 D27A 5	<input checked="" type="checkbox"/>
299289	WELL	PR	03/07/2010	OW	045-17645	N. Parachute EF11A-22 D27A 5	<input checked="" type="checkbox"/>
299290	WELL	PR	03/28/2010	LO	045-17646	N. PARACHUTE EF06A-22 D27A 5	<input checked="" type="checkbox"/>
299291	WELL	PR	04/19/2010	LO	045-17647	N. Parachute EF05C-22 D27A 5	<input checked="" type="checkbox"/>
299292	WELL	PR	04/29/2010	OW	045-17648	N. Parachute EF05A-22 D27A 5	<input checked="" type="checkbox"/>
299293	WELL	PR	03/08/2010	LO	045-17649	N. Parachute EF14A-22 D27A 5	<input checked="" type="checkbox"/>
299294	WELL	PR	03/21/2010	OW	045-17650	N. Parachute EF06C-22 D27A 5	<input checked="" type="checkbox"/>
299295	WELL	PR	05/10/2010	LO	045-17651	N. Parachute EF09D-21 D27A 5	<input checked="" type="checkbox"/>
299299	WELL	PR	03/31/2010	OW	045-17652	N. PARACHUTE EF13C-22 D27A 5	<input checked="" type="checkbox"/>
299386	WELL	PR	04/18/2010	GW	045-17662	N. PARACHUTE EF12A-22 D27A 5	<input checked="" type="checkbox"/>

Inspector Name: LONGWORTH, MIKE

335978	LOCATION	AC	04/14/2009		-	N. PARACHUTE-65S95W 27NWNW	<input type="checkbox"/>
413296	WELL	PR	03/31/2010	OW	045-18771	N. PARACHUTE EF04A-27 D27A 5	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Lease Road:**

Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Main	Satisfactory			

Signs/Marker:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory			
CONTAINERS	Satisfactory			
TANK LABELS/PLACARDS	Satisfactory			
BATTERY	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory

Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
DEBRIS	Unsatisfactory	pallet boards with nails, tread protectors,	Pick up location	04/18/2012

Spills:

Type	Area	Volume	Corrective action	CA Date
Lube Oil	WELLHEAD	<= 5 bbls	clean up and remediate spills around wells	04/18/2012

☒ Multiple Spills and Releases?**Equipment:**

Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Gas Meter Run	4	Satisfactory			
Plunger Lift	6	Satisfactory			
Plunger Lift	10	Satisfactory			

Inspector Name: LONGWORTH, MIKE

Tanks/Berms: <input type="checkbox"/> New Tank Tank ID: _____				
Contents	#	Capacity	Type	SE GPS
CONDENSATE	1	<100 BBLS	STEEL AST	,
S/U/V:	Satisfactory		Comment: lid open on tank	
Corrective Action:				Corrective Date:
<u>Paint</u>				
Condition				
Other (Content) _____				
Other (Capacity) _____				
Other (Type) _____				
<u>Berms</u>				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Corrective Action				Corrective Date
Comment				
<u>Venting:</u>				
Yes/No		Comment		
<u>Flaring:</u>				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 335978

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Wildlife BMPs:****Stormwater:****Comment:** _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Well**

Facility ID: 299283 API Number: 045-17639 Status: PR Insp. Status: PR

Facility ID: 299284 API Number: 045-17640 Status: PR Insp. Status: PR

Facility ID: 299285 API Number: 045-17641 Status: PR Insp. Status: PR

Facility ID: 299286 API Number: 045-17642 Status: PR Insp. Status: PR

Facility ID: 299287 API Number: 045-17643 Status: PR Insp. Status: PR

Workover

Comment: Swabing well with Rocky Mountain Wireline Service

Facility ID: 299288 API Number: 045-17644 Status: PR Insp. Status: PR

Facility ID: 299289 API Number: 045-17645 Status: PR Insp. Status: PR

Facility ID: 299290 API Number: 045-17646 Status: PR Insp. Status: PR

Inspector Name: LONGWORTH, MIKE

Facility ID:	299291	API Number:	045-17647	Status:	PR	Insp. Status:	PR
Facility ID:	299292	API Number:	045-17648	Status:	PR	Insp. Status:	PR
Facility ID:	299293	API Number:	045-17649	Status:	PR	Insp. Status:	PR
Facility ID:	299294	API Number:	045-17650	Status:	PR	Insp. Status:	PR
Facility ID:	299295	API Number:	045-17651	Status:	PR	Insp. Status:	PR
Facility ID:	299299	API Number:	045-17652	Status:	PR	Insp. Status:	PR
Facility ID:	299386	API Number:	045-17662	Status:	PR	Insp. Status:	PR
Facility ID:	413296	API Number:	045-18771	Status:	PR	Insp. Status:	PR

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Inspector Name: LONGWORTH, MIKE

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass			MHSP	Pass	

Inspector Name: LONGWORTH, MIKE

S/U/V: _____ Corrective Date: _____

Comment: _____

CA: _____