

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
04/03/2012

Document Number:
663800247

Overall Inspection:
Satisfactory

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name: <u>LONGWORTH, MIKE</u>
	<u>301038</u>	<u>335970</u>		

Operator Information:

OGCC Operator Number: 100185 Name of Operator: ENCANA OIL & GAS (USA) INC
 Address: 370 17TH ST STE 1700
 City: DENVER State: CO Zip: 80202-

Contact Information:

Contact Name	Phone	Email	Comment
Friesen, Kathy	970-285-2665	Kathy.Friesen@EnCana.com	

Compliance Summary:

QtrQtr: NENW Sec: 28 Twp: 5S Range: 95W

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
301038	WELL	PR	07/22/2010	LO	045-18075	N. PARACHUTE EF11A-28C28A595	<input checked="" type="checkbox"/>
301039	WELL	PR	07/28/2010	LO	045-18076	N. PARACHUTE EF03A-33C28A 5	<input checked="" type="checkbox"/>
301040	WELL	PR	11/13/2010	LO	045-18077	N. PARACHUTE EF05A-28C28A 5	<input checked="" type="checkbox"/>
301041	WELL	PR	08/18/2010	LO	045-18078	N. PARACHUTE EF05C-28C28A 5	<input checked="" type="checkbox"/>
301042	WELL	PR	07/26/2010	LO	045-18079	N. PARACHUTE EF11D-28C28A 5	<input checked="" type="checkbox"/>
301043	WELL	PR	07/01/2010	LO	045-18080	N. PARACHUTE EF06D-28C28A 5	<input checked="" type="checkbox"/>
301044	WELL	PR	06/30/2010	LO	045-18081	N. PARACHUTE EF06A-28C28A 5	<input checked="" type="checkbox"/>
301045	WELL	PR	06/27/2010	LO	045-18082	N. PARACHUTE EF14D-28C28A595	<input checked="" type="checkbox"/>
301046	WELL	PR	07/27/2010	LO	045-18083	N. PARACHUTE EF14B-28C28A595	<input checked="" type="checkbox"/>
301047	WELL	PR	07/12/2010	LO	045-18084	N. PARACHUTE EF12B-28C28A595	<input checked="" type="checkbox"/>
301048	WELL	PR	08/18/2010	LO	045-18085	N. PARACHUTE EF12C-28C28A595	<input checked="" type="checkbox"/>
301049	WELL	PR	06/27/2010	LO	045-18086	N. PARACHUTE EF03D-28C28A 5	<input checked="" type="checkbox"/>
335970	LOCATION	AC	04/14/2009		-	N. PARACHUTE-65S95W 28NENW	<input type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:				
Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Main	Satisfactory			

Signs/Marker:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory			
BATTERY	Satisfactory			
TANK LABELS/PLACARDS	Satisfactory			
CONTAINERS	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
DEBRIS	Unsatisfactory	trash, parts, blocks, netting and liner materials, tumble weeds	pick up location	04/18/2012

Spills:				
Type	Area	Volume	Corrective action	CA Date
Lube Oil	WELLHEAD	<= 5 bbls	clean up and remediate well oil stains	04/18/2012

Multiple Spills and Releases?

Equipment:					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Plunger Lift	10	Satisfactory			
Plunger Lift	2	Satisfactory			

Tanks/Berms:		<input type="checkbox"/> New Tank	Tank ID: _____		
Contents	#	Capacity	Type	SE GPS	
CONDENSATE	1	<100 BBLs	STEEL AST	,	
S/U/V:	Satisfactory	Comment:			
Corrective Action:				Corrective Date:	
Paint					
Condition	Inadequate				
Other (Content)	_____				
Other (Capacity)	_____				
Other (Type)	_____				
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Inadequate	Walls Sufficient	Base Sufficient	Adequate	
Corrective Action	bluid up berm to hold 110% of tank volume			Corrective Date	04/18/2012
Comment					
Venting:					
Yes/No	Comment				
Flaring:					
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date	

Predrill

Location ID: 335970

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____
 Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Wildlife BMPs:

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Well

Facility ID: 301038 API Number: 045-18075 Status: PR Insp. Status: PR

Facility ID: 301039 API Number: 045-18076 Status: PR Insp. Status: PR

Facility ID: 301040 API Number: 045-18077 Status: PR Insp. Status: PR

Facility ID: 301041 API Number: 045-18078 Status: PR Insp. Status: PR

Facility ID: 301042 API Number: 045-18079 Status: PR Insp. Status: PR

Facility ID: 301043 API Number: 045-18080 Status: PR Insp. Status: PR

Facility ID: 301044 API Number: 045-18081 Status: PR Insp. Status: PR

Facility ID: 301045 API Number: 045-18082 Status: PR Insp. Status: PR

Facility ID: 301046 API Number: 045-18083 Status: PR Insp. Status: PR

Facility ID: 301047	API Number: 045-18084	Status: PR	Insp. Status: PR
Facility ID: 301048	API Number: 045-18085	Status: PR	Insp. Status: PR
Facility ID: 301049	API Number: 045-18086	Status: PR	Insp. Status: PR

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment:

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location:

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment:

1003a. Debris removed? _____ CM _____ CA _____ CA Date _____

Waste Material Onsite? _____ CM _____ CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____ CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____ CA _____ CA Date _____

Guy line anchors removed? _____ CM _____ CA _____ CA Date _____

Guy line anchors marked? _____ CM _____ CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation _____

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: _____ Corrective Date: _____

Comment: _____

CA: _____