

**FORM  
INSP**Rev  
05/11

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

04/03/2012

Document Number:

663800248

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name:
	<u>282071</u>	<u>335822</u>		<u>LONGWORTH, MIKE</u>

**Operator Information:**OGCC Operator Number: 100185 Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVERState: COZip: 80202-**Contact Information:**

Contact Name	Phone	Email	Comment
Friesen, Kathy	970-285-2665	Kathy.Friesen@EnCana.com	

**Compliance Summary:**QtrQtr: NWNW Sec: 28 Twp: 5S Range: 95W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
04/07/2009	200209899	PR	PR	S			N

**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
281942	WELL	PR	04/05/2007	LO	045-11587	N. PARACHUTE EF04D D28 595	<input checked="" type="checkbox"/>
281943	WELL	PR	04/05/2007	LO	045-11588	N. PARACHUTE EF05B D28 595	<input checked="" type="checkbox"/>
282068	WELL	PR	02/01/2011	LO	045-11626	N. PARACHUTE EF14B D28 595	<input checked="" type="checkbox"/>
282069	WELL	PR	04/05/2007	LO	045-11625	N. PARACHUTE EF12D D28 595	<input checked="" type="checkbox"/>
282070	WELL	PR	04/05/2007	LO	045-11624	N. PARACHUTE EF13B D28 595	<input checked="" type="checkbox"/>
282071	WELL	PR	04/05/2007	LO	045-11623	N. PARACHUTE EF04B D28 595	<input checked="" type="checkbox"/>
282085	WELL	PR	04/05/2007	LO	045-11634	N. PARACHUTE EF13D D28 595	<input checked="" type="checkbox"/>
285097	WELL	PR	04/05/2007	LO	045-12377	N. PARACHUTE EF05D D28 595	<input checked="" type="checkbox"/>
297249	WELL	AL	07/07/2011	LO	045-16352	N. PARACHUTE EF04B-28 D28 59	<input type="checkbox"/>
297250	WELL	AL	07/07/2011	LO	045-16353	N. PARACHUTE EF03C-28 D28 59	<input type="checkbox"/>
297251	WELL	AL		LO	045-16354	N. PARACHUTE EF04C-28 D28 59	<input type="checkbox"/>
297252	WELL	AL	07/07/2011	LO	045-16355	N. PARACHUTE EF12C-21 D28 59	<input type="checkbox"/>

Inspector Name: LONGWORTH, MIKE

297255	WELL	AL	07/07/2011	LO	045-16358	N. PARACHUTE EF13A-21 D28 59	
297257	WELL	PR	04/01/2009	LO	045-16359	N. PARACHUTE EF13C-21 D28 59	
297258	WELL	AL	07/07/2011	LO	045-16360	N. PARACHUTE EF14A-21 D28 59	
297259	WELL	AL	07/07/2011	LO	045-16361	N. PARACHUTE EF14C-21 D28 59	
297260	WELL	AL		LO	045-16362	N. PARACHUTE EF08C-20 D28 59	
297261	WELL	AL	07/07/2011	LO	045-16363	N. PARACHUTE EF09B-20 D28 59	
297262	WELL	AL		LO	045-16364	N. PARACHUTE EF09C-20 D28 59	
297263	WELL	AL		LO	045-16365	N. PARACHUTE EF08D-20 D28 59	
297264	WELL	AL		LO	045-16366	N. PARACHUTE EF12A-21 D28 59	
297265	WELL	AL		LO	045-16367	N. PARACHUTE EF16B-20 D28 59	
297789	WELL	AL		LO	045-16963	N. PARACHUTE EF11D-21 D28 59	
297791	WELL	AL		LO	045-16965	N. PARACHUTE EF11B-21 D28 59	
335822	LOCATION	AC	04/14/2009		-	N. PARACHUTE-65S95W 28NWNW	
425763	PIT		10/05/2011		-	EF D28 595	

**Equipment:**Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location****Lease Road:**

Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Main	Satisfactory			

**Signs/Marker:**

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory			
BATTERY	Satisfactory			
CONTAINERS	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

<b>Good Housekeeping:</b>				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
DEBRIS	Unsatisfactory		pick up location	04/18/2012

<b>Spills:</b>				
Type	Area	Volume	Corrective action	CA Date
Lube Oil	WELLHEAD	<= 5 bbls	clean up and remediate stain at well	04/18/2012

☐ Multiple Spills and Releases?

<b>Equipment:</b>					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Gas Meter Run	4	Satisfactory			
Plunger Lift	8	Satisfactory			

<b><u>Venting:</u></b>		
Yes/No	Comment	

<b>Flaring:</b>				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

**Predrill**

Location ID: 335822

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_

Pads: \_\_\_\_\_

Soil Stockpile: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:****Wildlife BMPs:****Stormwater:****Comment:** \_\_\_\_\_**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Well**

Facility ID: 281942 API Number: 045-11587 Status: PR Insp. Status: PR

Facility ID: 281943 API Number: 045-11588 Status: PR Insp. Status: PR

Facility ID: 282068 API Number: 045-11626 Status: PR Insp. Status: PR

Facility ID: 282069 API Number: 045-11625 Status: PR Insp. Status: PR

Facility ID: 282070 API Number: 045-11624 Status: PR Insp. Status: PR

Facility ID: 282071 API Number: 045-11623 Status: PR Insp. Status: PR

Facility ID: 282085 API Number: 045-11634 Status: PR Insp. Status: PR

Facility ID: 285097 API Number: 045-12377 Status: PR Insp. Status: PR

**Environmental****Spills/Releases:**

Inspector Name: LONGWORTH, MIKE

Type of Spill: _____	Description: _____	Estimated Spill Volume: _____
Comment: _____		
Corrective Action: _____		Date: _____
Reportable: _____	GPS: Lat _____	Long _____
Proximity to Surface Water: _____	Depth to Ground Water: _____	

**Water Well:**

DWR Receipt Num: _____	Owner Name: _____	GPS : _____	Lat _____	Long _____
------------------------	-------------------	-------------	-----------	------------

**Field Parameters:**

Sample Location: \_\_\_\_\_

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Debris removed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Waste Material Onsite? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

RESTORATION AND REVEGETATION

Cropland

Inspector Name: LONGWORTH, MIKE

Top soil replaced \_\_\_\_\_

Recontoured \_\_\_\_\_

Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_

Recontoured \_\_\_\_\_

80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation \_\_\_\_\_

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_

Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_

Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_

No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_

Contoured \_\_\_\_\_

Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_

Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_

Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_

Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_

Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: \_\_\_\_\_ Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_