

Inspector Name: Baroumand, Soraya

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



| | | | |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Inspection Date:

03/09/2012

Document Number:

668500018

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

| | | | | |
|---------------------|-------------|--------|---------------|-----------------------------------|
| Location Identifier | Facility ID | Loc ID | Tracking Type | Inspector Name: Baroumand, Soraya |
| | 272088 | 334869 | | |

Operator Information:OGCC Operator Number: 96850 Name of Operator: WPX ENERGY ROCKY MOUNTAIN LLCAddress: 1001 17TH STREET - SUITE #1200City: DENVER State: CO Zip: 80202**Contact Information:****Compliance Summary:**QtrQtr: SESW Sec: 2 Twp: 7S Range: 96W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Unsatisfactory | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|------------------------------|----------|----------------|-----------------|
| 05/22/2008 | 200190831 | PR | PR | S | | | N |
| 01/24/2007 | 200107160 | PR | PR | U | I | F | Y |

Inspector Comment:**Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | |
|-------------|----------|--------|-------------|------------|-----------|------------------------|-------------------------------------|
| 211300 | WELL | PR | 11/10/1998 | | 045-07059 | UNOCAL GM 24-2 | <input checked="" type="checkbox"/> |
| 272034 | WELL | PR | 02/11/2005 | GW | 045-10010 | AMERICAN SODA GM 424-2 | <input checked="" type="checkbox"/> |
| 272088 | WELL | PR | 02/18/2005 | GW | 045-10020 | AMERICAN SODA GM 524-2 | <input checked="" type="checkbox"/> |
| 276177 | LEASE | PR | 02/14/2005 | | - | AMERICAN SODA GM 424-2 | <input type="checkbox"/> |
| 276537 | LEASE | PR | 03/02/2004 | | - | AMERICAN SODA GM 524-2 | <input type="checkbox"/> |
| 334869 | LOCATION | AC | 04/14/2009 | | - | UNOCAL-67S96W 2SESW | <input type="checkbox"/> |

Equipment:Location Inventory

| | | | |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

LocationEmergency Contact Number: (S/U/V) Satisfactory

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Inspector Name: Baroumand, Soraya

| Type | Area | Volume | Corrective action | CA Date |
|------|------|--------|-------------------|---------|
|------|------|--------|-------------------|---------|

☐ Multiple Spills and Releases?

| Fencing/: | | | | |
|------------------|-----------------------------|-------------|-------------------|---------|
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| WELLHEAD | Satisfactory | welded wire | | |
| TANK BATTERY | Satisfactory | welded wire | | |
| SEPARATOR | Satisfactory | welded wire | | |

| Equipment: | | | | | |
|----------------------|---|-----------------------------|-----------------------------|-------------------|---------|
| Type | # | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| Plunger Lift | 3 | Satisfactory | | | |
| Gas Meter Run | 1 | Satisfactory | | | |
| Horizontal Separator | 3 | Satisfactory | 1 dual-unit & 1 single unit | | |
| Bird Protectors | | Satisfactory | | | |

| | | | | | | |
|----------------------------|--------------|-----------------------------------|----------------|-----------|-----------------------|--|
| <u>Tanks/Berms:</u> | | <input type="checkbox"/> New Tank | Tank ID: _____ | | | |
| Contents | | # | Capacity | Type | SE GPS | |
| CONDENSATE | | 1 | <100 BBLS | STEEL AST | 39.461070,-108.080668 | |
| S/U/V: | Satisfactory | | Comment: | | | |
| Corrective Action: | | | | | Corrective Date: | |

| Paint | |
|------------------|----------|
| Condition | Adequate |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

| Berms | | | | |
|-------------------|----------|---------------------|---------------------|-----------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Corrective Action | | | | Corrective Date |
| Comment | | | | |

| Venting: | |
|-----------------|---------|
| Yes/No | Comment |
| | |

| Flaring: | | | | |
|-----------------|-----------------------------|---------|-------------------|---------|
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| | | | | |

Predrill

Location ID: 334869

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Wildlife BMPs:****Stormwater:****Comment:****Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Well**

Facility ID: 211300 API Number: 045-07059 Status: PR Insp. Status: PR

Facility ID: 272034 API Number: 045-10010 Status: PR Insp. Status: PR

Facility ID: 272088 API Number: 045-10020 Status: PR Insp. Status: PR

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? Pass CM _____
 CA _____ CA Date _____
 Waste Material Onsite? Pass CM _____
 CA _____ CA Date _____
 Unused or unneeded equipment onsite? Pass CM _____
 CA _____ CA Date _____
 Pit, cellars, rat holes and other bores closed? Pass CM _____
 CA _____ CA Date _____
 Guy line anchors removed? Pass CM _____
 CA _____ CA Date _____
 Guy line anchors marked? _____ CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? PassProduction areas have been stabilized? Pass Segregated soils have been replaced? Pass**RESTORATION AND REVEGETATION**Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-CroplandTop soil replaced Pass Recontoured Pass 80% Revegetation Pass

1003 f. Weeds Noxious weeds? _____ P _____

Comment: Location adequately minimized. Cut and fill slopes recontoured, stable, and well vegetated.

Overall Interim Reclamation Pass**Final Reclamation/ Abandoned Location:**

Inspector Name: Baroumand, Soraya

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation

| Storm Water: | | | | | | |
|---------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|-----------------------------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Other | Pass | | | | | mature vegetation on slopes |
| Gradient Terraces | Pass | | | | | vegetated diversion ditches |
| Drains | Pass | | | | | |

S/U/V: Satisfactory _____ Corrective Date: _____

Comment: _____

CA: _____