


| | | | |
|-------------------------------|--|--|----------------------|
| FORM INSP Rev 05/11 | State of Colorado Oil and Gas Conservation Commission 1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109 |  | DE ET OE ES |
|-------------------------------|--|--|----------------------|

Inspection Date:
03/14/2012

Document Number:
668000066

Overall Inspection:
Satisfactory

FIELD INSPECTION FORM

| | | | | |
|---------------------|---------------|---------------|---------------|------------------------------------|
| Location Identifier | Facility ID | Loc ID | Tracking Type | Inspector Name: <u>DURAN, JOHN</u> |
| | <u>262544</u> | <u>312069</u> | | |

Operator Information:

OGCC Operator Number: 100264 Name of Operator: XTO ENERGY INC

Address: 382 CR 3100

City: AZTEC State: NM Zip: 87410

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|---------------------------|-------------------------------|-----------------------------|
| Trujillo, Irwin | 719-846-0272/719-859-2264 | irwin_trujillo@xtoenergy.com | Sr. Env. Tech., Raton Basin |
| Harrison, Lyndon | 505-333-3100 | Lyndon_Harrison@xtoenergy.com | |
| Blatnick, Bill | 719-845-2112/719-859-3370 | bill_blatnick@xtoenergy.com | |
| Jaramillo, Diane | 505-333-3109 | diane_jaramillo@xtoenergy.com | Eng. Mngr - Reg., Aztec, NM |
| Kardos, Kelly | | kelly_kardos@xtoenergy.com | |

Compliance Summary:

QtrQtr: NWNE Sec: 8 Twp: 34S Range: 67W

| Insp. Date | Doc Num | Insp. Type | Insp Status | Satisfactory /Unsatisfactory | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|------------------------------|----------|----------------|-----------------|
| 05/06/2008 | 200190239 | PR | PR | S | | | N |
| 03/23/2005 | 200068637 | PR | PR | S | | P | N |
| 07/19/2002 | 200029270 | PR | PR | S | | P | N |

Inspector Comment:

Related Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | |
|-------------|----------|--------|-------------|------------|-----------|-----------------------------|-------------------------------------|
| 26922 | LEASE | PR | 12/08/1997 | | - | APACHE CANYON UNIT | <input type="checkbox"/> |
| 217393 | WELL | SI | 11/07/2011 | GW | 071-06169 | APACHE CANYON 8-2 | <input type="checkbox"/> |
| 262544 | WELL | PR | 03/09/2002 | GW | 071-07561 | APACHE CANYON 08-02R | <input checked="" type="checkbox"/> |
| 266449 | LEASE | PR | 02/18/2003 | | - | APACHE CANYON 08-02R | <input type="checkbox"/> |
| 268854 | PIT | | 07/28/2003 | | - | APACHE CANYON 08-02R | <input type="checkbox"/> |
| 312069 | LOCATION | AC | 04/14/2009 | | - | APACHE CANYON-634S67W 8NWNE | <input type="checkbox"/> |

Equipment:

Location Inventory

| | | | |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____ | Drilling Pits: _____ | Wells: _____ | Production Pits: _____ |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: _____ | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: _____ |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: _____ | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

| Signs/Marker: | | | | |
|----------------------|-----------------------------|---------|-------------------|---------|
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| WELLHEAD | Satisfactory | | | |

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____

Comment: _____

Corrective Action: _____

| Spills: | | | | |
|--|------|--------|-------------------|---------|
| Type | Area | Volume | Corrective action | CA Date |
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |

| Fencing/: | | | | |
|------------------|-----------------------------|---------|-------------------|---------|
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| PIT | Satisfactory | | | |

| Equipment: | | | | | |
|--------------------|---|-----------------------------|---------|-------------------|---------|
| Type | # | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| Compressor | 1 | Satisfactory | | | |
| Gas Meter Run | 1 | Satisfactory | | | |
| Vertical Separator | 1 | Satisfactory | | | |
| Progressive Cavity | 1 | Satisfactory | | | |
| Deadman # & Marked | 4 | Satisfactory | | | |

| | | | | | |
|------------------------|--------------|-----------------------------------|---------------------|------------------|--|
| Facilities: | | <input type="checkbox"/> New Tank | Tank ID: _____ | | |
| Contents | # | Capacity | Type | SE GPS | |
| PRODUCED WATER | 1 | <50 BBLS | STEEL AST | , | |
| S/U/V: | Satisfactory | | Comment: | | |
| Corrective Action: | | | | Corrective Date: | |
| <u>Paint</u> | | | | | |
| Condition | Adequate | | | | |
| Other (Content) _____ | | | | | |
| Other (Capacity) _____ | | | | | |
| Other (Type) _____ | | | | | |
| <u>Berms</u> | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| | | | | | |
| Corrective Action | | | | Corrective Date | |
| Comment | | | | | |

| | | | | | |
|------------------------|--------------|-----------------------------------|---------------------|------------------|--|
| Facilities: | | <input type="checkbox"/> New Tank | Tank ID: _____ | | |
| Contents | # | Capacity | Type | SE GPS | |
| PRODUCED WATER | 1 | <50 BBLS | FIBERGLASS AST | , | |
| S/U/V: | Satisfactory | | Comment: | | |
| Corrective Action: | | | | Corrective Date: | |
| <u>Paint</u> | | | | | |
| Condition | Adequate | | | | |
| Other (Content) _____ | | | | | |
| Other (Capacity) _____ | | | | | |
| Other (Type) _____ | | | | | |
| <u>Berms</u> | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| | | | | | |
| Corrective Action | | | | Corrective Date | |
| Comment | | | | | |

| | | |
|-----------------|---------|--|
| Venting: | | |
| Yes/No | Comment | |
| | | |

| | | | | |
|-----------------|-----------------------------|---------|-------------------|---------|
| Flaring: | | | | |
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| | | | | |

Predrill

Location ID: 312069

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____
Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Comment: _____

CA: _____ **Date:** _____

Wildlife BMPs:

Comment: _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Well

Facility ID: 262544 API Number: 071-07561 Status: PR Insp. Status: PR

Data retrieval failed for the subreport 'Subreport9' located at: \\dardensterling\cFarmPa
Data retrieval failed for the subreport 'Subreport10' located at: \\dardensterling\cFarmP

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____
Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

S/U/V: _____ Corrective Date: _____

Comment: _____

CA: _____

Pits:

Pit Type: Produced Water Lined: NO Pit ID: _____ Lat: _____ Long: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment: _____

Fencing:

Fencing Type: _____ Fencing Condition: _____

Comment: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: _____

Anchor Trench Present: _____ Oil Accumulation: NO 2+ feet Freeboard: _____

Pit (S/U/V): Satisfactory Comment: 25' X 70'

Corrective Action: _____ Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------------|---|
| 668000066 | INSPECTION APPROVED | http://cogcc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=2898126 |

