

**FORM  
INSP**Rev  
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

04/19/2012

Document Number:

661601139

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

Location Identifier Facility ID Loc ID Tracking Type  
 244813 323136 Inspector Name: MONTOYA, JOHN

**Operator Information:**OGCC Operator Number: 47120 Name of Operator: KERR-MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVERState: COZip: 80217-**Contact Information:**

Contact Name	Phone	Email	Comment
Price, Tom	/10318	tom.price@anadarko.com	Wattenberg South Prod'n Supervisor

**Compliance Summary:**QtrQtr: SWSW Sec: 28 Twp: 4N Range: 66W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
08/11/2008	200193632	PR	PR	S			N
03/04/2002	200024733	PR	PR	S		P	N
01/07/1998	500168867	PR	PR				
03/27/1996	500168866						

**Inspector Comment:****Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
244813	WELL	PR	12/08/1987		123-12608	KEISER 13-28	<input checked="" type="checkbox"/>
323136	LOCATION	AC	04/14/2009		-	KEISER-64N66W 28SWSW	<input type="checkbox"/>

**Equipment:**Location Inventory

Special Purpose Pits: \_\_\_\_\_ Drilling Pits: \_\_\_\_\_ Wells: \_\_\_\_\_ Production Pits: \_\_\_\_\_  
 Condensate Tanks: \_\_\_\_\_ Water Tanks: \_\_\_\_\_ Separators: \_\_\_\_\_ Electric Motors: \_\_\_\_\_  
 Gas or Diesel Mortors: \_\_\_\_\_ Cavity Pumps: \_\_\_\_\_ LACT Unit: \_\_\_\_\_ Pump Jacks: \_\_\_\_\_  
 Electric Generators: \_\_\_\_\_ Gas Pipeline: \_\_\_\_\_ Oil Pipeline: \_\_\_\_\_ Water Pipeline: \_\_\_\_\_  
 Gas Compressors: \_\_\_\_\_ VOC Combustor: \_\_\_\_\_ Oil Tanks: \_\_\_\_\_ Dehydrator Units: \_\_\_\_\_  
 Multi-Well Pits: \_\_\_\_\_ Pigging Station: \_\_\_\_\_ Flare: \_\_\_\_\_ Fuel Tanks: \_\_\_\_\_

**Location****Signs/Marker:**

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
BATTERY	Satisfactory			
TANK LABELS/PLACARDS	Satisfactory			

Inspector Name: MONTOYA, JOHN

CONTAINERS	Satisfactory			
WELLHEAD	Satisfactory			

Emergency Contact Number: (S/U/V) \_\_\_\_\_ Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

**Spills:**

Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

**Fencing:**

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
SEPARATOR	Satisfactory			
WELLHEAD	Satisfactory			
TANK BATTERY	Satisfactory			

**Equipment:**

Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Horizontal Heated Separator	1	Satisfactory			
Plunger Lift	1	Satisfactory			
Gas Meter Run	2	Satisfactory			
Bird Protectors	1	Satisfactory			

**Tanks/Berms:** ☐ New Tank Tank ID: \_\_\_\_\_

Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	<50 BBLS	CONCRETE SUMP/VAULT	,

S/U/V: \_\_\_\_\_ Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Corrective Date: \_\_\_\_\_

**Paint**

Condition	Adequate
Other (Content)	_____
Other (Capacity)	_____
Other (Type)	_____

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action \_\_\_\_\_ Corrective Date \_\_\_\_\_

Comment \_\_\_\_\_

**Tanks/Berms:** ☐ New Tank Tank ID: \_\_\_\_\_

Contents	#	Capacity	Type	SE GPS
CRUDE OIL	1	300 BBLS		40.275440,-104.786670

S/U/V:		Comment:	
Corrective Action:		Corrective Date:	

Paint

Condition	Adequate
-----------	----------

Other (Content) \_\_\_\_\_

Other (Capacity) \_\_\_\_\_

Other (Type) \_\_\_\_\_

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action		Corrective Date	
-------------------	--	-----------------	--

Comment	
---------	--

<b><u>Venting:</u></b>	
Yes/No	Comment
NO	

<b><u>Flaring:</u></b>				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

**Predrill**

Location ID: 323136

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_

Pads: \_\_\_\_\_

Soil Stockpile: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:****Wildlife BMPs:****Stormwater:****Comment:** \_\_\_\_\_**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

**Operator Rep. Contact Information:**

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

**LGD Contact Information:**

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

**Summary of Landowner Issues:****Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Well**

Facility ID: 244813 API Number: 123-12608 Status: PR Insp. Status: PR

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Inspector Name: MONTOYA, JOHN

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Debris removed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Waste Material Onsite? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation \_\_\_\_\_

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Inspector Name: MONTOYA, JOHN

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_  
Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_  
Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_  
Gravel removed \_\_\_\_\_  
Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_  
Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_  
Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_  
Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_  
Comment: \_\_\_\_\_  
Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
S/U/V: _____ Corrective Date: _____						
Comment: _____						
CA: _____						