

**Location ID: 334743 WPX ENERGY**



Viewing north: Cut slope experiencing rilling. Negligible vegetation observed.



Viewing north: Cut and side slopes experiencing rilling. Negligible vegetation observed.



Disturbed surfaces to the east has no vegetation or erosion control BMPs .

**“GV 21-35 Pad”**

April 16, 2012