

FORM 5A

Rev 02/08

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



Table with 4 columns: DE, ET, OE, ES

Document Number: 400275606

Date Received:

COMPLETED INTERVAL REPORT

The completed interval Report, Form 5A, shall be submitted within thirty (30) days of completing a formation (successful or not), when a formation is temporarily abandoned or permanently abandoned, for a recompletion, reperforation or restimulation, or when a formation is commingled. Fill out a section for each formation. Attach as many pages as required to fully describe the work. List in order of completion.

1. OGCC Operator Number: 66571
2. Name of Operator: OXY USA WTP LP
3. Address: P O BOX 27757
City: HOUSTON State: TX Zip: 77227
4. Contact Name: Joan Proulx
Phone: (970) 263-3641
Fax: (970) 263-3694

5. API Number 05-045-16019-00
6. County: GARFIELD
7. Well Name: CASCADE CREEK
Well Number: 697-16-13B
8. Location: QtrQtr: SWSE Section: 9 Township: 6S Range: 97W Meridian: 6
9. Field Name: GRAND VALLEY Field Code: 31290

Completed Interval

FORMATION: WILLIAMS FORK - CAMEO Status: PRODUCING
Treatment Date: 12/14/2011 Date of First Production this formation: 12/20/2009
Perforations Top: 6904 Bottom: 7138 No. Holes: 33 Hole size: 35/100
Provide a brief summary of the formation treatment: Open Hole: []
1 stage of slickwater frac with 4,276 bbls of frac fluid and 164,659 lbs of white sand proppant
This formation is commingled with another formation: [] Yes [X] No
Test Information:
Date: 04/03/2012 Hours: 24 Bbls oil: 0 Mcf Gas: 0 Bbls H2O: 0
Calculated 24 hour rate: Bbls oil: 0 Mcf Gas: 0 Bbls H2O: 0 GOR: 0
Test Method: Flowing Casing PSI: 728 Tubing PSI: 900 Choke Size: 18/64
Gas Disposition: SOLD Gas Type: DRY BTU Gas: 1061 API Gravity Oil: 0
Tubing Size: 2 + 3/8 Tubing Setting Depth: 7893 Tbg setting date: 02/21/2012 Packer Depth:
Reason for Non-Production:
Date formation Abandoned: Squeeze: [] Yes [] No If yes, number of sacks cmt
Bridge Plug Depth: Sacks cement on top:

Comment:
Repair work occurred on this well to drill through a tubing obstruction, tubing was re-landed and the well was returned to production.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.
Signed: Print Name: Joan Proulx
Title: Regulatory Analyst Date: Email joan_proulx@oxy.com

Attachment Check List

Att Doc Num	Name

Total Attach: 0 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>

Total: 0 comment(s)