

FORM INSP Rev 05/11	State of Colorado Oil and Gas Conservation Commission 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109		DE ET OE ES
-------------------------------	--	--	----------------------

Inspection Date: 05/09/2012

Document Number: 663901076

Overall Inspection: Unsatisfactory

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name: <u>QUINT, CRAIG</u>
	<u>337434</u>	<u>337434</u>		

Operator Information:

OGCC Operator Number: 100128 Name of Operator: VISTA OPERATING INC

Address: 61 MCMURRAY RD STE 300

City: PITTSBURGH State: PA Zip: 15241

Contact Information:

Contact Name	Phone	Email	Comment
Nicklas, David M	412-833-8884 off	dnicklas@vistaresources.com	

Compliance Summary:

QtrQtr: SESW Sec: 28 Twp: 1N Range: 48W

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
285769	WELL	SI	04/16/2012	GW	125-10195	S-Y KIRCHENSCHLAGER 24-28	<input checked="" type="checkbox"/>

Equipment: Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:

Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Access	Satisfactory	GRAVEL 2 TRACK THROUGH PASTURE.		

Signs/Marker:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory	LEASE SIGN BY WELLHEAD		
OTHER	Satisfactory	LEASE SIGN BY METER		

TANK LABELS/PLACARDS	Unsatisfactory	NO VISIBLE TANK LABELING	Install sign to comply with rule 210.d.	08/09/2012
----------------------	----------------	--------------------------	---	------------

Emergency Contact Number: (S/U/V) Satisfactory _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
LOCATION	Satisfactory	LOCATION FENCED WITH WIRE		

Equipment:

Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Vertical Separator	2	Satisfactory	1-VGS 50% BURIED, 1-VGS IN A METAL SHED		
Gas Meter Run	1	Satisfactory			
Ancillary equipment	1	Unsatisfactory	CHEMICAL TANK WITHOUT CONTAINMENT BY WELLHEAD.	INSTALL CONTAINMENT	08/09/2012

Facilities: New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
PRODUCED WATER	1	<50 BBLS	PBV PLASTIC	40.019920,-102.749310

S/U/V: Satisfactory Comment: _____

Corrective Action: _____ Corrective Date: _____

Paint

Condition: _____

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Corrective Action: _____ Corrective Date: _____

Comment: _____

Venting:

Yes/No	Comment

Flaring:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 337434

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Comment: _____

CA: _____ **Date:** _____

Wildlife BMPs:

Comment: _____

CA: _____ **Date:** _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 285769 API Number: 125-10195 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____
S/V: Satisfactory CA Date: _____
CA: _____
Comment: _____

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
Comment: _____
Corrective Action: _____ Date: _____
Reportable: _____ GPS: Lat _____ Long _____
Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____
DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____
Comment: _____
Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____
Land Use: _____
Comment: _____
1003a. Debris removed? Pass CM _____ CA _____ CA Date _____
Waste Material Onsite? Pass CM _____ CA _____ CA Date _____
Unused or unneeded equipment onsite? Pass CM _____ CA _____ CA Date _____
Pit, cellars, rat holes and other bores closed? Pass CM _____ CA _____ CA Date _____
Guy line anchors removed? _____ CM _____ CA _____ CA Date _____
Guy line anchors marked? _____ CM _____ CA _____ CA Date _____
1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Pass
 Production areas have been stabilized? Pass Segregated soils have been replaced? Pass

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced Pass Recontoured Pass 80% Revegetation Pass

1003 f. Weeds Noxious weeds? P

Comment:

Overall Interim Reclamation Pass

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment:

Corrective Action: Date _____

Overall Final Reclamation

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Seeding	Pass	Gravel	Pass	MHSP	Fail	

S/U/V: Unsatisfactory Corrective Date: 08/09/2012

Comment: CHEMICAL TANK WITHOUT CONTAINMENT

CA: INSTALL CONTAINMENT

Pits:

Pit Type: Evaporation Lined: NO Pit ID: _____ Lat: 40.019920 Long: -102.749310

Lining:

Liner Type: _____ Liner Condition: _____

Comment: _____

Fencing:

Fencing Type: Livestock Fencing Condition: Adequate

Comment: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment: _____

Anchor Trench Present: _____ Oil Accumulation: NO 2+ feet Freeboard: _____

Pit (S/U/V): Unsatisfactory Comment: UNLINED PIT WITOUT MONITORING EQUIPMENT OR ADEQUATE FREE BOARD.

Corrective Action: IF PLACED BACK INTO PRODUCTION INSTALL MONITORING EQUIPMENT AND REPAIR FREE BOARD. Date: 08/09/2012

Monitoring:	Monitoring Type	Comment
	None	NO VISIBLE MONITORING EQUIPMENT