

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

05/17/2012

Document Number:

663800343

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

Location Identifier Facility ID Loc ID Tracking Type
 291476 335667 Inspector Name: LONGWORTH, MIKE

Operator Information:OGCC Operator Number: 100185 Name of Operator: ENCANA OIL & GAS (USA) INCAddress: 370 17TH ST STE 1700City: DENVERState: COZip: 80202-**Contact Information:**

Contact Name	Phone	Email	Comment
Friesen, Kathy	970-285-2665	Kathy.Friesen@EnCana.com	

Compliance Summary:QtrQtr: SENW Sec: 23 Twp: 5S Range: 96W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
09/10/2010	200278116	PR	PR	S			N

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
282296	WELL	PR	08/03/2006	GW	045-11726	N PARACHUTE WF06C-23 F23596	X
291476	WELL	PR	01/31/2009	OW	045-14383	N PARACHUTE WF12D-23 F23596	X
291501	WELL	PR	07/31/2008	OW	045-14427	N PARACHUTE WF14C-23 F23596	X
291502	WELL	PR	07/23/2007	LO	045-14426	N PARACHUTE WF15A-23 F23596	X
291503	WELL	PR	01/31/2009	OW	045-14425	N PARACHUTE WF05C-23 F23596	X
291504	WELL	AL	05/27/2011	LO	045-14424	ENCANA RPW 511-23-596	X
291505	WELL	SI	01/12/2012	GW	045-14423	N PARACHUTE WF11D-23 F23596	X
291506	WELL	PR	07/08/2009	LO	045-14422	N PARACHUTE WF06D-23 F23596	X
291508	WELL	PR	04/11/2012	OW	045-14421	N. PARACHUTE WF 14A-23F23596	X
291510	WELL	AL	05/27/2011	LO	045-14420	ENCANA RPW 312-23-596	X
291512	WELL	PR	03/01/2009	OW	045-14419	N PARACHUTE WF12A-23 F23596	X
291514	WELL	PR	07/23/2007	LO	045-14418	N PARACHUTE WF14B-23 F23596	X
291518	WELL	PR	04/01/2008	LO	045-14417	N PARACHUTE WF05D-23 F23596	X

Inspector Name: LONGWORTH, MIKE

291523	WELL	AL	05/27/2011	LO	045-14416	ENCANA RPW 411-23-596	X
291524	WELL	AL	05/27/2011	LO	045-14415	ENCANA RPW 311-23-596	X
291525	WELL	PR	01/01/2009	OW	045-14414	N PARACHUTE WF11B-23 F23596	X
291526	WELL	AL	05/27/2011	LO	045-14413	ENCANA RPW 12-23-596	X
291527	WELL	PR	07/23/2007	LO	045-14412	N PARACHUTE WF11A-23 F23596	X
291528	WELL	AL	05/27/2011	LO	045-14411	ENCANA RPW 11-23-596	X
291529	WELL	PR	01/19/2009	OW	045-14410	N PARACHUTE WF12B-23 F23596	X
291530	WELL	PR	01/17/2009	OW	045-14408	N PARACHUTE WF11C-23 F23596	X
291531	WELL	AL	05/27/2011	LO	045-14409	ENCANA RPW 22-23-596	X

Equipment:Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Lease Road:**

Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Access	Satisfactory			

Signs/Marker:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
BATTERY	Satisfactory			
TANK LABELS/PLACARDS	Unsatisfactory		Install sign to comply with rule 210.d.	06/01/2012
WELLHEAD	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory

Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
UNUSED EQUIPMENT	Unsatisfactory		remove unused equipment	06/01/2012

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?**Fencing/:**

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory			

Inspector Name: LONGWORTH, MIKE

SEPARATOR	Satisfactory			
TANK BATTERY	Satisfactory			

Equipment:					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Bird Protectors	13	Satisfactory			
Horizontal Heated Separator	20	Satisfactory			
Plunger Lift	15	Satisfactory			

Facilities: ☐ New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
CONDENSATE	4	300 BBLS	STEEL AST	,
S/U/V:	Satisfactory	Comment:		
Corrective Action:				Corrective Date:

Paint	
Condition	Adequate
Other (Content)	_____
Other (Capacity)	_____
Other (Type)	_____

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Corrective Action				Corrective Date
Comment				

Venting:	
Yes/No	Comment

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 335667

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Comment:** _____**CA:** _____**Date:** _____**Wildlife BMPs:****Comment:** _____**CA:** _____**Date:** _____**Stormwater:**

Erosion BMPs

Present

Other BMPs

Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment: _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**Facility**

Facility ID: 282296 API Number: 045-11726 Status: PR Insp. Status: PR

Facility ID: 291476 API Number: 045-14383 Status: PR Insp. Status: PR

Facility ID: 291501 API Number: 045-14427 Status: PR Insp. Status: PR

Inspector Name: LONGWORTH, MIKE

Facility ID:	291502	API Number:	045-14426	Status:	PR	Insp. Status:	PR
Facility ID:	291503	API Number:	045-14425	Status:	PR	Insp. Status:	PR
Facility ID:	291504	API Number:	045-14424	Status:	AL	Insp. Status:	AL
Facility ID:	291505	API Number:	045-14423	Status:	SI	Insp. Status:	PR
Facility ID:	291506	API Number:	045-14422	Status:	PR	Insp. Status:	PR
Facility ID:	291508	API Number:	045-14421	Status:	PR	Insp. Status:	PR
Facility ID:	291510	API Number:	045-14420	Status:	AL	Insp. Status:	AL
Facility ID:	291512	API Number:	045-14419	Status:	PR	Insp. Status:	PR
Facility ID:	291514	API Number:	045-14418	Status:	PR	Insp. Status:	PR
Facility ID:	291518	API Number:	045-14417	Status:	PR	Insp. Status:	PR
Facility ID:	291523	API Number:	045-14416	Status:	AL	Insp. Status:	AL
Facility ID:	291524	API Number:	045-14415	Status:	AL	Insp. Status:	AL
Facility ID:	291525	API Number:	045-14414	Status:	PR	Insp. Status:	PR
Facility ID:	291526	API Number:	045-14413	Status:	AL	Insp. Status:	AL
Facility ID:	291527	API Number:	045-14412	Status:	PR	Insp. Status:	PR
Facility ID:	291528	API Number:	045-14411	Status:	AL	Insp. Status:	AL
Facility ID:	291529	API Number:	045-14410	Status:	PR	Insp. Status:	PR
Facility ID:	291530	API Number:	045-14408	Status:	PR	Insp. Status:	PR
Facility ID:	291531	API Number:	045-14409	Status:	AL	Insp. Status:	AL

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment:

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat

Long

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Inspector Name: LONGWORTH, MIKE

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: _____ Corrective Date: _____

Comment: _____

CA: _____