

From: [Lujan, Carlos](#)
To: [Scan, OGCC](#)
Cc: "[bdodek@ltenv.com](#)"; "[bbruns@petd.com](#)"; [Axelson, John](#)
Subject: FW: Jason 1, 2, 34-31 NFA Request
Date: Friday, May 18, 2012 1:43:13 PM
Attachments: [Jason 1, 2, 34-31 GW NFA Report.pdf](#)
[PDC NFA Letter Jason REM# 6010 May 18 2012.pdf](#)

Amber,

Please upload the two attached documents (and this email as well) to

- REM # 6010
- Location ID # 322990
- API # 123 12387

Brian,

Four consecutive quarters of Colorado Oil and Gas Conservation Commission Table 910-1 compliant groundwater analytical results have been achieved.

Please find attached the NFA letter for the Jason 1, 2, 34-31 Tank Battery release.

The remediation Project # 6010 has been closed with Form 27A.

Thanks,

Carlos

Carlos A. Luján, Ph.D

Groundwater Hydrologist

Cell: (720) 272-2306

**Colorado Oil & Gas Conservation
Commission**

1120 Lincoln Street, Suite 801, Denver, CO

80203

(303) 894-2100 Ext. 5105

Carlos.lujan@state.co.us



Please consider the environment prior to printing this e-mail...

From: Brian Dodek [<mailto:bdodek@ltenv.com>]
Sent: Thursday, May 10, 2012 6:00 PM
To: Axelson, John
Cc: Brandon Bruns (bbruns@petd.com)
Subject: Jason 1, 2, 34-31 NFA Request

John,

LTE would like to submit the following No Further Action determination request on behalf of PDC. Please review the attached supporting documentation for activities associated with a failed oil dumphline and

produced water vault at the above referenced subject site located in the NWSE Section 31-T6N-R64W. Soil and groundwater were impacted at the site from the release. Approximately 530 cubic yards of impacted soil were removed from the site and transported to a licensed disposal facility. Analytical results indicated that the final extent of the excavation associated with the release were in compliance with COGCC Table 910-1 Concentration Levels. Activated carbon was applied to the excavation before backfilling activities to remediate residual hydrocarbons. Monitoring wells were installed in April 2011. Groundwater samples were collected on a quarterly basis until analytical data was in compliance with CDPHE Regulation 41 Standards for four consecutive quarters.

As four consecutive quarters of CDPHE Reg 41 compliant groundwater analytical results have been achieved, PDC is requesting a No Further Action determination for this site.

Please call Brandon Bruns at 303-831-3971 if you have any questions regarding this site.

Thanks,
Brian

Brian Dodek, P.G.
*Senior Geologist / Client
Manager*

LT Environmental, Inc.
4600 West 60th Avenue
Arvada, Colorado 80003

(303) 433-9788 Office
(303) 962-5535 Direct
(303) 483-5486 Cell
(303) 433-1432 Fax



Compliance • Engineering • Remediation

www.LTEEnv.com
bdodek@LTEEnv.com

 Please consider the environment before printing this e-mail or attachments.

This message is privileged, confidential and intended solely for the use of the addressee. Any review, retransmission, dissemination or other use of or taking of any action in reliance upon this information by persons or entities other than the intended recipient is prohibited. The comments and opinions expressed herein are those of the author of this message. If you are not the intended recipient you have received this in error. Please contact the sender by reply email and destroy all copies of the original message from your computer, and any network to which your computer is connected. Thank you.