

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

05/17/2012

Document Number:

668400219

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

Location Identifier: 228394 Facility ID: 314337 Tracking Type: _____ Inspector Name: BROWNING, CHUCK

Operator Information:OGCC Operator Number: 51130 Name of Operator: LOCIN OIL CORPORATIONAddress: 25231 GROGAN'S MILL RD STE 500City: THE WOODLANDS State: TX Zip: 77380**Contact Information:**

Contact Name	Phone	Email	Comment
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Clavenna, Mark	281-362-8600 X22	mclavenna@nclnr.com	

Compliance Summary:QtrQtr: NWSE Sec: 13 Twp: 1S Range: 102W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
03/16/1999	500156610	PR	PR			P	N

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
228394	WELL	PA	04/18/2002		103-05238	DOUGLAS "AG" A-5	<input checked="" type="checkbox"/>

Equipment:Location Inventory

Special Purpose Pits: _____ Drilling Pits: _____ Wells: _____ Production Pits: _____
 Condensate Tanks: _____ Water Tanks: _____ Separators: _____ Electric Motors: _____
 Gas or Diesel Motors: _____ Cavity Pumps: _____ LACT Unit: _____ Pump Jacks: _____
 Electric Generators: _____ Gas Pipeline: _____ Oil Pipeline: _____ Water Pipeline: _____
 Gas Compressors: _____ VOC Combustor: _____ Oil Tanks: _____ Dehydrator Units: _____
 Multi-Well Pits: _____ Pigging Station: _____ Flare: _____ Fuel Tanks: _____

LocationEmergency Contact Number: (S/U/V) Unsatisfactory

Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Venting:		
Yes/No	Comment	

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 314337

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****Comment:** _____**CA:** _____ **Date:** _____**Stormwater:**

Erosion BMPs	Present	Other BMPs	Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment: _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 228394 API Number: 103-05238 Status: PA Insp. Status: PA

Data retrieval failed for the subreport, 'rptInsp12',

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use:

Comment:

1003a. Debris removed? CM CA Date

Waste Material Onsite? CM CA Date

Unused or unneeded equipment onsite? CM CA Date

Pit, cellars, rat holes and other bores closed? CM CA Date

Guy line anchors removed? CM CA Date

Guy line anchors marked? CM CA Date

1003b. Area no longer in use? Production areas stabilized ?

1003c. Compacted areas have been cross ripped?

1003d. Drilling pit closed? Subsidence over on drill pit?

Cuttings management:

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing?

Production areas have been stabilized? Segregated soils have been replaced?

RESTORATION AND REVEGETATIONCropland

Top soil replaced Recontoured Perennial forage re-established

Non-Cropland

Top soil replaced Recontoured 80% Revegetation

1003 f. Weeds Noxious weeds?

Comment:

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: Date Final Reclamation Completed:

Final Land Use:

Reminder:

Inspector Name: BROWNING, CHUCK

Comment:

Well plugged Pass Pit mouse/rat holes, cellars backfilled Pass
Debris removed Pass No disturbance /Location never built Pass
Access Roads Regraded Pass Contoured Pass Culverts removed Pass
Gravel removed Pass
Location and associated production facilities reclaimed In Locations, facilities, roads, recontoured Pass
Compaction alleviation Pass Dust and erosion control Pass
Non cropland: Revegetated 80% In Cropland: perennial forage Pass
Weeds present Pass Subsidence Pass

Comment: Poor regrowth. Needs reseeding.

Corrective Action:

Date

Overall Final Reclamation In Process

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
------------------	-----------------	-------------------------	-----------------------	---------------	--------------------------	---------

S/U/V: Satisfactory Corrective Date:

Comment:

CA: