


FORM INSP Rev 05/11	State of Colorado Oil and Gas Conservation Commission 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109		DE	ET	OE	ES
	Inspection Date: <u>05/22/2012</u>					

FIELD INSPECTION FORM			
Location Identifier	Facility ID <u>335808</u>	Loc ID <u>335808</u>	Tracking Type _____ Inspector Name: <u>LONGWORTH, MIKE</u>
Document Number: <u>663800355</u> Overall Inspection: <u>Satisfactory</u>			

Operator Information:

OGCC Operator Number: 100185 Name of Operator: ENCANA OIL & GAS (USA) INC

Address: 370 17TH ST STE 1700

City: DENVER State: CO Zip: 80202-

Contact Information:

Contact Name	Phone	Email	Comment
Friesen, Kathy	970-285-2665	Kathy.Friesen@EnCana.com	

Compliance Summary:

QtrQtr: NESW Sec: 23 Twp: 5S Range: 96W

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
277667	WELL	PR	11/06/2006	LO	045-10744	N.PARACHUTE WF09B K23 596	<input checked="" type="checkbox"/>
277668	WELL	PR	11/06/2006	LO	045-10745	N. PARACHUTE WF08D K23 596	<input checked="" type="checkbox"/>
277669	WELL	PR	07/18/2007	OW	045-10746	N. PARACHUTE WF08B K23 596	<input checked="" type="checkbox"/>
277670	WELL	PR	08/16/2007	GW	045-10747	N. PARACHUTE WF07D K23 596	<input checked="" type="checkbox"/>
277671	WELL	PR	09/03/2007	GW	045-10748	N. PARACHUTE WF10B K23 596	<input checked="" type="checkbox"/>
277672	WELL	PR	03/17/2006	GW	045-10749	N. PARACHUTE WF02D K23 596	<input checked="" type="checkbox"/>
277673	WELL	PR	11/20/2005	GW	045-10750	N. PARACHUTE WF15D K23 596	<input checked="" type="checkbox"/>
277674	WELL	PR	12/26/2005	GW	045-10751	N. PARACHUTE WF03D K23 596	<input checked="" type="checkbox"/>

Equipment: Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:				
Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Access	Satisfactory			

Signs/Marker:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
TANK LABELS/PLACARDS				
BATTERY	Satisfactory			
WELLHEAD	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
STORAGE OF SUPL	Satisfactory			
TRASH	Satisfactory			

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Equipment:					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Plunger Lift	8	Satisfactory			
Horizontal Heated Separator	1	Satisfactory			
Gas Meter Run	3	Satisfactory			
Bird Protectors	1	Satisfactory			

Facilities:		<input type="checkbox"/> New Tank	Tank ID: _____	
Contents	#	Capacity	Type	SE GPS
CONDENSATE	1	<100 BBLS	STEEL AST	,
S/U/V:	Satisfactory	Comment:		
Corrective Action:				Corrective Date:

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Sufficient	Base Sufficient	Adequate
Corrective Action	Build up berm walls			Corrective Date 06/08/2012
Comment				

Venting:	
Yes/No	Comment

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 335808

Site Preparation:
 Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____
 Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Comment: _____
CA: _____ **Date:** _____

Wildlife BMPs:

Comment: _____
CA: _____ **Date:** _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____
 Other BMPs: _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility				
Facility ID:	<u>277667</u>	API Number:	<u>045-10744</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Facility ID:	<u>277668</u>	API Number:	<u>045-10745</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Facility ID:	<u>277669</u>	API Number:	<u>045-10746</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Facility ID:	<u>277670</u>	API Number:	<u>045-10747</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Facility ID:	<u>277671</u>	API Number:	<u>045-10748</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Facility ID:	<u>277672</u>	API Number:	<u>045-10749</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Facility ID:	<u>277673</u>	API Number:	<u>045-10750</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
Facility ID:	<u>277674</u>	API Number:	<u>045-10751</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment:

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS: _____ Lat _____ Long _____

Field Parameters:

Sample Location:

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment:

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation

Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
Drains	Pass					

S/U/V: Satisfactory Corrective Date: _____

Comment: _____

CA: _____