

FORM INSP
Rev 05/11

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
06/01/2012

Document Number:
663901169

Overall Inspection:
Unsatisfactory

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name:
	<u>418794</u>	<u>418794</u>		<u>QUINT, CRAIG</u>

Operator Information:

OGCC Operator Number:	<u>10267</u>	Name of Operator:	<u>VECTA OIL & GAS LTD</u>
Address:	<u>575 UNION BLVD #208</u>		
City:	<u>LAKEWOOD</u>	State:	<u>CO</u>
		Zip:	<u>80228</u>

Contact Information:

Contact Name	Phone	Email	Comment
Goolsby, Matt	303-618-7736 cell	mdgoolsby@comcast.net	

Compliance Summary:

QtrQtr:	<u>SWSW</u>	Sec:	<u>12</u>	Twp:	<u>14S</u>	Range:	<u>47W</u>
---------	-------------	------	-----------	------	------------	--------	------------

Inspector Comment:

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
418793	WELL	XX	08/16/2010		017-07698	LINCOLN 14-12	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits:	<u> </u>	Drilling Pits:	<u>1</u>	Wells:	<u>1</u>	Production Pits:	<u> </u>
Condensate Tanks:	<u> </u>	Water Tanks:	<u>2</u>	Separators:	<u>1</u>	Electric Motors:	<u>1</u>
Gas or Diesel Mortors:	<u>1</u>	Cavity Pumps:	<u> </u>	LACT Unit:	<u> </u>	Pump Jacks:	<u>1</u>
Electric Generators:	<u> </u>	Gas Pipeline:	<u> </u>	Oil Pipeline:	<u> </u>	Water Pipeline:	<u> </u>
Gas Compressors:	<u>1</u>	VOC Combustor:	<u> </u>	Oil Tanks:	<u>2</u>	Dehydrator Units:	<u> </u>
Multi-Well Pits:	<u> </u>	Pigging Station:	<u> </u>	Flare:	<u> </u>	Fuel Tanks:	<u>1</u>

Location

Emergency Contact Number: <u>(S/U/V)</u> <u> </u>	Corrective Date: <u> </u>
Comment: <u> </u>	
Corrective Action: <u> </u>	

Spills:

Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Venting:

Yes/No	Comment

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 418794

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____
 Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Comment: _____

CA: _____ **Date:** _____

Wildlife BMPs:

Comment: _____

CA: _____ **Date:** _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____
 Other BMPs: _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 418793 Type: WELL API Number: 017-07698 Status: XX Insp. Status: PA

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____
Comment: _____
Corrective Action: _____ Date: _____
Reportable: _____ GPS: Lat _____ Long _____
Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____
DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____
Comment: _____
Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____
Land Use: CRP
Comment: _____
1003a. Debris removed? _____ CM _____
CA _____ CA Date _____
Waste Material Onsite? _____ CM _____
CA _____ CA Date _____
Unused or unneeded equipment onsite? _____ CM _____
CA _____ CA Date _____
Pit, cellars, rat holes and other bores closed? _____ CM _____
CA _____ CA Date _____
Guy line anchors removed? _____ CM _____
CA _____ CA Date _____
Guy line anchors marked? _____ CM _____
CA _____ CA Date _____
1003b. Area no longer in use? _____ Production areas stabilized ? _____
1003c. Compacted areas have been cross ripped? _____
1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
Cuttings management: _____
1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: CRP

Reminder: _____

Comment: _____

Well plugged Pass Pit mouse/rat holes, cellars backfilled Pass

Debris removed Pass No disturbance /Location never built _____

Access Roads Regraded In Contoured In Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured In

Compaction alleviation In Dust and erosion control _____

Non cropland: Revegetated 80% In Cropland: perennial forage _____

Weeds present In Subsidence In

Comment: **LOCATION HAS BEEN MOWED, WILL NEED TO SEED.**

Corrective Action: **DIG UP, CUT AND CAP WELLHEAD, RECLAIM LOCATION** Date **09/01/2012**

Overall Final Reclamation In Process

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: _____ Corrective Date: _____

Comment: _____

CA: _____