

**FORM  
INSP**Rev  
05/11**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

04/26/2012

Document Number:

662300425

Overall Inspection:

**Unsatisfactory****FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name:
	<u>292858</u>	<u>335897</u>		<u>NEIDEL, KRIS</u>

**Operator Information:**OGCC Operator Number: 28700 Name of Operator: EXXON MOBIL OIL CORPORATIONAddress: P O BOX 4358 WGR RM 310City: HOUSTONState: TXZip: 77210-**Contact Information:****Compliance Summary:**QtrQtr: SESE Sec: 34 Twp: 1S Range: 97W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
03/28/2011	200305377	PR	PR	S			Y

**Inspector Comment:**

All wells have telemetry and gauge on surface, intermediate and production casing.

**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
159361	UIC DISPOSAL	AC	02/25/2011		-	PICEANCE CREEK UNIT 197-34B8	
292855	WELL	PR	03/18/2011	GW	103-11090	PICEANCE CREEK UNIT 197-34B3	X
292858	WELL	PR	08/20/2010	LO	103-11089	PICEANCE CREEK UNIT 197-34B9	X
292860	WELL	PR	08/11/2010	LO	103-11088	PICEANCE CREEK UNIT 197-34B5	X
292871	WELL	PR	08/13/2010	LO	103-11087	PICEANCE CREEK UNIT 197-34B4	X
292873	WELL	PR	08/09/2010	LO	103-11086	PICEANCE CREEK UNIT 197-34B7	X
292887	WELL	PR	02/09/2011	LO	103-11085	PICEANCE CREEK UNIT 197-34B2	X
292888	WELL	PR	08/08/2010	LO	103-11084	PICEANCE CREEK UNIT 197-34B1	X
292889	WELL	PR	08/08/2010	LO	103-11083	PICEANCE CREEK UNIT 197-34B6	X
292890	WELL	IJ	06/20/2011	DSPW	103-11082	PICEANCE CREEK UNIT 197-34B8	
293965	WELL	PR	08/26/2010	LO	103-11146	PICEANCE CREEK UNIT 197-34B10	X
335897	LOCATION	AC	04/14/2009		-	PICEANCE CREEK UNIT-61S97W 34SESE	

**Equipment:****Location Inventory**

Inspector Name: NEIDEL, KRIS

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

**Location**

Emergency Contact Number: (S/U/V) \_\_\_\_\_

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

**Spills:**

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

**Venting:**

Yes/No	Comment
--------	---------

**Flaring:**

Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
------	-----------------------------	---------	-------------------	---------

**Predrill**

Location ID: 335897

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_

Pads: \_\_\_\_\_

Soil Stockpile: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:****Comment:****CA:****Date:****Wildlife BMPs:****Comment:****CA:****Date:****Stormwater:**

Erosion BMPs

Present

Other BMPs

Present

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Comments: Erosion BMPs: \_\_\_\_\_

Other BMPs: \_\_\_\_\_

**Comment:****Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

**Operator Rep. Contact Information:**

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

**LGD Contact Information:**

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

**Summary of Landowner Issues:****Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Facility**

Facility ID: 292855 Type: WELL API Number: 103-11090 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Facility ID: 292858 Type: WELL API Number: 103-11089 Status: PR Insp. Status: PR

Inspector Name: NEIDEL, KRIS

**Producing Well**

Comment:

Facility ID: 292860 Type: WELL API Number: 103-11088 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Facility ID: 292871 Type: WELL API Number: 103-11087 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Facility ID: 292873 Type: WELL API Number: 103-11086 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Facility ID: 292887 Type: WELL API Number: 103-11085 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Facility ID: 292888 Type: WELL API Number: 103-11084 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Facility ID: 292889 Type: WELL API Number: 103-11083 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Facility ID: 293965 Type: WELL API Number: 103-11146 Status: PR Insp. Status: PR

**Producing Well**

Comment:

**Environmental**

**Spills/Releases:**

Type of Spill:  Description:  Estimated Spill Volume:

Comment:

Corrective Action:  Date:

Reportable:  GPS: Lat  Long

Proximity to Surface Water:  Depth to Ground Water:

**Water Well:**

Lat  Long

DWR Receipt Num:  Owner Name:  GPS :

**Field Parameters:**

Sample Location:

Inspector Name: NEIDEL, KRIS

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

1003a. Debris removed? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Waste Material Onsite? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? Pass CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? Fail Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? Fail Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? Pass Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation Fail

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Inspector Name: NEIDEL, KRIS

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_  
Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_  
Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_  
Gravel removed \_\_\_\_\_  
Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_  
Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_  
Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_  
Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_  
Comment: \_\_\_\_\_  
Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: \_\_\_\_\_ Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_

**Pits:**

Pit Type: Centralized Frac Lined: YES Pit ID: \_\_\_\_\_ Lat: \_\_\_\_\_ Long: \_\_\_\_\_

**Lining:**

Liner Type: PVC Liner Condition: Adequate

Comment: \_\_\_\_\_

**Fencing:**

Fencing Type: Livestock Fencing Condition: Adequate

Comment: \_\_\_\_\_

**Netting:**

Netting Type: Mesh Netting Condition: Good

Comment: \_\_\_\_\_

Anchor Trench Present: \_\_\_\_\_ Oil Accumulation: YES 2+ feet Freeboard: \_\_\_\_\_

Pit (S/U/V): Unsatisfactory Comment: what is the plan for pit; clouser, use, etc. not all pits are netted.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_