

State of Colorado
Oil and Gas Conservation Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203 (303)894-2100 Fax:(303)894-2109

FOR OGCC USE ONLY

RECEIVED
6/11/2012

SPILL/RELEASE REPORT

This form is to be submitted by the party responsible for the oil and gas spill or release. Any spill or release which may impact waters of the State must be reported as soon as practicable; any spill over 20 bbls must be reported within 24 hours and all spills over five bbls must be reported within ten days. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

Spill report taken by:

FACILITY ID:

OPERATOR INFORMATION

Name of Operator: <u>Continental Resources, Inc</u>	OGCC Operator No: <u>10347</u>	Phone Numbers No: <u>(406) 478-4450</u> Fax: <u>(406) 377 1331</u> E-Mail: <u>Stacy.Aguirre@clr.com</u>
Address: <u>PO Box 1389</u>		
City: <u>Glendive</u>	State: <u>MT</u> Zip: <u>59330</u>	
Contact Person: <u>Stacy Aguirre</u>		

DESCRIPTION OF SPILL OR RELEASE

Date of Incident: <u>06/03/2012</u>	Facility Name & No.: <u>Dunn 1-13H</u>	County: <u>Weld</u>
Type of Facility (well, tank battery, flow line, pit): <u>Well</u>		QtrQtr: <u>NENE</u> Section: <u>13</u>
Well Name and Number: <u>Dunn 1-13H</u>		Township: <u>8N</u> Range: <u>62W</u>
API Number: <u>0512334135</u>		Meridian: _____
Specify volume spilled and recovered (in bbls) for the following materials:		
Oil spilled: <u>8</u> bbls	Oil recov'd: <u>6</u> bbls	Water spilled: <u>0</u> Water recov'd: <u>0</u> Other spilled: <u>0</u> Other recov'd: <u>0</u>
Ground Water impacted? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Surface Water impacted? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Contained within berm? <input checked="" type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Area and vertical extent of spill: <u>200</u> feet <u>x</u> <u>100</u> feet	
Current land use: <u>Rangeland</u>	Weather conditions: <u>Clear, 85 degrees, Wind 5 mph NE</u>	
Soil/geology description: <u>Vona Loamy Sand, 5 to 9 percent slopes</u>		
IF LESS THAN A MILE, report distance IN FEET to nearest.... Surface water: <u>0</u> wetlands: <u>0</u> buildings: <u>800</u> feet		
Livestock: <u>0</u> water wells: <u>800</u> feet Depth to shallowest ground water: <u>> 6.67</u> feet		
Cause of spill (e.g., equipment failure, human error, etc.): <u>Equipment failure</u> Detailed description of the spill/release incident: <u>The well started flowing hard and the seperator popped off and a small mist was released from the flare stack.</u>		

CORRECTIVE ACTION

Describe immediate response (how stopped, contained and recovered):
The well was shut in, earth berms were built around the spill area, a roustabout crew and vac truck were called to location. Approx. 6 bbls of oil were recovered. On location, the contaminated soil was removed and disposed of at Buffalo Ridge.

Describe any emergency pits constructed:
Earth berms were constructed around the spill area.

How was the extent of contamination determined:
Ground Staining

Further remediation activities proposed (attach separate sheet if needed):
On Location: contaminated material was removed and new fill material placed. Off location: S200 (bionutrient) will be sprayed on stained soil.

Describe measures taken to prevent problem from reoccurring:
All the pop-offs on all the tank batteries will be tied into the dump lines going to the production tanks.

OTHER NOTIFICATIONS

List the parties and agencies notified (County, BLM, EPA, DOT, Local Emergency Planning Coordinator or other).


Date	Agency	Contact	Phone	Response

Spill/Release Tracking No: **2229048**

DELORME

T 8 N, R 62 W

Topo USA® 8



Data use subject to license.

© DeLorme. Topo USA® 8.

www.delorme.com



Scale 1 : 25,000
 0 1000 2000 3000 4000 5000
 0 500 1000 1500 2000 2500 3000
 1" = 2,083.3 ft Data Zoom 13-0