

| | | | | | | |
|--|---|--|----|----|----|----|
| FORM INSP Rev 05/11 | State of Colorado Oil and Gas Conservation Commission <small>1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109</small> |  | DE | ET | OE | ES |
|--|---|--|----|----|----|----|

Inspection Date:
06/11/2012

Document Number:
663300168

Overall Inspection:
Satisfactory

FIELD INSPECTION FORM

| | | | | |
|---------------------|------------------------------|-------------------------|---------------|------------------------------------|
| Location Identifier | Facility ID <u>422543</u> | Loc ID <u>422544</u> | Tracking Type | Inspector Name: <u>SCHURE, KYM</u> |
|---------------------|------------------------------|-------------------------|---------------|------------------------------------|

Operator Information:

OGCC Operator Number: 10245 Name of Operator: SINGLETREE RESOURCES INC

Address: 521 PROGRESS CIRCLE #1

City: CHEYENNE State: WY Zip: 82007

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-----------------------------------|------------------|---------|
| Markve, Tony | (303) 462-3604/ (970) 630-5229 | tony@doubdts.com | |

Compliance Summary:

QtrQtr: SESE Sec: 24 Twp: 11N Range: 54W

Inspector Comment:

MIT inspection (5) year satisfactory

Related Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------------------------------|
| 422543 | WELL | XX | 04/06/2011 | | 075-09396 | Haley Smith 44-24 | <input checked="" type="checkbox"/> |

Equipment: Location Inventory

| | | | |
|------------------------------|-------------------------|----------------------|---------------------------|
| Special Purpose Pits: _____ | Drilling Pits: <u>1</u> | Wells: <u>1</u> | Production Pits: <u>1</u> |
| Condensate Tanks: _____ | Water Tanks: _____ | Separators: <u>1</u> | Electric Motors: _____ |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____ | LACT Unit: _____ | Pump Jacks: <u>1</u> |
| Electric Generators: _____ | Gas Pipeline: _____ | Oil Pipeline: _____ | Water Pipeline: _____ |
| Gas Compressors: _____ | VOC Combustor: _____ | Oil Tanks: <u>2</u> | Dehydrator Units: _____ |
| Multi-Well Pits: _____ | Pigging Station: _____ | Flare: _____ | Fuel Tanks: _____ |

Location

Lease Road:

| Type | Satisfactory/Unsatisfactory | comment | Corrective Action | Date |
|--------|-----------------------------|---------|-------------------|------|
| Access | Satisfactory | | | |

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

| Type | Area | Volume | Corrective action | CA Date |
|--|------|--------|-------------------|---------|
| <input type="checkbox"/> Multiple Spills and Releases? | | | | |

| Equipment: | | | | | |
|-------------------|---|-----------------------------|---------|-------------------|---------|
| Type | # | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| Plunger Lift | 1 | Satisfactory | | | |

| Venting: | |
|-----------------|---------|
| Yes/No | Comment |
| | |

| Flaring: | | | | |
|-----------------|-----------------------------|---------|-------------------|---------|
| Type | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
| | | | | |

Predrill

Location ID: 422544

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____
 Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

| Group | User | Comment | Date |
|-------|----------|--|------------|
| OGLA | allisonr | A reference area map and photographs must be submitted within twelve (12) months of the Form 2A (3/14/2012). | 03/28/2011 |
| OGLA | allisonr | A Form 15 Pit Permit must be approved prior to using a production pit on the location. | 03/28/2011 |

Comment: _____

CA: _____ **Date:** _____

Wildlife BMPs:

Comment: _____

CA: _____ **Date:** _____

Stormwater:

| Erosion BMPs | Present | Other BMPs | Present |
|--------------|---------|------------|---------|
| | | | |

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 422543 Type: WELL API Number: 075-09396 Status: XX Insp. Status: XX

Underground Injection Control

UIC Violation: _____

Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg _____ Previous Test Pressure _____ MPP _____
(e.g. 30 psig or -30" Hg) Inj Zone: _____

TC: Pressure or inches of Hg _____ Previous Test Pressure _____ Last MIT: _____

Brhd: Pressure or inches of Hg _____ Previous Test Pressure _____ AnnMTReq: _____

Comment: _____

Method of Injection: _____

Test Type: 5 Year _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: Pass _____

Comment: Starting casing test pressure 350 psi, (5) min. 340psi, (10) min. 330psi, final casing pressure 320psi. -30 loss during test Within 10 % margin for satisfactory approval.

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1003a. Debris removed? _____ CM _____

CA _____ CA Date _____

Waste Material Onsite? _____ CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? _____ CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? _____ CM _____

CA _____ CA Date _____

Guy line anchors removed? _____ CM _____

CA _____ CA Date _____

Guy line anchors marked? _____ CM _____

CA _____ CA Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

S/U/V: _____ Corrective Date: _____

Comment: _____

CA: _____