

FORM
5Rev
02/08

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Document Number:

400260446

Date Received:

03/29/2012

DRILLING COMPLETION REPORT

This form is to be submitted within 30 days of the setting of production casing, the plugging of a dry hole, the deepening or sidetracking of a well, or any time the wellbore configuration is changed. If the well is deepened or sidetracked a new Form 5 is required. If an attempt has been made to complete/produce a well, then the operator shall submit Form 5A (Completed Interval Report.) If the well has been plugged, a form 6 (Well Abandonment Report) is required.

Completion Type ☒ Final completion ☐ Preliminary completion

1. OGCC Operator Number: 96850

4. Contact Name: Sandra Salazar

2. Name of Operator: WPX ENERGY ROCKY MOUNTAIN LLC

Phone: (303) 629-8456

3. Address: 1001 17TH STREET - SUITE #1200

Fax: (303) 629-8268

City: DENVER State: CO Zip: 80202

5. API Number 05-045-19790-00

6. County: GARFIELD

7. Well Name: Farris

Well Number: RWF 334-31

8. Location: QtrQtr: SESW Section: 31 Township: 6S Range: 94W Meridian: 6

Footage at surface: Distance: 337 feet Direction: FSL Distance: 2403 feet Direction: FWL

As Drilled Latitude: 39.475125 As Drilled Longitude: -107.929333

GPS Data:

Data of Measurement: 12/09/2010 PDOP Reading: 1.2 GPS Instrument Operator's Name: Jack Kirkpatrick

** If directional footage at Top of Prod. Zone Dist.: 619 feet. Direction: FSL Dist.: 1623 feet. Direction: FEL

Sec: 31 Twp: 6S Rng: 94W

** If directional footage at Bottom Hole Dist.: 630 feet. Direction: FSL Dist.: 1605 feet. Direction: FEL

Sec: 31 Twp: 6S Rng: 94W

9. Field Name: RULISON

10. Field Number: 75400

11. Federal, Indian or State Lease Number:

12. Spud Date: (when the 1st bit hit the dirt) 08/18/2011 13. Date TD: 08/28/2011 14. Date Casing Set or D&A: 08/29/2011

15. Well Classification:

☐ Dry ☐ Oil ☒ Gas/Coalbed ☐ Disposal ☐ Stratigraphic ☐ Enhanced Recovery ☐ Storage ☐ Observation

16. Total Depth MD 8146 TVD** 8054 17 Plug Back Total Depth MD 8089 TVD** 7997

18. Elevations GR 5710 KB 5736

One paper copy of all electric and mud logs must be submitted, along with one digital LAS copy as available.

19. List Electric Logs Run:

RPM, MUD, and CBL

20. Casing, Liner and Cement:

CASING

Casing Type	Size of Hole	Size of Casing	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Top	Cmt Bot	Status
CONDUCTOR	24	18	48	0	79	30	0	79	VISU
SURF	13+1/2	9+5/8	32.3	0	1,133	320	0	1,133	VISU
1ST	8+3/4	4+1/2	11.6	0	8,126	1,270	3,300	8,126	CBL

STAGE/TOP OUT/REMEDIAL CEMENT

Cement work date: _____

Method used	String	Cementing tool setting/pref depth	Cement volume	Cement top	Cement bottom

Details of work:

21. Formation log intervals and test zones:

FORMATION LOG INTERVALS AND TEST ZONES

FORMATION NAME	Measured Depth		Check if applies		COMMENTS (All DST and Core Analyses must be submitted to COGCC)
	Top	Bottom	DST	Cored	
WASATCH	2,189		<input type="checkbox"/>	<input type="checkbox"/>	
MESAVERDE	4,635		<input type="checkbox"/>	<input type="checkbox"/>	
CAMEO	7,128		<input type="checkbox"/>	<input type="checkbox"/>	
ROLLINS	8,072		<input type="checkbox"/>	<input type="checkbox"/>	

Comment:

The "as-drilled" GPS information provided is actual data of the existing well conductor location prior to the big rig spud date.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Sandra Salazar

Title: Permit Technician II Date: 3/29/2012 Email: sandra.salazar@wpenergy.com

Attachment Check List

Att Doc Num	Document Name	attached ?			
<u>Attachment Checklist</u>					
400260528	CMT Summary *	Yes	<input checked="" type="checkbox"/>	No	<input type="checkbox"/>
	Core Analysis	Yes	<input type="checkbox"/>	No	<input checked="" type="checkbox"/>
2288715	Directional Survey **	Yes	<input checked="" type="checkbox"/>	No	<input type="checkbox"/>
	DST Analysis	Yes	<input type="checkbox"/>	No	<input checked="" type="checkbox"/>
	Logs	Yes	<input type="checkbox"/>	No	<input checked="" type="checkbox"/>
	Other	Yes	<input type="checkbox"/>	No	<input checked="" type="checkbox"/>
<u>Other Attachments</u>					
400260446	FORM 5 SUBMITTED	Yes	<input checked="" type="checkbox"/>	No	<input type="checkbox"/>
400260486	DIRECTIONAL DATA	Yes	<input checked="" type="checkbox"/>	No	<input type="checkbox"/>
400266653	DIRECTIONAL DATA	Yes	<input checked="" type="checkbox"/>	No	<input type="checkbox"/>

General Comments

User Group	Comment	Comment Date
Permit	Off hold. Per operators email attached directional survey and a comment about the GPS date.	6/11/2012 12:09:53 PM
Permit	On hold. Requested PDF directional survey, paper RPM log, and as built GPS explanation. Added Mud to list of logs run.	3/7/2012 7:40:17 AM

Total: 2 comment(s)