

**FORM**  
**5**  
Rev  
02/08

**State of Colorado**  
**Oil and Gas Conservation Commission**  
1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Document Number:  
400267705  
  
Date Received:  
04/03/2012

**DRILLING COMPLETION REPORT**

This form is to be submitted within 30 days of the setting of production casing, the plugging of a dry hole, the deepening or sidetracking of a well, or any time the wellbore configuration is changed. If the well is deepened or sidetracked a new Form 5 is required. If an attempt has been made to complete/produce a well, then the operator shall submit Form 5A (Completed Interval Report.) If the well has been plugged, a form 6 (Well Abandonment Report) is required.

Completion Type  Final completion  Preliminary completion

1. OGCC Operator Number: 96850 4. Contact Name: Angela Neifert-Kraiser  
2. Name of Operator: WPX ENERGY ROCKY MOUNTAIN LLC Phone: (303) 606-4398  
3. Address: 1001 17TH STREET - SUITE #1200 Fax: \_\_\_\_\_  
City: DENVER State: CO Zip: 80202

5. API Number 05-045-19730-00 6. County: GARFIELD  
7. Well Name: ExxonMobil Well Number: GM 23-27  
8. Location: QtrQtr: SESW Section: 27 Township: 6S Range: 96W Meridian: 6  
Footage at surface: Distance: 1140 feet Direction: FSL Distance: 2509 feet Direction: FWL  
As Drilled Latitude: 39.491060 As Drilled Longitude: -108.095195

GPS Data:  
Date of Measurement: 11/01/2010 PDOP Reading: 3.5 GPS Instrument Operator's Name: Jack Kirkpatrick

\*\* If directional footage at Top of Prod. Zone Dist.: 2484 feet. Direction: FSL Dist.: 1834 feet. Direction: FWL

Sec: 27 Twp: 6s Rng: 96w

\*\* If directional footage at Bottom Hole Dist.: 2469 feet. Direction: FSL Dist.: 1828 feet. Direction: FWL

Sec: 23 Twp: 6s Rng: 96w

9. Field Name: GRAND VALLEY 10. Field Number: 31290

11. Federal, Indian or State Lease Number: COC 034553A

12. Spud Date: (when the 1st bit hit the dirt) 04/22/2011 13. Date TD: 04/27/2011 14. Date Casing Set or D&A: 04/28/2011

15. Well Classification:  
 Dry  Oil  Gas/Coalbed  Disposal  Stratigraphic  Enhanced Recovery  Storage  Observation

16. Total Depth MD 7293 TVD\*\* 7003 17 Plug Back Total Depth MD 7237 TVD\*\* 6947

18. Elevations GR 5604 KB 5628 One paper copy of all electric and mud logs must be submitted, along with one digital LAS copy as available.

19. List Electric Logs Run:  
CBL, MUD, and Reservoir Performance Monitor (RPM)

20. Casing, Liner and Cement:

**CASING**

Casing Type	Size of Hole	Size of Casing	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Top	Cmt Bot	Status
CONDUCTOR	26	18	48	0	43	16	0	43	VISU
SURF	13+1/2	9+5/8	32.3	0	1,480	355	0	1,480	VISU
1ST	7+7/8	4+1/2	11.6	0	7,272	1,000	2,820	7,272	CBL

**STAGE/TOP OUT/REMEDIAL CEMENT**

Cement work date: \_\_\_\_\_

Method used	String	Cementing tool setting/pref depth	Cement volume	Cement top	Cement bottom

Details of work:

21. Formation log intervals and test zones:

**FORMATION LOG INTERVALS AND TEST ZONES**

FORMATION NAME	Measured Depth		Check if applies		COMMENTS (All DST and Core Analyses must be submitted to COGCC)
	Top	Bottom	DST	Cored	
WASATCH G	2,152		<input type="checkbox"/>	<input type="checkbox"/>	
MESAVERDE	4,092		<input type="checkbox"/>	<input type="checkbox"/>	
CAMEO	6,729		<input type="checkbox"/>	<input type="checkbox"/>	
ROLLINS	7,166		<input type="checkbox"/>	<input type="checkbox"/>	

Comment:

: the "as-drilled" GPS information provided is actual data of the existing well conductor location prior to the big rig spud date

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Angela Neifert-Kraiser

Title: Regulatory Specialist Date: 4/3/2012 Email: Angela.Neifert-Kraiser@WPXEnergy.com

**Attachment Check List**

Att Doc Num	Document Name	attached ?	
<b>Attachment Checklist</b>			
400267903	CMT Summary *	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
	Core Analysis	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
2288701	Directional Survey **	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
	DST Analysis	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
	Logs	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
	Other	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
<b>Other Attachments</b>			
400267705	FORM 5 SUBMITTED	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
400267900	DIRECTIONAL DATA	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
400267902	WELLBORE DIAGRAM	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>

**General Comments**

User Group	Comment	Comment Date
Permit	Off Hold. Per operator attached directional survey, corrected KB elevation, and input a comment regarding the GPS information. Paper RPM log has been requested.	6/7/2012 10:02:48 AM
Permit	On hold. Requested PDF directional survey, KB elevation, paper RPM log, and as built GPS explanation. Added Mud to list of logs run.	3/7/2012 7:12:33 AM

Total: 2 comment(s)