

Document Number:
400264107

Date Received:
03/22/2012

DRILLING COMPLETION REPORT

This form is to be submitted within 30 days of the setting of production casing, the plugging of a dry hole, the deepening or sidetracking of a well, or any time the wellbore configuration is changed. If the well is deepened or sidetracked a new Form 5 is required. If an attempt has been made to complete/produce a well, then the operator shall submit Form 5A (Completed Interval Report.) If the well has been plugged, a form 6 (Well Abandonment Report) is required.

Completion Type Final completion Preliminary completion

1. OGCC Operator Number: 100185 4. Contact Name: Marina Ayala
 2. Name of Operator: ENCANA OIL & GAS (USA) INC Phone: (720) 876-5905
 3. Address: 370 17TH ST STE 1700 Fax: (720) 876-6905
 City: DENVER State: CO Zip: 80202-

5. API Number 05-045-18702-00 6. County: GARFIELD
 7. Well Name: N. Parachute Well Number: MF11A-16 H17 69
 8. Location: QtrQtr: SENE Section: 17 Township: 6S Range: 96W Meridian: 6
 Footage at surface: Distance: 1582 feet Direction: FNL Distance: 294 feet Direction: FEL
 As Drilled Latitude: 39.527318 As Drilled Longitude: -108.123581

GPS Data:
 Date of Measurement: 09/09/2010 PDOP Reading: 2.4 GPS Instrument Operator's Name: Brian Baker

** If directional footage at Top of Prod. Zone Dist.: 2833 feet. Direction: FNL Dist.: 1531 feet. Direction: FWL
 Sec: 16 Twp: 6S Rng: 96W
 ** If directional footage at Bottom Hole Dist.: 2844 feet. Direction: FNL Dist.: 1492 feet. Direction: FWL
 Sec: 16 Twp: 6S Rng: 96W

9. Field Name: GRAND VALLEY 10. Field Number: 31290
 11. Federal, Indian or State Lease Number: _____

12. Spud Date: (when the 1st bit hit the dirt) 02/12/2011 13. Date TD: 02/21/2011 14. Date Casing Set or D&A: 02/22/2011

15. Well Classification:
 Dry Oil Gas/Coalbed Disposal Stratigraphic Enhanced Recovery Storage Observation

16. Total Depth MD 7830 TVD** 7230 17 Plug Back Total Depth MD 7799 TVD** 7199

18. Elevations GR 5654 KB 5676 One paper copy of all electric and mud logs must be submitted, along with one digital LAS copy as available.

19. List Electric Logs Run:
RST, CBL (included in Triple Combo), EDR

20. Casing, Liner and Cement:

CASING

Casing Type	Size of Hole	Size of Casing	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Top	Cmt Bot	Status
CONDUCTOR	26	16	42	0	160	200	0	160	CALC
SURF	12+1/4	9+5/8	36	0	1,410	328	0	1,410	CALC
1ST	8+3/4	4+1/2	11.60	0	7,824	1,117	2,970	7,830	CBL

STAGE/TOP OUT/REMEDIAL CEMENT

Cement work date: _____

Method used	String	Cementing tool setting/pref depth	Cement volume	Cement top	Cement bottom

Details of work:

21. Formation log intervals and test zones:

FORMATION LOG INTERVALS AND TEST ZONES

FORMATION NAME	Measured Depth		Check if applies		COMMENTS (All DST and Core Analyses must be submitted to COGCC)
	Top	Bottom	DST	Cored	
WILLIAMS FORK	4,546	7,733	<input type="checkbox"/>	<input type="checkbox"/>	
ROLLINS	7,734	7,830	<input type="checkbox"/>	<input type="checkbox"/>	

Comment:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Marina Ayala

Title: Permitting Technician Date: 3/22/2012 Email: marina.ayala@encana.com

Attachment Check List

Att Doc Num	Document Name	attached ?	
<u>Attachment Checklist</u>			
400264161	CMT Summary *	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
	Core Analysis	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
2288703	Directional Survey **	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
	DST Analysis	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
	Logs	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
	Other	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
<u>Other Attachments</u>			
400264107	FORM 5 SUBMITTED	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
400264113	MUD	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
400264114	TRIPLE COMBINATION	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
400264155	CEMENT BOND	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
400264165	DIRECTIONAL DATA	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Permit	Off Hold. Per operator corrected directional survey and BHL.	3/7/2012 2:52:21 PM
Permit	On hold. Requested verification of BHL. Missing directional survey attachment. Added EDR to logs run.	6/7/2012 12:41:24 PM

Total: 2 comment(s)