

FORM  
5  
Rev  
02/08

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Document Number:  
400288991

Date Received:  
05/25/2012

DRILLING COMPLETION REPORT

This form is to be submitted within 30 days of the setting of production casing, the plugging of a dry hole, the deepening or sidetracking of a well, or any time the wellbore configuration is changed. If the well is deepened or sidetracked a new Form 5 is required. If an attempt has been made to complete/produce a well, then the operator shall submit Form 5A (Completed Interval Report.) If the well has been plugged, a form 6 (Well Abandonment Report) is required.

Completion Type  Final completion  Preliminary completion

1. OGCC Operator Number: 96850  
2. Name of Operator: WPX ENERGY ROCKY MOUNTAIN LLC  
3. Address: 1001 17TH STREET - SUITE #1200  
City: DENVER State: CO Zip: 80202  
4. Contact Name: Angela Neifert-Kraiser  
Phone: (303) 606-4398  
Fax:

5. API Number 05-045-20468-00  
6. County: GARFIELD  
7. Well Name: ExxonMobil  
Well Number: GM 533-23  
8. Location: QtrQtr: NWSW Section: 23 Township: 6S Range: 96W Meridian: 6  
Footage at surface: Distance: 1816 feet Direction: FSL Distance: 869 feet Direction: FWL  
As Drilled Latitude: 39.506254 As Drilled Longitude: -108.083053

GPS Data:  
Date of Measurement: 04/13/2011 PDOP Reading: 3.2 GPS Instrument Operator's Name: Jack Kirkpatrick

\*\* If directional footage at Top of Prod. Zone Dist.: 1502 feet. Direction: FSL Dist.: 2297 feet. Direction: FEL  
Sec: 23 Twp: 6s Rng: 96w  
\*\* If directional footage at Bottom Hole Dist.: 1488 feet. Direction: FSL Dist.: 2312 feet. Direction: FEL  
Sec: 23 Twp: 6s Rng: 96w

9. Field Name: GRAND VALLEY 10. Field Number: 31290  
11. Federal, Indian or State Lease Number:

12. Spud Date: (when the 1st bit hit the dirt) 10/06/2011 13. Date TD: 10/12/2011 14. Date Casing Set or D&A: 10/13/2012

15. Well Classification:  
 Dry  Oil  Gas/Coalbed  Disposal  Stratigraphic  Enhanced Recovery  Storage  Observation

16. Total Depth MD 8010 TVD\*\* 7635 17 Plug Back Total Depth MD 7965 TVD\*\* 7590

18. Elevations GR 5974 KB 6000  
One paper copy of all electric and mud logs must be submitted, along with one digital LAS copy as available.

19. List Electric Logs Run:  
CBL, XMAC, Mud, and Reservoir Performance Monitor (RPM)

20. Casing, Liner and Cement:

CASING

Casing Type	Size of Hole	Size of Casing	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Top	Cmt Bot	Status
CONDUCTOR	26	18	48	0	80	24	0	80	VISU
SURF	13+1/2	9+5/8	32.3	0	1,155	320	0	1,155	VISU
1ST	7+7/8	4+1/2	11.6	0	7,999	1,015	4,050	7,999	CBL

**STAGE/TOP OUT/REMEDIAL CEMENT**

Cement work date: \_\_\_\_\_

Method used	String	Cementing tool setting/pref depth	Cement volume	Cement top	Cement bottom

Details of work:

21. Formation log intervals and test zones:

**FORMATION LOG INTERVALS AND TEST ZONES**

FORMATION NAME	Measured Depth		Check if applies		COMMENTS (All DST and Core Analyses must be submitted to COGCC)
	Top	Bottom	DST	Cored	
WASATCH G	2,592		<input type="checkbox"/>	<input type="checkbox"/>	
MESAVERDE	4,705		<input type="checkbox"/>	<input type="checkbox"/>	
CAMEO	7,360		<input type="checkbox"/>	<input type="checkbox"/>	
ROLLINS	7,915		<input type="checkbox"/>	<input type="checkbox"/>	

Comment:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Angela Neifert-Kraiser

Title: Regulatory Specialist Date: 5/25/2012 Email: Angela.Neifert-Kraiser@wpenergy.com

**Attachment Check List**

Att Doc Num	Document Name	attached ?	
<b>Attachment Checklist</b>			
400288999	CMT Summary *	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
	Core Analysis	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
2288713	Directional Survey **	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
	DST Analysis	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
	Logs	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
	Other	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
<b>Other Attachments</b>			
400288991	FORM 5 SUBMITTED	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
400288996	DIRECTIONAL DATA	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
400288997	WELLBORE DIAGRAM	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>

**General Comments**

<b>User Group</b>	<b>Comment</b>	<b>Comment Date</b>
Permit	Off hold. Input correct elevations per operators email.	6/11/2012 12:02:20 PM
Permit	On Hold. Need verification of GR and KB elevation. Requested paper copy of RPM and XMAC log.	5/8/2012 8:05:49 AM

Total: 2 comment(s)