

**FORM  
INSP**Rev  
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



|    |    |    |    |
|----|----|----|----|
| DE | ET | OE | ES |
|----|----|----|----|

Inspection Date:

06/13/2012

Document Number:

663300172

Overall Inspection:

Satisfactory**FIELD INSPECTION FORM**

|                     |               |               |               |                    |
|---------------------|---------------|---------------|---------------|--------------------|
| Location Identifier | Facility ID   | Loc ID        | Tracking Type | Inspector Name:    |
|                     | <u>225210</u> | <u>313806</u> |               | <u>SCHURE, KYM</u> |

**Operator Information:**OGCC Operator Number: 10203 Name of Operator: BLACK RAVEN ENERGY INCAddress: 1331 17TH STREET - #350City: DENVERState: COZip: 80202**Contact Information:**

| Contact Name   | Phone | Email                         | Comment |
|----------------|-------|-------------------------------|---------|
| Hataway, Billy |       | bhataway@blackravenenergy.com |         |

**Compliance Summary:**QtrQtr: NESE Sec: 30 Twp: 2N Range: 57W

| Insp. Date | Doc Num   | Insp. Type | Insp Status | Satisfactory /Unsatisfactory | PA P/F/I | Pas/Fail (P/F) | Violation (Y/N) |
|------------|-----------|------------|-------------|------------------------------|----------|----------------|-----------------|
| 01/27/2009 | 200203243 | ID         | TA          | U                            |          |                | Y               |
| 05/27/2004 | 200055279 | PR         | TA          | S                            |          | P              | N               |

**Inspector Comment:**

Spoke to company pumper, recently took over responsibilities, working on bringing location into compliance. Concrete pumping unit pad remains, pump jack and equipment removed.

**Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name |                                     |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------------------------------|
| 225210      | WELL | SI     | 08/27/1998  | OW         | 087-05610 | GLENN I-3     | <input checked="" type="checkbox"/> |

**Equipment:****Location Inventory**

|                              |                        |                     |                         |
|------------------------------|------------------------|---------------------|-------------------------|
| Special Purpose Pits: _____  | Drilling Pits: _____   | Wells: _____        | Production Pits: _____  |
| Condensate Tanks: _____      | Water Tanks: _____     | Separators: _____   | Electric Motors: _____  |
| Gas or Diesel Mortors: _____ | Cavity Pumps: _____    | LACT Unit: _____    | Pump Jacks: _____       |
| Electric Generators: _____   | Gas Pipeline: _____    | Oil Pipeline: _____ | Water Pipeline: _____   |
| Gas Compressors: _____       | VOC Combustor: _____   | Oil Tanks: _____    | Dehydrator Units: _____ |
| Multi-Well Pits: _____       | Pigging Station: _____ | Flare: _____        | Fuel Tanks: _____       |

**Location****Lease Road:**

| Type   | Satisfactory/Unsatisfactory | comment | Corrective Action | Date |
|--------|-----------------------------|---------|-------------------|------|
| Access | Satisfactory                |         |                   |      |

Emergency Contact Number: (S/U/V) Satisfactory

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

|                           |                             |  |                   |            |
|---------------------------|-----------------------------|--|-------------------|------------|
| <b>Good Housekeeping:</b> |                             |  |                   |            |
| Type                      | Satisfactory/Unsatisfactory | Comment                                    | Corrective Action | CA Date    |
| DEBRIS                    | Unsatisfactory              | Pipe fittings laying on ground at wellhead | Remove fittings   | 08/31/2012 |

|  |      |        |                   |         |
|--|------|--------|-------------------|---------|
| <b>Spills:</b>   |      |        |                   |         |
| Type   | Area | Volume | Corrective action | CA Date |
| <input type="checkbox"/> Multiple Spills and Releases? |      |        |                   |         |

|                   |   |                             |         |         |
|-------------------|---|-----------------------------|---------|---------|
| <b>Equipment:</b> |   |                             |         |         |
| Type              | # | Satisfactory/Unsatisfactory | Comment | CA Date |
|                   |   |                             |         |         |

|                 |         |  |
|-----------------|---------|--|
| <b>Venting:</b> |         |  |
| Yes/No          | Comment |  |
|                 |         |  |

|                 |                             |         |                   |         |
|-----------------|-----------------------------|---------|-------------------|---------|
| <b>Flaring:</b> |                             |         |                   |         |
| Type            | Satisfactory/Unsatisfactory | Comment | Corrective Action | CA Date |
|                 |                             |         |                   |         |

**Predrill**

Location ID: 313806

**Site Preparation:**

Lease Road Adeq.: \_\_\_\_\_

Pads: \_\_\_\_\_

Soil Stockpile: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_ CDP Num.: \_\_\_\_\_

**Form 2A COAs:****Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Wildlife BMPs:****Comment:** \_\_\_\_\_**CA:** \_\_\_\_\_ **Date:** \_\_\_\_\_**Stormwater:**

|              |         |            |         |
|--------------|---------|------------|---------|
| Erosion BMPs | Present | Other BMPs | Present |
|              |         |            |         |

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Comments: Erosion BMPs: \_\_\_\_\_

Other BMPs: \_\_\_\_\_

**Comment:** \_\_\_\_\_**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Facility**

Facility ID: 225210 Type: WELL API Number: 087-05610 Status: SI Insp. Status: SI

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_ Description: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Inspector Name: SCHURE, KYM

|   |  |                              |            |
|---|--|------------------------------|------------|
| Comment: <input style="width: 700px;" type="text"/>         |  |                              |            |
| Corrective Action: _____                                    |  | Date: _____                  |            |
| Reportable: _____   | GPS: Lat _____                                     | Long _____                   |            |
| Proximity to Surface Water: _____                           |  | Depth to Ground Water: _____ |            |
| <b>Water Well:</b>  |  |                              |            |
|   |  | Lat _____                    | Long _____ |
| DWR Receipt Num: _____                                      | Owner Name: _____                                  | GPS : _____                  |            |
| <b>Field Parameters:</b>                                    |  |                              |            |
| <input style="width: 300px;" type="text"/>                  |  |                              |            |
| Sample Location: <input style="width: 400px;" type="text"/> |  |                              |            |
| Emission Control Burner (ECB): _____                        |  |                              |            |
| Comment: _____  |  |                              |            |
| Pilot: _____  | Wildlife Protection Devices (fired vessels): _____ |                              |            |

**Reclamation - Storm Water - Pit**

**Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment:

1003a. Debris removed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Waste Material Onsite? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors removed? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_ CM \_\_\_\_\_

CA \_\_\_\_\_ CA Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**

Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Inspector Name: SCHURE, KYM

Non-Cropland

Top soil replaced \_\_\_\_\_

Recontoured \_\_\_\_\_

80% Revegetation \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment: \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_

Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_

Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_

No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_

Contoured \_\_\_\_\_

Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_

Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_

Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_

Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_

Subsidence \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date \_\_\_\_\_

Overall Final Reclamation

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

S/U/V: \_\_\_\_\_

Corrective Date: \_\_\_\_\_

Comment: \_\_\_\_\_

CA: \_\_\_\_\_