

FORM 5A

Rev 06/12

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



Table with columns DE, ET, OE, ES

Document Number: 400271751

Date Received: 04/12/2012

COMPLETED INTERVAL REPORT

The completed interval Report, Form 5A, shall be submitted within thirty (30) days of completing a formation (successful or not), when a formation is temporarily abandoned or permanently abandoned, for a recompletion, reperforation or restimulation, or when a formation is commingled. Fill out a section for each formation. Attach as many pages as required to fully describe the work. List in order of completion.

1. OGCC Operator Number: 96850
2. Name of Operator: WPX ENERGY ROCKY MOUNTAIN LLC
3. Address: 1001 17TH STREET - SUITE #1200
City: DENVER State: CO Zip: 80202
4. Contact Name: Julie Lawson
Phone: (303) 260-4533
Fax: (303) 629-8268

5. API Number 05-045-20472-00
6. County: GARFIELD
7. Well Name: ExxonMobil
Well Number: GM 412-23
8. Location: QtrQtr: NWSW Section: 23 Township: 6S Range: 96W Meridian: 6
9. Field Name: GRAND VALLEY Field Code: 31290

Completed Interval

FORMATION: WILLIAMS FORK - CAMEO Status: PRODUCING Treatment Type:

Treatment Date: 12/13/2011 End Date: Date of First Production this formation: 12/29/2011

Perforations Top: 5978 Bottom: 7694 No. Holes: 131 Hole size: 0.35

Provide a brief summary of the formation treatment: Open Hole: []

2499 gal 7.5% HCL; 895000# 30/50 Sand; 40517 BBL's Slickwater (Summary).

This formation is commingled with another formation: [] Yes [X] No

Total fluid used in treatment (bbl): Max pressure during treatment (psi):

Total gas used in treatment (mcf): Fluid density at initial fracture (lbs/gal):

Type of gas used in treatment: Number of staged intervals:

Total acid used in treatment (bbl): Max frac gradient (psi/ft):

Recycled water used in treatment (bbl): Flowback volume recovered (bbl):

Fresh water used in treatment (bbl): Disposition method for flowback:

Total proppant used (lbs): Rule 805 green completion techniques were utilized: []

Reason why green completion not utilized:

Fracture stimulations must be reported on FracFocus.org

Test Information:

Date: 02/22/2012 Hours: 24 Bbl oil: 0 Mcf Gas: 1425 Bbl H2O: 0

Calculated 24 hour rate: Bbl oil: 0 Mcf Gas: 1425 Bbl H2O: 0 GOR: 0

Test Method: flowing Casing PSI: 2113 Tubing PSI: 1917 Choke Size: 11/64

Gas Disposition: SOLD Gas Type: DRY Btu Gas: 1022 API Gravity Oil: 0

Tubing Size: 2 + 3/8 Tubing Setting Depth: 7522 Tbg setting date: 02/06/2012 Packer Depth:

Reason for Non-Production:

Date formation Abandoned: Squeeze: [] Yes [] No If yes, number of sacks cmt

Bridge Plug Depth: Sacks cement on top:

Comment:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Julie Lawson

Title: Permit Tech II Date: 4/12/2012 Email julie.lawson@wpenergy.com
:

Attachment Check List

Att Doc Num	Name
400271751	FORM 5A SUBMITTED
400271760	WELLBORE DIAGRAM

Total Attach: 2 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Permit	Input 24 hour flow rate based on test data.	6/15/2012 9:55:34 AM

Total: 1 comment(s)