

Inspector Name: EDELEN, RANDY

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

06/20/2012

Document Number:

663400487

Overall Inspection:

Unsatisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name: EDELEN, RANDY
	202996	320201		

Operator Information:

OGCC Operator Number: 79905 Name of Operator: SMITH OIL PROPERTIES INC

Address: 518 17TH ST STE 360

City: DENVER State: CO Zip: 80202-

Contact Information:

Contact Name	Phone	Email	Comment
RAMOS, MARTHA		martha.ramos@state.co.us	

Compliance Summary:

QtrQtr: SWSE Sec: 17 Twp: 2S Range: 61W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
05/18/2009	200219681	CC	PA	S			N
03/07/2006	200088901	PR	SI	U		F	N
01/07/1999	500132905	PR	SI			P	N

Inspector Comment:

Inspection of a PA from 5/19/2009

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
202996	WELL	PA	05/19/2009		001-08402	PANAMA-UPRR 92-1	<input checked="" type="checkbox"/>

Equipment:**Location Inventory**

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Emergency Contact Number: (S/U/V) _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:

Type	Area	Volume	Corrective action	CA Date
------	------	--------	-------------------	---------

☐ Multiple Spills and Releases?

Venting:		
Yes/No	Comment	

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 320201

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Comment:** _____**CA:** _____**Date:** _____**Wildlife BMPs:****Comment:** _____**CA:** _____**Date:** _____**Stormwater:**

Erosion BMPs	Present	Other BMPs	Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment: _____**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:**Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:**

Inspector Name: EDELEN, RANDY

Facility

Facility ID: 202996 Type: WELL API Number: 001-08402 Status: PA Insp. Status: PA

Environmental

Spills/Releases:

Type of Spill: Description: Estimated Spill Volume:
Comment:
Corrective Action: Date:
Reportable: GPS: Lat Long
Proximity to Surface Water: Depth to Ground Water:

Water Well:

Lat Long
DWR Receipt Num: Owner Name: GPS :

Field Parameters:

Sample Location:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use:

Comment:

1003a. Debris removed? CM
CA CA Date
Waste Material Onsite? CM
CA CA Date
Unused or unneeded equipment onsite? CM
CA CA Date
Pit, cellars, rat holes and other bores closed? CM
CA CA Date
Guy line anchors removed? CM
CA CA Date
Guy line anchors marked? CM
CA CA Date

1003b. Area no longer in use? Production areas stabilized ?

1003c. Compacted areas have been cross ripped?

1003d. Drilling pit closed? Subsidence over on drill pit?

Inspector Name: EDELEN, RANDY

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: Meter and meter run, risers, deadmen all left on location

Well plugged _____ Pit mouse/rat holes, cellars backfilled Pass

Debris removed Fail No disturbance /Location never built _____

Access Roads Regraded Pass Contoured Pass Culverts removed Pass

Gravel removed Fail

Location and associated production facilities reclaimed Fail Locations, facilities, roads, recontoured Fail

Compaction alleviation Fail Dust and erosion control Pass

Non cropland: Revegetated 80% _____ Cropland: perennial forage Fail

Weeds present Pass Subsidence Fail

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation Fail

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: Satisfactory Corrective Date: _____

Comment: _____

CA: _____