

FORM  
5

Rev  
02/08

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Document Number:

400209138

Date Received:

04/25/2012

DRILLING COMPLETION REPORT

This form is to be submitted within 30 days of the setting of production casing, the plugging of a dry hole, the deepening or sidetracking of a well, or any time the wellbore configuration is changed. If the well is deepened or sidetracked a new Form 5 is required. If an attempt has been made to complete/produce a well, then the operator shall submit Form 5A (Completed Interval Report.) If the well has been plugged, a form 6 (Well Abandonment Report) is required.

Completion Type  Final completion  Preliminary completion

1. OGCC Operator Number: 95960 4. Contact Name: Jim Horner  
2. Name of Operator: WEXPRO COMPANY Phone: (307) 352-7523  
3. Address: P O BOX 45003 Fax: (307) 352-7500  
City: SALT LAKE CITY State: UT Zip: 84145-

5. API Number 05-081-07628-00 6. County: MOFFAT  
7. Well Name: GOVERNMENT Well Number: 15  
8. Location: QtrQtr: SESW Section: 5 Township: 11N Range: 97W Meridian: 6  
Footage at surface: Distance: 161 feet Direction: FSL Distance: 1444 feet Direction: FWL  
As Drilled Latitude: 40.935451 As Drilled Longitude: -108.319913

GPS Data:  
Date of Measurement: 04/07/2011 PDOP Reading: 1.7 GPS Instrument Operator's Name: M.L. Brown

\*\* If directional footage at Top of Prod. Zone Dist.: 119 feet. Direction: FNL Dist.: 2396 feet. Direction: FEL  
Sec: 8 Twp: 11N Rng: 97W  
\*\* If directional footage at Bottom Hole Dist.: 95 feet. Direction: FNL Dist.: 2428 feet. Direction: FEL  
Sec: 8 Twp: 11N Rng: 97W

9. Field Name: POWDER WASH 10. Field Number: 69800  
11. Federal, Indian or State Lease Number: COD0040866

12. Spud Date: (when the 1st bit hit the dirt) 10/24/2010 13. Date TD: 12/09/2010 14. Date Casing Set or D&A: 12/11/2010

15. Well Classification:  
 Dry  Oil  Gas/Coalbed  Disposal  Stratigraphic  Enhanced Recovery  Storage  Observation

16. Total Depth MD 9921 TVD\*\* 9664 17 Plug Back Total Depth MD 9873 TVD\*\* 9616

18. Elevations GR 7037 KB 28  
One paper copy of all electric and mud logs must be submitted, along with one digital LAS copy as available.

19. List Electric Logs Run:  
CNL-FDL, DIL, GR, CBL

20. Casing, Liner and Cement:

CASING

Casing Type	Size of Hole	Size of Casing	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Top	Cmt Bot	Status
CONDUCTOR	26	20	42	0	80	150	0	80	CALC
SURF	12+1/4	9+5/8	36	0	1,563	835	0	1,563	VISU
1ST	7+7/8	4+1/2	13.5	0	9,920	2,170	0	9,920	VISU

**STAGE/TOP OUT/REMEDIAL CEMENT**

Cement work date: \_\_\_\_\_

Method used	String	Cementing tool setting/perf depth	Cement volume	Cement top	Cement bottom

Details of work:

21. Formation log intervals and test zones:

**FORMATION LOG INTERVALS AND TEST ZONES**

FORMATION NAME	Measured Depth		Check if applies		COMMENTS (All DST and Core Analyses must be submitted to COGCC)
	Top	Bottom	DST	Cored	
WASATCH	0		<input type="checkbox"/>	<input type="checkbox"/>	
FORT UNION	6,030		<input type="checkbox"/>	<input type="checkbox"/>	
LANCE	9,669		<input type="checkbox"/>	<input type="checkbox"/>	

Comment:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Chris Beilby

Title: Completion Manager Date: 4/25/2012 Email: chris.beilby@questar.com

**Attachment Check List**

Att Doc Num	Document Name	attached ?	
<b>Attachment Checklist</b>			
	CMT Summary *	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
	Core Analysis	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
2288755	Directional Survey **	Yes <input checked="" type="checkbox"/>	No <input type="checkbox"/>
	DST Analysis	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
	Logs	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>
	Other	Yes <input type="checkbox"/>	No <input checked="" type="checkbox"/>

**General Comments**

User Group	Comment	Comment Date
Permit	On hold. Directional survey does not match drilling tab. Missing directional template. Cement Job summary is on doc #2505891	6/20/2012 8:45:58 AM

Total: 1 comment(s)