

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

07/09/2012

Document Number:

663300290

Overall Inspection:

Unsatisfactory**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name:
	<u>219143</u>	<u>312158</u>		<u>SCHURE, KYM</u>

Operator Information:

OGCC Operator Number:	<u>10380</u>	Name of Operator:	<u>BENCHMARK ENERGY LLC</u>
Address:	<u>PO BOX 8747</u>		
City:	<u>PRATT</u>	State:	<u>KS</u>
		Zip:	<u>67124</u>

Contact Information:

Contact Name	Phone	Email	Comment
Nash, Jerry	(620) 672-9700	lferrell@profsecservices.com	

Compliance Summary:

QtrQtr:	<u>NENE</u>	Sec:	<u>12</u>	Twp:	<u>8N</u>	Range:	<u>54W</u>
Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
11/21/2011	664000148	IJ	AC	S	P		N
10/11/2011	200324950	MI	SI	U			Y
06/16/2011	200312771	MI	AC	U			Y
07/26/2010	200263867	RT	TA	S			N
07/19/2010	200264964	SR	AC	S	I		N
01/27/2010	200229253	MI	SI	S			N
12/21/2009	200225699	MI	SI	U			Y
07/23/2009	200215464	MI	SI	U			Y
07/22/2009	200215463	MI	SI	U			Y
04/17/2008	200130595	MI	AC	U			Y
06/20/2007	200115791	MI	AC	S		P	N
06/08/2006	200091673	RT	AC	S		P	N
07/05/2005	200074145	RT	AC	S		P	N
06/15/2004	200055914	RT		S		P	N
04/02/2003	200037008	RT	AC	S		P	N
08/02/2002	200029314	MI	SI	S		P	N
07/17/2002	200028858	MI	AC	U		F	Y
08/23/2001	200019591	RT	AC	S		P	N
08/04/2000	200008426	RT	AC	S		P	N

Inspector Comment:

Incorrect/Invalid signage at wellhead. Incorrect/Invalid emergency contact information. Surface owner expressed dissatisfaction with cattle gates being left open. Routine UIC - Satisfactory

Related Facilities:

Inspector Name: SCHURE, KYM

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
219143	WELL	IJ	06/24/2010	ERIW	075-05972	NW GRAYLIN D-SAND UNIT 20-W	<input checked="" type="checkbox"/>

Equipment:

Location Inventory

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Signs/Marker:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Unsatisfactory	Incorrect/Invalid signage at wellhead.	Install sign to comply with rule 210.b.	07/23/2012

Emergency Contact Number: (S/U/V) Unsatisfactory Corrective Date: 07/23/2012

Comment: Incorrect/Invalid emergency contact information.
Emergency contact must have live attendant 24-7-365 to answer emergency calls.

Corrective Action: Install correct emergency contact information with 24-7-365 attendance.

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Venting:		
Yes/No	Comment	

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 312158

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Comment:****CA:****Date:****Wildlife BMPs:****Comment:****CA:****Date:****Stormwater:**

Erosion BMPs

Present

Other BMPs

Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment:**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:**Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Facility**

Facility ID: 219143 Type: WELL API Number: 075-05972 Status: IJ Insp. Status: IJ

Underground Injection Control

UIC Violation: _____

Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg _____ Previous Test Pressure _____ MPP _____
 (e.g. 30 psig or -30" Hg) Inj Zone: DSND

TC: Pressure or inches of Hg _____ Previous Test Pressure _____ Last MIT: 11/21/2011

Brhd: Pressure or inches of Hg _____ Previous Test Pressure _____ AnnMTReq: _____

Comment: No leaks indicated at wellhead. Routine UIC Inspection - Satisfactory

Method of Injection: _____

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? Pass CM _____

CA _____ CA Date _____

Waste Material Onsite? Pass CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass CM _____

CA _____ CA Date _____
 Guy line anchors removed? In CM _____
 CA _____ CA Date _____
 Guy line anchors marked? Pass CM _____
 CA _____ CA Date _____

1003b. Area no longer in use? In Production areas stabilized ? In
 1003c. Compacted areas have been cross ripped? Fail
 1003d. Drilling pit closed? Pass Subsidence over on drill pit? In
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? In
 Production areas have been stabilized? In Segregated soils have been replaced? Fail

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced Fail Recontoured Pass 80% Revegetation In

1003 f. Weeds Noxious weeds? I

Comment: _____

Overall Interim Reclamation In Process

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Inspector Name: SCHURE, KYM

S/U/V:	_____	Corrective Date:	_____
Comment:	<div></div>		
CA:	<div></div>		