

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

07/16/2012

Document Number:

661601729

Overall Inspection:

Unsatisfactory**FIELD INSPECTION FORM**

Location Identifier: 265349 Facility ID: 331746 Loc ID: Tracking Type: Inspector Name: MONTOYA, JOHN

Operator Information:OGCC Operator Number: 65110 Name of Operator: O'BRIEN ENERGY RESOURCES CORPAddress: 18 CONGRESS ST STE 207City: PORTSMOUTH State: NH Zip: 3801-**Contact Information:**

Contact Name	Phone	Email	Comment
Joe Forma		joeobenergy@aol.com	
ONYSKIW, DENISE		denise.onyskiw@state.co.us	

Compliance Summary:QtrQtr: SWSE Sec: 17 Twp: 3N Range: 62W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
08/16/2011	200318455	RT	AC	U			Y
08/06/2010	200265947	RT	SI	U			Y
05/22/2009	200211402	RT	SI	U			Y
07/23/2008	200195235	ES	AC	S			N
04/14/2008	200130202	MI	PD	S			N
03/07/2008	200127683	ES	SI	U			Y

Inspector Comment:**Related Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
265349	WELL	IJ	04/19/2012	DSPW	123-21237	NORTH LOST CREEK 11	<input checked="" type="checkbox"/>

Equipment:**Location Inventory**

Special Purpose Pits: Drilling Pits: Wells: Production Pits:
 Condensate Tanks: Water Tanks: Separators: Electric Motors:
 Gas or Diesel Mortors: Cavity Pumps: LACT Unit: Pump Jacks:
 Electric Generators: Gas Pipeline: Oil Pipeline: Water Pipeline:
 Gas Compressors: VOC Combustor: Oil Tanks: Dehydrator Units:
 Multi-Well Pits: Pigging Station: Flare: Fuel Tanks:

Location

Signs/Marker:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Unsatisfactory	NO WELLHEAD SIGN	Install sign to comply with rule 210.b.	08/16/2012
BATTERY	Satisfactory			
TANK LABELS/PLACARDS	Satisfactory			

Emergency Contact Number: (S/U/V) _____ Corrective Date: _____

Comment: _____

Corrective Action: _____

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
LOCATION	Satisfactory			

Equipment:					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Ancillary equipment	1	Satisfactory	TANK HEATER ON OIL SALES TANK		
Ancillary equipment	1	Satisfactory	PROPANE TANK		

Facilities: ☐ New Tank Tank ID: _____

Contents	#	Capacity	Type	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST	40.219770,-104.340450

S/U/V: _____ Comment: _____

Corrective Action: _____ Corrective Date: _____

Paint

Condition	Adequate
-----------	----------

Other (Content) _____

Other (Capacity) _____

Other (Type) _____

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Corrective Action: _____ Corrective Date: _____

Comment: _____

Facilities:		<input type="checkbox"/> New Tank		Tank ID: _____	
Contents	#	Capacity	Type	SE GPS	
PRODUCED WATER	2	300 BBLS	STEEL AST	,	
S/U/V:			Comment:		
Corrective Action:				Corrective Date:	
Paint					
Condition	Adequate				
Other (Content) _____					
Other (Capacity) _____					
Other (Type) _____					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Corrective Action				Corrective Date	
Comment					
Venting:					
Yes/No		Comment			
NO					
Flaring:					
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date	

Predrill

Location ID: 331746

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Comment:** _____**CA:** _____ **Date:** _____**Wildlife BMPs:****Comment:** _____**CA:** _____ **Date:** _____**Stormwater:**

Erosion BMPs	Present	Other BMPs	Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment: _____**Staking:****On Site Inspection (305):**Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 265349 Type: WELL API Number: 123-21237 Status: IJ Insp. Status: AC

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Inspector Name: MONTOYA, JOHN

Comment: <input style="width: 700px;" type="text"/>			
Corrective Action: _____		Date: _____	
Reportable: _____	GPS: Lat _____	Long _____	
Proximity to Surface Water: _____		Depth to Ground Water: _____	
Water Well:			
		Lat _____	Long _____
DWR Receipt Num: _____	Owner Name: _____	GPS : _____	
Field Parameters:			
<input style="width: 300px;" type="text"/>			
Sample Location: <input style="width: 400px;" type="text"/>			
Emission Control Burner (ECB): _____			
Comment: _____			
Pilot: _____	Wildlife Protection Devices (fired vessels): _____		

Reclamation - Storm Water - Pit

Interim Reclamation:			
Date Interim Reclamation Started: _____		Date Interim Reclamation Completed: _____	
Land Use: _____			
Comment: <input style="width: 750px;" type="text"/>			
1003a.	Debris removed? _____ CM _____		
	CA _____	CA Date _____	
	Waste Material Onsite? _____ CM _____		
	CA _____	CA Date _____	
	Unused or unneeded equipment onsite? _____ CM _____		
	CA _____	CA Date _____	
	Pit, cellars, rat holes and other bores closed? _____ CM _____		
	CA _____	CA Date _____	
	Guy line anchors removed? _____ CM _____		
	CA _____	CA Date _____	
	Guy line anchors marked? _____ CM _____		
	CA _____	CA Date _____	
1003b.	Area no longer in use? _____		Production areas stabilized ? _____
1003c.	Compacted areas have been cross ripped? _____		
1003d.	Drilling pit closed? _____		Subsidence over on drill pit? _____
	Cuttings management: _____		
1003e.	Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____		
	Production areas have been stabilized? _____		Segregated soils have been replaced? _____
RESTORATION AND REVEGETATION			
<u>Cropland</u>			
	Top soil replaced _____	Recontoured _____	Perennial forage re-established _____

Inspector Name: MONTOYA, JOHN

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: _____

Corrective Date: _____

Comment: _____

CA: _____

COGCC Comments

Comment	User	Date
TALKED TO COMPANY MAN SAID THEY WOULD TAKE CARE OF SIGNAGE PROBLEM AND CLEAN UP MESS INSIDE WELL AREA AND CUT WEEDS ON LOCATION INSIDE FENCED AREA NUMBER 1-800-291-1969 I WILL BE BACK TO CHECK ON THIS LOCATION IN 30 DAYS	MontoyaJ	07/16/2012