

FORM INSP Rev 05/11	State of Colorado Oil and Gas Conservation Commission 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109		DE ET OE ES
-------------------------------	--	--	-------------

Inspection Date:
07/17/2012

Document Number:
663400623

Overall Inspection:
Unsatisfactory

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name: <u>EDELEN, RANDY</u>
	<u>233948</u>	<u>316974</u>		

Operator Information:

OGCC Operator Number: 82470 Name of Operator: STELBAR OIL CORP INC

Address: 1625 N WATERFRONT PKWY #200

City: WICHITA State: KS Zip: 67206-

Contact Information:

Contact Name	Phone	Email	Comment
ONYSKIW, DENISE		denise.onyskiw@state.co.us	
Mendenhall, Roscoe	316-264-8378 off	roscoe@stelbar.com	

Compliance Summary:

QtrQtr: SWSE Sec: 9 Twp: 2S Range: 49W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
04/28/2011	200308993	RT	TA	S			N
06/28/2010	200258535	RT	TA	S			N
06/22/2009	200213559	RT	SI	S			N
07/17/2008	200193750	MI	PD	S			N
04/22/2008	200130624	RT	SI	S			N
05/04/2007	200111016	MI	SI	S		P	N
04/04/2006	200088812	RT	AC	S		P	N
07/06/2005	200074165	RT	SI	S		P	N
05/04/2004	200054058	RT	SI	S		P	N
09/25/2003	200049374	ES	SI	U	F	F	Y
08/06/2003	200042559	RT	SI	S		P	N
05/15/2002	200027049	MI	SI	S		P	N
01/10/2002	200023273	RT	SI	S		P	N
08/31/2001	200020197	RT	SI	S		P	N
08/24/2000	200009280	RT	SI	S		P	N
12/04/1995	500158534	PR	PR			P	N
09/18/1995	500158533	PR	PR			F	Y

Inspector Comment:

Routine UIC

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name
233948	WELL	SI	02/01/1997	OW	121-06033	CLAYPOOL 1

Equipment:		<u>Location Inventory</u>	
Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Motors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:				
Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Access	Satisfactory			

Signs/Marker:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Unsatisfactory	Information incomplete	Install sign to comply with rule 210.b.	07/31/2012

Emergency Contact Number: (S/U/V) Unsatisfactory Corrective Date: 07/31/2012
 Comment: _____
 Corrective Action: Post a emergency number at wellhead

Good Housekeeping:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
DEBRIS	Unsatisfactory	Various debris around wellhead	Remove all debris	08/31/2012

Spills:				
Type	Area	Volume	Corrective action	CA Date
Crude Oil	WELLHEAD	<= 5 bbls	Stained soil around wellhead needs to be remediated or removed	08/31/2012

Multiple Spills and Releases?

Fencing/:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory			

Equipment:					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Deadman # & Marked	4	Satisfactory			

Venting:	
Yes/No	Comment
NO	

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 316974

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____
 Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Comment: _____

CA: _____ **Date:** _____

Wildlife BMPs:

Comment: _____

CA: _____ **Date:** _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____
 Other BMPs: _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 233948 Type: WELL API Number: 121-06033 Status: SI Insp. Status: TA

Underground Injection Control

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

Inj./Tube: Pressure or inches of Hg _____ Previous Test Pressure _____ MPP _____
 (e.g. 30 psig or -30" Hg) Inj Zone: JSND

TC: Pressure or inches of Hg _____ Previous Test Pressure _____ Last MIT: 07/17/2008

Brhd: Pressure or inches of Hg _____ Previous Test Pressure _____ AnnMTReq: _____

Comment: Tubing and annulus pressures could not be measured
 No provision to measure bradenhead pressure
 Flowline has been removed

Method of Injection: _____

Test Type: _____ Tbg psi: _____ Csg psi: _____ BH psi: _____

Insp. Status: _____

Comment: _____

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

S/V: Satisfactory CA Date: _____

CA: _____

Comment: Well must be either: 1) Put on production or 2) Per COGCC Rule 326.b.(1) a mechanical integrity test shall be performed on each temporarily abandoned well within thirty (30) days of the date the well becomes incapable of production or 3) Be properly plugged and abandoned. 4) A sundry requesting continued temporarily abandoned status should be submitted to Bob Koehler at the COGCC within thirty (30) days of receipt of this report - the sundry should detail the plan for the future operation of the well and the way the well is closed to the atmosphere. Shut-in and temporarily abandoned wells must be properly reported on COGCC Form 7, Operator's Monthly Production Report.

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS: _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1003a. Debris removed? Fail CM _____

CA Remove debris CA Date 08/31/2012

Waste Material Onsite? Pass CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass CM _____

CA _____ CA Date _____

Guy line anchors removed? In CM _____

CA _____ CA Date _____

Guy line anchors marked? Pass CM _____

CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? Pass

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Pass

Production areas have been stabilized? Pass Segregated soils have been replaced? Pass

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced Pass Recontoured Pass 80% Revegetation Pass

1003 f. Weeds Noxious weeds? P

Comment: _____

Overall Interim Reclamation Pass

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% Cropland: perennial forage _____

Inspector Name: EDELEN, RANDY

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: Satisfactory _____ Corrective Date: _____

Comment: _____

CA: _____