

CEMENT JOB REPORT



CUSTOMER ENCANA OIL & GAS (USA) INC			DATE 02-APR-12		F.R. # 1001899117		SERV. SUPV. REESE A ANDERSON					
LEASE & WELL NAME PRATT #2-0-29 - API 05123323760000			LOCATION 29-1N-68W			COUNTY-PARISH-BLOCK Weid Colorado						
DISTRICT Brighton			DRILLING CONTRACTOR RIG # ENSIGN 122			TYPE OF JOB Surface						
SIZE & TYPE OF PLUGS		LIST-CSG-HARDWARE		MECHANICAL BARRIERS		MD	TVD	HANGER TYPES		MD	TVD	
BJ Cement Plug, Rubber, Top 8-5/8 i		Float Shoe 8-5/8 - 8rd										
		Centralizer, with Pins, 8-5/8 in										
		Cement Basket, Slip On, 8-5/8 in										
		Float Collar, Auto Fill, 8-5/8 - 8rd										
MATERIALS FURNISHED BY BJ				LAB REPORT NO.		PHYSICAL SLURRY PROPERTIES						
						SACKS OF CEMENT	SLURRY WGT PPG	SLURRY YLD FT³	WATER GPS	PUMP TIME HR:MIN	Bbl SLURRY	Bbl MIX WATER
Fresh Water				0		0	8.34	0	0	00:00	54.77	
Fresh Water + Dye				0		0	8.34	0	0	00:00	10	
Type III + 1.5% CaCl ₂ + 1.5% CF						365	14.5	1.41	6.82	02:30	91.7	59.46
Available Mix Water		280 Bbl.		Available Displ. Fluid		280 Bbl.		TOTAL		156.47		59.46
HOLE			TBG-CSG-D.P.					COLLAR DEPTHS				
SIZE	% EXCESS	DEPTH	ID	OD	WGT.	TYPE	MD	TVD	GRADE	SHOE	FLOAT	STAGE
12.25	40	900	8.097	8.625	24	CSG	900	900		921	881	879
LAST CASING			PKR-CMT RET-BR PL-LINER			PERF. DEPTH		TOP CONN		WELL FLUID		
ID	OD	WGT.	TYPE	MD	TVD	BRAND & TYPE	DEPTH	TOP	BTM	SIZE	THREAD	TYPE
						NO PACKER	0			8.625	8 RD	WATER BASED
DISPL. VOLUME		DISPL. FLUID		CAL. PSI	CAL. MAX PSI	OP. MAX	MAX TBG PSI		MAX CSG PSI		MIX WATER	
VOLUME	UOM	TYPE	WGT.	BUMP PLUG	TO REV.	SQ. PSI	RATED	Operator	RATED	Operator		
57	BBLS	Fresh Water	8.34	850	0	0	0	0	2360	1000	RIG TANK	
Circulation Prior to Job												
Circulated Well: Rig <input checked="" type="checkbox"/> BJ <input type="checkbox"/>						Circulation Time: 1			Circulation Rate: 6 BPM			
Mud Density In: 9 LBS/GAL Mud Density Out: 9 LBS/GAL						PV & YP Mud In: 28			PV & YP Mud Out: 28			
Gas Present: NO <input checked="" type="checkbox"/> YES <input type="checkbox"/> Units:						Solids Present at End of Circulation: NO <input checked="" type="checkbox"/> YES <input type="checkbox"/>						
Displacement And Mud Removal												
Displaced By: Rig <input type="checkbox"/> BJ <input checked="" type="checkbox"/>						Amount Bled Back After Job: 1 BBLS						
Returns During Job: <input type="checkbox"/> NONE <input type="checkbox"/> PARTIAL <input checked="" type="checkbox"/> FULL						Method Used to Verify Returns: VISUAL						
Cement Returns at Surface: <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO						Were Returns Planned at Surface: <input type="checkbox"/> NO <input checked="" type="checkbox"/> YES						
Pipe Movement: <input type="checkbox"/> ROTATION <input type="checkbox"/> RECIPROICATION <input checked="" type="checkbox"/> NONE <input type="checkbox"/> UNABLE DUE TO STUCK PIPE												
Centralizers: <input type="checkbox"/> NO <input checked="" type="checkbox"/> YES						Quantity: 12			Type: <input type="checkbox"/> BOW <input type="checkbox"/> RIGID			
Job Pumped Through: <input type="checkbox"/> CHOKE MANIFOLD <input type="checkbox"/> SQUEEZE MANIFOLD <input checked="" type="checkbox"/> MANIFOLD <input type="checkbox"/> NO MANIFOLD												
Plugs												
Number of Attempts by BJ: 0						Competition: 0			Wiper Balls Used: <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES Quantity:			
Plug Catcher Used: <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES						Parabow Used: <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES						
Was There a Bottom: <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES						Top of Plug: 0 FT			Bottom of Plug: 0 FT			
Squeezes (Update Original Treatment Report for Primary Job)												
BLOCK SQUEEZE <input type="checkbox"/> SHOE SQUEEZE <input type="checkbox"/> TOP OF LINER SQUEEZE <input type="checkbox"/> PLANNED <input type="checkbox"/> UNPLANNED <input type="checkbox"/>												
Liner Packer: <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES						Bond Log: <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES			PSI Applied: 0 Fluid Weight: 0 LBS/GAL			
Casing Test (Update Original Treatment Report for Primary Job)												
Casing Test Pressure: 0 PSI						With 0 LBS/GAL Mud			Time Held: 00 Hours 00 Minutes			
EXPLANATION: TROUBLE SETTING TOOL, RUNNING CSG, ETC. PRIOR TO CEMENTING: NONE												

CEMENT JOB REPORT



Shoe Test (Update Original Treatment Report for Primary Job)

Depth Drilled out of Shoe: 0 FT Target EMW: 0 LBS/GAL Actual EMW: 0 LBS/GAL
 Number of Times Tests Conducted: 0 Mud Weight When Test was Conducted: 0 LBS/GAL

Problems Before Job (I.E. Running Casing, Circulating Well, ETC)
 NONE

Problems During Job (I.E. Lost Returns, Equipment Failure, Bulk Delivery, Foaming, ETC)
 NONE

Problems After Job (I.E. Gas at Surface, Float Equipment Failed, ETC)
 NONE

PRESSURE/RATE DETAIL

EXPLANATION

TIME HR:MIN.	PRESSURE - PSI		RATE BPM	Bbl. FLUID PUMPED	FLUID TYPE	SAFETY MEETING: BJ CREW <input checked="" type="checkbox"/> CO. REP. <input checked="" type="checkbox"/>	
	PIPE	ANNULUS				TEST LINES	2259 PSI
						CIRCULATING WELL - RIG	<input checked="" type="checkbox"/> BJ <input type="checkbox"/>
17:15	0	0	0	0	NA	YARD CALL	
18:42	0	0	0	0	NA	LEAVE YARD	
19:23	0	0	0	0	NA	ARRIVE ON LOCATION	
19:25	0	0	0	0	NA	SPOT TRUCKS/PRE RIG UP MEETING/RIG UP	
19:50	0	0	0	0	NA	SAFETY MEETING	
20:04	2250	0	0	0	H2O	PRESSURE TEST	
20:13	73	0	6	20	H2O	PRE FLUSH	
20:19	71	0	6	10	H2O	DYED SPACER	
20:23	78	0	4.4	87	CMT	BATCH UP, WEIGH AND PUMP 365 SX TYPE III + 0.08 LBS/SACK STATIC FREE + 1.5% CACL + 0.15 LBS/SACK CELLO FLAKE	
20:41	0	0	0	0	NA	DROP PLUG	
20:47	223	0	6	40	H2O	DISPLACEMENT	
20:57	299	0	3.2	10	H2O	RATE CHANGE	
21:00	309	0	2.8	7	H2O	RATE CHANGE	
21:03	321	0	2.8	57	H2O	SHUT DOWN @ 57 BBLS	
21:14	0	0	0	0	NA	SHUT IN HEAD AND MANIFOLD	
21:18	0	0	0	0	NA	PRE RIG DOWN MEETING/RIG DOWN	
21:50	0	0	0	0	NA	LEAVE LOCATION	
BUMPED PLUG	PSI TO BUMP PLUG	TEST FLOAT EQUIP.	BBL.CMT RETURNS/ REVERSED	TOTAL BBL. PUMPED	PSI LEFT ON CSG	SPOT TOP OUT CEMENT	Service Supervisor Signature:
Y <input checked="" type="checkbox"/> N	321	<input checked="" type="checkbox"/> Y N	0	174	0	Y <input checked="" type="checkbox"/> N	



BJ Services JobMaster Program Version 3.50
Job Number: 1001899117
Customer: ENCANA
Well Name: PRATT 2-0-29

