

FORM 5A Rev 06/12

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



Table with columns DE, ET, OE, ES

Document Number: 400308034

Date Received:

COMPLETED INTERVAL REPORT

The completed interval Report, Form 5A, shall be submitted within thirty (30) days of completing a formation (successful or not), when a formation is temporarily abandoned or permanently abandoned, for a recompletion, reperforation or restimulation, or when a formation is commingled. Fill out a section for each formation. Attach as many pages as required to fully describe the work. List in order of completion.

1. OGCC Operator Number: 66571
2. Name of Operator: OXY USA WTP LP
3. Address: P O BOX 27757 City: HOUSTON State: TX Zip: 77227
4. Contact Name: Joan Proulx Phone: (970) 263-3641 Fax: (970) 263-3694

5. API Number 05-045-16009-00
6. County: GARFIELD
7. Well Name: CASCADE CREEK Well Number: 697-09-54B
8. Location: QtrQtr: SWSE Section: 9 Township: 6S Range: 97W Meridian: 6
9. Field Name: GRAND VALLEY Field Code: 31290

Completed Interval

FORMATION: WILLIAMS FORK - CAMEO Status: PRODUCING Treatment Type: FRACTURE STIMULATION

Treatment Date: End Date: Date of First Production this formation: 12/27/2009

Perforations Top: 7020 Bottom: 8669 No. Holes: 156 Hole size: 37/100

Provide a brief summary of the formation treatment: Open Hole: [ ]

5 stages of slickwater frac with 190,071 bbls of frac fluid and 692,150 lbs of 20/40 white sand proppant

This formation is commingled with another formation: [ ] Yes [X] No

Total fluid used in treatment (bbl): Max pressure during treatment (psi):

Total gas used in treatment (mcf): Fluid density at initial fracture (lbs/gal):

Type of gas used in treatment: Max frac gradient (psi/ft):

Total acid used in treatment (bbl): Number of staged intervals:

Recycled water used in treatment (bbl): Flowback volume recovered (bbl):

Fresh water used in treatment (bbl): Disposition method for flowback:

Total proppant used (lbs): Rule 805 green completion techniques were utilized: [ ]

Reason why green completion not utilized:

Fracture stimulations must be reported on FracFocus.org

Test Information:

Date: 07/18/2012 Hours: 24 Bbl oil: 0 Mcf Gas: 0 Bbl H2O: 0

Calculated 24 hour rate: Bbl oil: 0 Mcf Gas: 0 Bbl H2O: 0 GOR: 0

Test Method: Flowing Casing PSI: 694 Tubing PSI: 488 Choke Size: 32/64

Gas Disposition: SOLD Gas Type: DRY Btu Gas: 1066 API Gravity Oil: 0

Tubing Size: 2 + 3/8 Tubing Setting Depth: 8278 Tbg setting date: 06/26/2012 Packer Depth:

Reason for Non-Production:

Date formation Abandoned: Squeeze: [ ] Yes [ ] No If yes, number of sacks cmt

\*\* Bridge Plug Depth: \*\* Sacks cement on top: \*\* Wireline and Cement Job Summary must be attached.

Comment:

Work occurred on the 697-09-54B well to cleanout a stuck plunger and lower the tubing.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Joan Proulx

Title: Regulatory Analyst Date: \_\_\_\_\_ Email: joan\_proulx@oxy.com  
:

### **Attachment Check List**

Att Doc Num	Name

Total Attach: 0 Files

### **General Comments**

<b><u>User Group</u></b>	<b><u>Comment</u></b>	<b><u>Comment Date</u></b>

Total: 0 comment(s)