

Inspector Name: LEONARD, MIKE

**FORM
INSP**Rev
05/11**State of Colorado****Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:

07/18/2012

Document Number:

668200011

Overall Inspection:

Violation**FIELD INSPECTION FORM**

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name:
	<u>273866</u>	<u>306888</u>		<u>LEONARD, MIKE</u>

Operator Information:OGCC Operator Number: 7125 Name of Operator: BEEMAN OIL & GAS LLCAddress: 91 WEDGEWOOD CIRCity: DURANGO State: CO Zip: 81391**Contact Information:**

Contact Name	Phone	Email	Comment
KOEHLER, BOB		bob.koehler@state.co.us	
Blake, Alberta	(970) 259-2788	alberta_blake@yahoo.com	

Compliance Summary:QtrQtr: SWSE Sec: 12 Twp: 33N Range: 13W

Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
05/10/2012	661700333	SI	SI	V			Y
10/15/2004	200065522	DG	DG	S		P	N

Inspector Comment:

WELL WAS SPUDDED 10/2004.WELL FILE SHOWS IT WAS PERFORATED. CASING OPEN TO ATMOSPHERE.NO RECORD OF MIT. NO INTERIM RECLAMATION HAS BEEN PERFORMED. PIT IS STILL OPEN AND TRASH AN DEBRIS ARE SCATTERED ON LOCATION.

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
273866	WELL	SI	09/29/2004	GW	067-08979	GROMMET 1	<input checked="" type="checkbox"/>

Equipment:**Location Inventory**

Special Purpose Pits: _____	Drilling Pits: _____	Wells: _____	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location**Lease Road:**

Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Main	Unsatisfactory	ROAD RUTTED	MAINTAIN ROAD	08/31/2012

Inspector Name: LEONARD, MIKE

Signs/Marker:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory			

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____

Comment: _____

Corrective Action: _____

Good Housekeeping:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
TRASH	Violation	JUNK FURNITURE, CLOTHING, TIRES AND DEBRIS BEING DUMPED ON LOCATION	REMOVE TRASH	08/31/2012

Spills:				
Type	Area	Volume	Corrective action	CA Date

☐ Multiple Spills and Releases?

Venting:		
Yes/No	Comment	

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 306888

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

Corrective Action: _____

Date: _____ CDP Num.: _____

Form 2A COAs:**Comment:****CA:****Date:****Wildlife BMPs:****Comment:****CA:****Date:****Stormwater:**

Erosion BMPs

Present

Other BMPs

Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____

Other BMPs: _____

Comment:**Staking:****On Site Inspection (305):****Surface Owner Contact Information:**

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:**Summary of Operator Response to Landowner Issues:****Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:****Facility**

Facility ID: 273866 Type: WELL API Number: 067-08979 Status: SI Insp. Status: TA

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____S/V: ViolationCA Date: 08/31/2012

CA: Well must be either: 1) Put on production or 2) Per COGCC Rule 326.b.(1) a mechanical integrity test shall be performed on each temporarily abandoned well within thirty (30) days of the date the well becomes incapable of production or 3) Be properly plugged and abandoned. 4) A sundry requesting continued temporarily abandoned status should be submitted to Bob Koehler at the COGCC within thirty (30) days of receipt of this report - the sundry should detail the plan for the future operation of the well and the way the well is closed to the atmosphere. Shut-in and temporarily abandoned wells must be properly reported on COGCC Form 7, Operator's Monthly Production Report.

Comment: _____

Environmental**Spills/Releases:**

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: BRUSH CLEARED TO BUILD LOCATION HAS BEEN PILED AROUND LOCATION. NO ATTEMPTS AT INTERIM RECLAMATION HAVE BEEN MADE

1003a. Debris removed? Fail CM _____CA REMOVE BRUSH PILESCA Date 08/31/2012Waste Material Onsite? Fail CM _____CA REMOVE BRUSH PILESCA Date 08/31/2012Unused or unneeded equipment onsite? Pass CM _____

CA _____

CA Date _____

Pit, cellars, rat holes and other bores closed? Fail CM _____CA SAMPLE AND CLOSE PIT AS REQUIREDCA Date 08/31/2012Guy line anchors removed? Pass CM _____

CA _____

CA Date _____

Inspector Name: LEONARD, MIKE

Guy line anchors marked? _____ CM _____
CA _____ CA Date _____

1003b. Area no longer in use? Fail Production areas stabilized ? Fail

1003c. Compacted areas have been cross ripped? Fail

1003d. Drilling pit closed? Fail Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Fail

Production areas have been stabilized? Fail Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced Fail Recontoured Fail 80% Revegetation Fail

1003 f. Weeds Noxious weeds? _____

Comment: NO INTERIM RECLAMATION HAS BEEN PERFORMED

Overall Interim Reclamation Fail

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

S/U/V: **Violation** Corrective Date: **08/31/2012**

Comment: NO STORMWATER BMP'S IN PLACE

CA: INSTALL NECESSARY BMP'S TO STABILIZE LOCATION

COGCC Comments

Comment	User	Date
WELL WAS SPUDDED 10/2004.WELL FILE SHOWS IT WAS PERFORATED. CASING OPEN TO ATMOSPHERE.NO RECORD OF MIT. NO INTERIM RECLAMATION HAS BEEN PERFORMED. PIT IS STILL OPEN AND TRASH AN DEBRIS ARE SCATTERED ON LOCATION.	leonardm	07/31/2012

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
668200012	WELLHEAD,NO VALVE	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=2961642
668200013	PIT	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=2961643
668200014	TRASH	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=2961644
668200015	BRUSH PILES	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=2961645
668200016	TIRES,BRUSH PILE	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=2961646
668200017	MORE BRUSH PILE	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=2961647
668200018	LOCATION ID AND TRASH	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=2961648