Click here to reset form

FORM 4 Rev 12/05

TECHNICAL INFORMATION PAGE

FOR OGCC USE ONLY

1. OGCC Operator Number: 28700 API Number: 05-103-01097
2. Name of Operator: Exxon Mobil Corporation OGCC Facility ID #
3. Well/Facility Name: PCU Well/Facility Number: T45-18G
4. Location (QtrQtr, Sec, Twp, Rng, Meridian): NESW, 18, 2S, 96W, 6 PM

This form is to be completed whenever a Sundry Notice is submitted requiring detailed report of work to be performed or completed. This form shall be transmitted within 30 days of work completed as a "subsequent" report and must accompany Form 4, page 1.

5. **DESCRIBE PROPOSED OR COMPLETED OPERATIONS**

We have removed an out of service tank from PCU T45-18G. A sample was collected from beneath the low point of the tank area and sampled per COGCC 910. Soil left in place does not exceed the allowable concentration levels listed in Table 910-1. Clean backfill material will be imported from the Connel Pit in Meeker, CO. An Assessment Report provided by KRW Consulting Inc. is attached.

We respectfully request No Further Action for the tank abandonment at PCU 45-18.