



Photograph 1 – View of completed pit closure, N side facing S, closed Freshwater and Reserve Pits



Photograph 2 – View of completed pit closure, N side facing S, closed Freshwater and Reserve Pits



Photograph 3 – View of completed pit closure, S side facing N, closed Cuttings Pits



Photos Taken: 3/20/2012

XTO FRU 197-33A
Piceance Basin, CO

Site Photographs