

FORM INSP
Rev 05/11

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Inspection Date:
07/31/2012

Document Number:
663400669

Overall Inspection:
Satisfactory

FIELD INSPECTION FORM

Location Identifier	Facility ID	Loc ID	Tracking Type	Inspector Name: <u>EDELEN, RANDY</u>
	<u>249687</u>	<u>329537</u>		

Operator Information:

OGCC Operator Number: <u>47120</u>	Name of Operator: <u>KERR-MCGEE OIL & GAS ONSHORE LP</u>
Address: <u>P O BOX 173779</u>	
City: <u>DENVER</u>	State: <u>CO</u> Zip: <u>80217-</u>

Contact Information:

Contact Name	Phone	Email	Comment
Kilcrease, Keith	(970) 506-5926	keith.kilcrease@anadarko.com	Production Superintendent
Avant, Paul	(720) 929-6457	Paul.Avant@anadarko.com	Compliance Regulatory Analyst
Cocciolone, Ashley	(720) 929-6625	Ashley.Cocciolone@anadarko.com	Regulatory Supervisor

Compliance Summary:

QtrQtr: <u>NWSE</u>	Sec: <u>6</u>	Twp: <u>2N</u>	Range: <u>65W</u>				
Insp. Date	Doc Num	Insp. Type	Insp Status	Satisfactory /Unsatisfactory	PA P/F/I	Pas/Fail (P/F)	Violation (Y/N)
02/15/2011	200299746	PR	PR	S			N
01/11/2006	200086420	PR	PR	S		P	N
02/09/1999	500175309	PR	PR				
07/27/1994	500175308		PR			P	
03/30/1994	500175306		ND				

Inspector Comment:

Producing wells See inspection 663400670 for details on shared facilities

Related Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	
249687	WELL	PR	04/27/1999	OW	123-17490	NICHOLS 33-6	X
422371	WELL	PR	08/29/2011		123-33236	NICHOLS 24-6	X
422374	WELL	PR	08/26/2011		123-33237	NICHOLS 23-6	X
422435	WELL	PR	08/03/2011		123-33254	NICHOLS 10-6	X
422453	WELL	PR	08/25/2011		123-33264	NICHOLS 38-6	X
422461	WELL	PR	08/24/2011		123-33268	NICHOLS 9-6	X
422463	WELL	PR	08/23/2011		123-33269	NICHOLS 16-6	X

Equipment:

Location Inventory

--

Special Purpose Pits: _____	Drilling Pits: _____	Wells: <u>7</u>	Production Pits: _____
Condensate Tanks: _____	Water Tanks: _____	Separators: _____	Electric Motors: _____
Gas or Diesel Mortors: _____	Cavity Pumps: _____	LACT Unit: _____	Pump Jacks: _____
Electric Generators: _____	Gas Pipeline: _____	Oil Pipeline: _____	Water Pipeline: _____
Gas Compressors: _____	VOC Combustor: _____	Oil Tanks: _____	Dehydrator Units: _____
Multi-Well Pits: _____	Pigging Station: _____	Flare: _____	Fuel Tanks: _____

Location

Lease Road:				
Type	Satisfactory/Unsatisfactory	comment	Corrective Action	Date
Access	Satisfactory			

Signs/Marker:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory	Nichols 33-6Nichols 24-6Nichols 23-6Nichols 10-6Nichols 38-6Nichols 9-6Nichols 16-6		

Emergency Contact Number: (S/U/V) Satisfactory Corrective Date: _____
 Comment: Previously verified
 Corrective Action: _____

Good Housekeeping:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
DEBRIS	Unsatisfactory	Valves, piping, wire, and various debris around wellheadCrumpled grain bin on location	Remove all debris	09/30/2012

Spills:				
Type	Area	Volume	Corrective action	CA Date
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
WELLHEAD	Satisfactory	Nichols 33-6Nichols 24-6Nichols 23-6Nichols 10-6Nichols 38-6Nichols 9-6Nichols 16-6		
LOCATION	Satisfactory			

Equipment:					
Type	#	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date
Plunger Lift	7	Satisfactory	Nichols 33-6Nichols 24-6Nichols 23- 6Nichols 10- 6Nichols 38- 6Nichols 9-6Nichols 16-6		
Flow Line	7	Satisfactory	Nichols 33-6Nichols 24-6Nichols 23- 6Nichols 10- 6Nichols 38- 6Nichols 9-6Nichols 16-6		

Venting:	
Yes/No	Comment
NO	

Flaring:				
Type	Satisfactory/Unsatisfactory	Comment	Corrective Action	CA Date

Predrill

Location ID: 329537

Site Preparation:

Lease Road Adeq.: _____ Pads: _____ Soil Stockpile: _____
 Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

Comment: _____

CA: _____ **Date:** _____

Wildlife BMPs:

Comment: _____

CA: _____ **Date:** _____

Stormwater:

Erosion BMPs	Present	Other BMPs	Present

Corrective Action: _____ Date: _____

Comments: Erosion BMPs: _____
 Other BMPs: _____

Comment: _____

Staking:

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 249687 Type: WELL API Number: 123-17490 Status: PR Insp. Status: PR

Facility ID: 422371 Type: WELL API Number: 123-33236 Status: PR Insp. Status: PR

Facility ID: 422374 Type: WELL API Number: 123-33237 Status: PR Insp. Status: PR

Facility ID: 422435 Type: WELL API Number: 123-33254 Status: PR Insp. Status: PR

Facility ID: 422453 Type: WELL API Number: 123-33264 Status: PR Insp. Status: PR

Facility ID: 422461 Type: WELL API Number: 123-33268 Status: PR Insp. Status: PR

Producing Well

Comment: _____

Facility ID: 422463 Type: WELL API Number: 123-33269 Status: PR Insp. Status: PR

Producing Well

Comment: _____

Environmental

Spills/Releases:

Type of Spill: _____ Description: _____ Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____ Date: _____

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well:

DWR Receipt Num: _____ Owner Name: _____ GPS: _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: IMPROVED PASTURE

Comment: _____

1003a. Debris removed? Fail CM _____

CA Remove debris CA Date 09/30/2012

Waste Material Onsite? Pass CM _____

CA _____ CA Date _____

Unused or unneeded equipment onsite? Pass CM _____

CA _____ CA Date _____

Pit, cellars, rat holes and other bores closed? Pass CM _____

CA _____ CA Date _____

Inspector Name: EDELEN, RANDY

Guy line anchors removed? Pass CM _____
CA _____ CA Date _____
Guy line anchors marked? _____ CM _____
CA _____ CA Date _____

1003b. Area no longer in use? Pass Production areas stabilized ? Pass
1003c. Compacted areas have been cross ripped? Pass
1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? Pass
Production areas have been stabilized? Pass Segregated soils have been replaced? Pass

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced Pass Recontoured Pass 80% Revegetation Pass

1003 f. Weeds Noxious weeds? P

Comment: _____

Overall Interim Reclamation Pass

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: IMPROVED PASTURE

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

Comment: _____

Corrective Action: _____ Date _____

Overall Final Reclamation

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Inspector Name: EDELEN, RANDY

S/U/V: Satisfactory Corrective Date: _____

Comment: _____

CA: _____